



PETECHTOOL 8P8C Color Code Instruction Manual

[Home](#) » [PETECHTOOL](#) » PETECHTOOL 8P8C Color Code Instruction Manual 

Contents

- [1 PETECHTOOL 8P8C Color Code](#)
- [2 RJ45 color code](#)
- [3 How to make an Ethernet cable](#)
- [4 Documents / Resources](#)
 - [4.1 References](#)
- [5 Related Posts](#)




PETECHTOOL 8P8C Color Code




RJ45 color code

1. White Green
2. Green
3. White Orange
4. Blue
5. White Blue
6. Orange
7. White Brown
8. Brown



1. White Orange
2. Orange
3. White Green
4. Blue
5. White Blue
6. Green
7. White Brown
8. Brown




How to make an Ethernet cable

1. Arrange the ethernet cable, plug ,crimp tool and the strain relief boot.
2. Put the boot into the cable if you have the boot.




3. Strip off the skin of the network cable.

4. Remove the skin off.



5. Separate the twisted pair and straighten it.

6. Arrange the wires according to the rj45 color "T568B"



7. Trim the network cable neatly to make it easier to perforate.

8. Pass the wires thru the connector and Perform sequence verification again




9. Put the plug into the tool and confirm push to the bottom.

10. Crimp the plug.



11. Finish.

12. If you have the boot, you need to push it off like this photo, then finish.



Documents / Resources

	PETECHTOOL 8P8C Color Code [pdf] Instruction Manual 8P8C Color Code, 8P8C, Color Code, Code
---	--

References

- [User Manual](#)