PHILIPS PDDEG-S Dynalite Ethernet Gateway Supervisor





# **PHILIPS PDDEG-S Dynalite Ethernet Gateway Supervisor Instruction Manual**

Home » Philips » PHILIPS PDDEG-S Dynalite Ethernet Gateway Supervisor Instruction Manual



# **Contents**

- 1 PHILIPS PDDEG-S Dynalite Ethernet Gateway
- **Supervisor**
- **2 Installation Instructions**
- **3 WHAT IN THE BOX**
- **4 DIMENSION**
- **5 FEATURES**
- **6 INSTALLATION INSTRUCTION**
- 7 FCC and RSS-210 of IC (Industry Canada) Rules
- 8 Documents / Resources
  - 8.1 References
- 9 Related Posts




**PHILIPS PDDEG-S Dynalite Ethernet Gateway Supervisor** 




## **Installation Instructions**


Devices must be installed in an approved enclosure by a qualified electrician by all national and local electrical and construction codes and regulations.

## WHAT IN THE BOX



# **DIMENSION**





## **FEATURES**


























# **INSTALLATION INSTRUCTION**





























**Caution** – risk of explosion if battery is replaced by an incorrect type.

### FCC and RSS-210 of IC (Industry Canada) Rules

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC Rules and pursuant to RSS210 of the IC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures: Reorient or relocate the receiving antenna. Increase the separation between the equipment and receiver. Connect the equipment into an outlet on a circuit different from that to which the receiver is connected. Consult the dealer or an experienced radio/TV technician for help. Any modifications not approved by the manufacturer of this device could void the user's authority to operate this device.

- This Class B digital apparatus complies with Canadian ICES-003: CAN ICES-3(B)/NMB-3(B). Cet appareil numerique de la Classe B est conforme a la norme NMB-003 du Canada: CAN ICES-3(B)/NMB-3(B).
- Installation of a home and building automation and control system shall comply with IEC 60364 (all parts). The
  temperature limits and current-carrying capacities for the communication wires specified in IEC 60364-5-52
  shall not be exceeded.
- 2023 Signify Holding. All rights reserved. Specifications are subject to change without notice. No representation
  or warranty as to the accuracy or completeness of the information included herein is given and any liability for
  any action in reliance thereon is disclaimed. Philips and the Philips Shield Emblem are registered trademarks of
  Koninklijke Philips N.V. All other trademarks are owned by Signify Holding or their respective owners.
- www.dynalite.com

#### **Documents / Resources**



PHILIPS PDDEG-S Dynalite Ethernet Gateway Supervisor [pdf] Instruction Manual PDDEG-S Ethernet Gateway Supervisor, PDDEG-S, Ethernet Gateway Supervisor, Gateway Supervisor, Supervisor

#### References

- O Philips Dynalite Lighting Controls, Lighting Management
- User Manual

#### Manuals+, Privacy Policy

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.