

**Pioneer**

DMH-ZF8550BT  
Certain In-Dash  
AV Receivers  
Firmware  
Updating



## Pioneer DMH-ZF8550BT Certain In-Dash AV Receivers Firmware Updating Instructions

[Home](#) » [Pioneer](#) » Pioneer DMH-ZF8550BT Certain In-Dash AV Receivers Firmware Updating Instructions 

### Contents

- [1 Pioneer DMH-ZF8550BT Certain In-Dash AV Receivers Firmware Updating](#)
- [2 Product Information](#)
- [3 Product Usage Instructions](#)
- [4 FAQs](#)
- [5 Can I install this firmware update on other Pioneer models?](#)
  - [5.1 How to Obtain the Free Firmware Update](#)
- [6 Documents / Resources](#)
  - [6.1 References](#)
- [7 Related Posts](#)

**Pioneer**

### Pioneer DMH-ZF8550BT Certain In-Dash AV Receivers Firmware Updating



## Product Information

### Specifications

- Product Name: Pioneer In-Dash AV Receiver
- Model: DMH-ZF8550BT
- Region: Australia & New Zealand
- Update Type: Firmware
- Update Time: Approximately 15 minutes

### Product Usage Instructions

#### How to Install Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website: [Pioneer Firmware Update](#).
2. Transfer the downloaded files to a USB storage device.
3. Insert the USB storage device into the Pioneer In-Dash AV Receiver.
4. Follow the on-screen instructions on the receiver to complete the firmware update process.

#### Important Note

Ensure that you are using the correct firmware update for the specific model mentioned to prevent irreversible damage to the device.

### FAQs

#### Can I install this firmware update on other Pioneer models?

No, this firmware update is only for the Pioneer In-Dash AV Receiver model DMH-ZF8550BT sold in Australia & New Zealand. Installing it on other models could cause damage.

#### How long does the firmware update process take?

The update process typically takes about fifteen minutes to complete.

#### What should I do if I encounter issues during the update?

If you face any problems or have questions, please contact Pioneer Technical Support via their website during business hours.

Firmware Update for Certain Pioneer In-Dash AV Receivers

June 18, 2024

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for only the following Pioneer In-Dash AV Receivers sold in Australia & New Zealand. Installation on any other product could cause irreversible damage.

**DMH-ZF8550BT**

**This firmware update corrects the following matter.**

- Corrects an issue with voice agent responses being cut off or not occurring.

**To perform this update, the following items are needed:**

- Pioneer In-Dash AV Receiver
- Blank USB storage device (no files), 512 MB or larger in capacity, formatted to FAT32 or NTFS.

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take about fifteen minutes to complete.

## How to Obtain the Free Firmware Update

1. Download the firmware update files to a computer from the Pioneer website:

<https://www.pioneer.com.au/firmwaresoftware/>


2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

## Questions

If you have any questions, please contact the Pioneer Technical Support team via our website at <https://www.pioneer.com.au/contact-us/>, Monday through Friday, 9:00 AM – 4:30 PM (excluding holidays).

Sincerely,  
Pioneer Electronics Australia Pty Ltd.

## Documents / Resources

	<p><a href="#">Pioneer DMH-ZF8550BT Certain In-Dash AV Receivers Firmware Updating</a> [pdf] Instruction S</p> <p>DMH-ZF8550BT, Certain In-Dash AV Receivers Firmware Updating, Certain AV Receivers Firmware Updating, In-Dash Receivers Firmware Updating, AV Receivers Firmware Updating, Receivers Firmware Updating, Receivers Firmware, Firmware Updating, Firmware, DMH-ZF8550BT, DMH-ZF8550BT Certain In-Dash AV Receivers Firmware Updating</p>
---	--

## References

- [User Manual](#)

[Manuals+](#), [Privacy Policy](#)

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.