



SHARP How to Power DOWN a CB-Series Display with OPS PC Installed Instructions

[Home](#) » [Sharp](#) » SHARP How to Power DOWN a CB-Series Display with OPS PC Installed Instructions 

Contents

- [1 SHARP How to Power DOWN a CB-Series Display with OPS PC Installed](#)
- [2 How to Power DOWN a CB-Series Display with OPS PC Installed](#)
- [3 How to Power UP a CB-Series Display with OPS PC Installed](#)
- [4 Documents / Resources](#)
- [5 Related Posts](#)




SHARP How to Power DOWN a CB-Series Display with OPS PC Installed



How to Power DOWN a CB-Series Display with OPS PC Installed


Step 1: Select the 'Windows' button at the bottom left-hand corner of your screen




Step 2: Select the power button



Step 3: Select Shutdown and wait for the system to shut itself down




Step 4: When the following image is displayed press the power button located near the lower right-hand corner of the monitor




How to Power UP a CB-Series Display with OPS PC Installed

Step 1: Press the Power button located near the lower right-hand corner of the monitor to Power UP the Display and OPS PC. Once the display turns ON the OPS will begin the boot up process.

Note: You may need to log in with username and password.



Documents / Resources

	<p>SHARP How to Power DOWN a CB-Series Display with OPS PC Installed [pdf] Instructions</p> <p>How to Power DOWN a CB-Series Display with OPS PC Installed, How to Power DOWN PC, Power Down CB-Series Display with OPS PC Installed</p>
---	---

Manuals+,