



SMT-35 Turnover Stone Machine Instructions

[Home](#) » [SMT](#) » SMT-35 Turnover Stone Machine Instructions 

SMT-35 Turnover Stone Machine Instructions



Contents

- [1 SMT-35 Turnover Stone Machine\(Chain Type\)](#)
- [2 Documents / Resources](#)
 - [2.1 References](#)

SMT-35 Turnover Stone Machine(Chain Type)

Overturn steady , high efficiency, 3 minutes when turning at 90 degrees The primary of the machine is to have large blocks overturn angle, instead o manually using the lever to reduce the labor of workers and improve labor productivity.

Machine Model		SMT-35	SMT-45
Max.loading weight	T	35	45
Max. Block Size	mm	3000X1600X2000	3500X1600X2000
Turn degree	n	90	90
Power of main motor	Kw	3	7.5
Reducer type		350	450
Gross weight	Kgs	4000	5000
Dimensions(Lx W x H)	Mm	2800x1800x2300	2900x1800x2300

<https://xinhaineng.en.made-in-china.com/product/HwYAheQbCorK/China-SMT-35-45-Chain-Type-Turnover-Stone-Machine-Turning-at-90-Degrees.html>



Documents / Resources

A small thumbnail image of a PDF document titled 'SMT SMT-35 Turnover Stone Machine [pdf] Instructions'. The document shows a table with technical specifications and a list of parts.	SMT SMT-35 Turnover Stone Machine [pdf] Instructions SMT-35, SMT-45, SMT-35 Turnover Stone Machine, SMT-35, Turnover Stone Machine, Stone Machine, Machine
--	---

References

- [User Manual](#)