

Software s Esteem Technical Bulletin Horizon Software Update Instructions

[Home](#) » [Software s](#) » Software s Esteem Technical Bulletin Horizon Software Update Instructions 



Technical Bulletin

Horizon Software Update
Update – December 2021 (SW update-horizon-202112031127)

Contents

- [1 New Features](#)
- [2 Operating System Update](#)
- [3 Documents / Resources](#)
 - [3.1 References](#)
- [4 Related Posts](#)

New Features

In this software update, the following new features were implemented: Wireless – The Horizon radio network can be customized for any network size and data throughput for maximum efficiency on every wireless link. Security – The default wireless passphrase will be randomized for added security. Reporting – The Horizon radios now support flat file “screen scraping” on the wireless status page.

Update Procedure

The software update can be completed using the Discovery Utility, ESTeem Networking Suite or web interface. This procedure will update the radios using the web interface to integrate the security update and new features. To complete the software update you will need the following update file either sent by ESTeem support or available for download from our web page at <https://www.esteem.com/firmware/swupdate-horizon-202112031127.img> (Firmware Update Image)

Operating System Update

1. To update the operating system software, open the Horizon radio's web interface with any web browser and select Software Update (Figure 1). Select "Software update image file" and press the Next button.

1.




Figure 1: Software Update

Select "Upload via web browser" and press the Next button.

2. Press the Choose File button and select the SW update-horizon-202112031127.img file from the location it was saved on the computer. The file name will be displayed in the "software image path". Press the Upload File button and Figure 2 will be displayed.
3. Press the Validate and Update button to verify the integrity of the update file and complete the software update. The software update will take approximately 2 minutes to complete the update.





Figure 2: Validate and Update

Revised: 21 December 2021
ESTeem Horizon Series

Documents / Resources

	Software s Esteeem Technical Bulletin Horizon Software Update [pdf] Instructions Esteeem Technical Bulletin Horizon Software Update
---	--

References

-  [Firmware Download - ESteeem](#)

Manuals+.