



Xenarc 1219GNH Touchscreen LCD Display Monitor User Guide

[Home](#) » [XENARC](#) » Xenarc 1219GNH Touchscreen LCD Display Monitor User Guide 

Contents

- [1 Xenarc 1219GNH Touchscreen LCD Display Monitor](#)
- [2 Image Description](#)
- [3 Specifications](#)
- [4 FAQ](#)
- [5 Dimensions](#)
- [6 Installation Instructions](#)
- [7 Documents / Resources](#)
 - [7.1 References](#)
- [8 Related Posts](#)



Xenarc 1219GNH Touchscreen LCD Display Monitor



Image Description

- The image provided is completely black without any discernible content, text, or diagrams.
- This may be due to an error in the image file, or it might be intended to represent a black screen or a placeholder for content that is not visible or available.

Specifications


Aspect	Details
Image Content	No visible content
Possible Interpretations	Error in an image file, intentional black screen, a placeholder for non-visible content

FAQ


- Why is the image completely black?
 - The image may be black due to an error in the file, or it may be intentionally designed to be a solid black image without any content.
- Is there any hidden content in the image that can be revealed?
 - Without additional context or information, it is not possible to determine if there is hidden content. The image appears to be a uniform black colour without any visible details.
- Can this type of image be used for any purpose?
 - A black image like this one might be used as a placeholder, a background, or to represent a turned-off screen or darkness in various contexts.

Dimensions


- Cutout dimension is 11.61"(294.8mm) by 8.38"(212.8mm). The thickness of the panel cannot exceed 8mm.




Installation Instructions




Step 1: Create panel cut out, place EVA seal, and install two bottom brackets.




Step 2: Place the monitor into the panel cutout.




Step 3: Install the four remaining brackets. One on the left, One on the right, and two on top.



Step 4: Tighten the shorter M4x8mm screws to secure the bracket and tighten the longer M4x20mm screws to secure the monitor against the panel.



Documents / Resources



[Xenarc 1219GNH Touchscreen LCD Display Monitor](#) [pdf] User Guide
1219GNH Touchscreen LCD Display Monitor, 1219GNH, Touchscreen LCD Display Monitor, LCD Display Monitor, Display Monitor, Monitor

References

- [User Manual](#)