

ZENDURE SuperPort 4 Dual USB Type-C & USB Type-A Desktop Charger Instruction Manual


[Home](#) » [ZENDURE](#) » ZENDURE SuperPort 4 Dual USB Type-C & USB Type-A Desktop Charger Instruction Manual 

Contents


- [1 ZENDURE SuperPort 4 Dual USB Type-C & USB Type-A Desktop Charger](#)
- [2 Product Overview](#)
- [3 Using Your Charger](#)
- [4 Specifications](#)
- [5 Documents / Resources](#)
- [6 Related Posts](#)

ZENDURE

ZENDURE SuperPort 4 Dual USB Type-C & USB Type-A Desktop Charger




Product Overview



1. Power Cord
2. LED Indicator
3. USB C PD PORT
4. USB-A Port with Zen+
5. AC INPUT

Using Your Charger

Connect the power cord into AC input port, and LED indicator turns on.



Connect your devices to the USB-C PD ports or USB-A ports of Zendure charger with a charge/sync cable.

Caution

1. Storage in a cool and dry place. Recommend storage temperature: -20°C to 55°C; Operating temperature: -10°C to 45°C.
2. Do not expose to moisture or submerge it in liquid.
3. Use origin or certified cables.
4. Do not disassemble or attempt to re-purpose or modify it in any manner.
5. Do not clean with harmful chemicals or detergents.

Specifications

Model	ZD4P90DPD
Input	100V~240V~50/60Hz
Output	USB-C (1): 5V~20V, up to 5A, 100W USB-C (2): 5V=3A, 9V=2A, 12V=1.5A, 18W USB-A (1): 5V=3A, 9V=2A, 12V=1.5A, 18W (ZEN+ 2.0) USB-A (2): 5V=3A, 9V=2A, 12V=1.5A, 18W (ZEN+ 2.0)
Dimensions	4.5" x 3.9" x 0.9" 114mm x 100mm x 24mm
Weight	8.3oz / 236g
Operating Temperature	32° F to 95° F / 0° C to 35° C

Documents / Resources

	ZENDURE SuperPort 4 Dual USB Type-C & USB Type-A Desktop Charger [pdf] Instruction Manual SuperPort 4, Dual USB Type-C USB Type-A Desktop Charger, SuperPort 4 Dual USB Type-C U SB Type-A Desktop Charger
---	--

[Manuals+](#).