



ZENDURE ZDPX5PD-B X5 USB-C PD Portable Charger and Hub User Manual

[Home](#) » [ZENDURE](#) » ZENDURE ZDPX5PD-B X5 USB-C PD Portable Charger and Hub User Manual 

Contents


- [1 ZENDURE ZDPX5PD-B X5 USB-C PD Portable Charger and Hub](#)
- [2 PRODUCT OVERVIEW](#)
- [3 Check the Power Level](#)
- [4 Charge your device](#)
- [5 USB Hub Mode](#)
- [6 X-Charge Mode](#)
- [7 Recharge Your X5](#)
- [8 Caution](#)
- [9 Specifications](#)
- [10 Documents / Resources](#)
- [11 Related Posts](#)

ZENDURE

ZENDURE ZDPX5PD-B X5 USB-C PD Portable Charger and Hub



PRODUCT OVERVIEW



1. power button
2. digital LED indicator
3. USB-C Port
4. USB-A ZEN+2.0


Check the Power Level

- Press the power button, and the LED indicator will display current power level.

○ ○ ○ ○	0%
⊙ ○ ○ ○	≤5%
● ○ ○ ○	6%~25%
● ● ○ ○	26%~50%
● ● ● ○	51%~75%
● ● ● ●	76%~100%


Charge your device

1. Charge your device with USB-A port.



Connect your device to the USB-A output port of X5 with a charge/sync cable. As the device is being charged, the LED indicator display the power level.


2. Charge your device with USB-C PD port



Connect your device to the USB-C PD port of X5 with a USB-C charge/sync cable. As the device is being charged, the LED indicator displays the power level.

Note: To avoid your laptop recharging X5, press and hold the power button for 3seconds to switch power output from X5 to your laptop.


USB Hub Mode



Connect the USB-C Hub port of X5 to USB-C port of your laptop with USB-C to C cable. Double click the power button, and X5 will enter USB hub mode, you can sync and manage your files with 2 USB-A ports. Double click


again to turn off USB hub mode.

X-Charge Mode



Double press power button, X5 will enter X-Charge mode and LED indicator will show as follow. Connect your low-current devices to the USB-A output ports of X5 with a charge/sync cable and they will be continuously charged. Double press power button again to quit X-Charge mode.

Recharge Your X5



Connect the power adapter to the USB-C PD port of your X5 with a USB-C charge/sync cable. During charging, the LED indicator will flash and display the charging power level.

Caution


- Fully charge your Zendure external battery before using it for the first time.
- Storage in a cool and dry place. Recommend storage temperature: -10°C to 45°C; Operating temperature: 0°C to 35°C.
- Do not expose to moisture or submerge it in liquid.
- Do not disassemble or attempt to re-purpose or modify it in any manner
- Use origin or certified cables.
- Stop using and contact manufacturer if the product is excessively hot, is emitting odor, deformed, or any other abnormalities
- Do not clean with harmful chemicals or detergents.

- Do not operate your battery in an enclosed or unventilated environment, such as a carrying bag, pocket or purse, to prevent overheating.
- Avoid strenuous Vibration, impact, extrusion on transportation, and keep the product away from intense sunlight and rain.
- Be cautious of drops, bumps, abrasions, or other impacts.
- Keep it away from children under 3 years old for safety.
- Please dispose of discarded products properly according to local regulations.

Specifications

Model	ZDPX5PD
Battery Cell	High-Density Lithium Battery
Capacity	15,000mAh 3.6V/54Wh
Input	USB-C: 5V \equiv 3A, 9V \equiv 3A, 12V \equiv 3A, 15V \equiv 3A, 20V \equiv 2.25A , 45W Max
Output	USB-C: 5V \equiv 3A, 9V \equiv 3A, 12V \equiv 3A, 15V \equiv 3A, 20V \equiv 2.25A , 45W Max USB-A1/2: 5V \equiv 3A, 9V \equiv 2A, 12V \equiv 1.5A, 18W Max (ZEN+2.0) Total Output: 48W Max
USB Hub	USB 3.0, 5Gbps data transfer
Dimensions	4.5" x 2.9" x 1.0" 114.5mm x 74mm x 25mm
Weight	10.69oz / 303g

Documents / Resources

	ZENDURE ZDPX5PD-B X5 USB-C PD Portable Charger and Hub [pdf] User Manual ZDPX5PD-B, X5 USB-C PD Portable Charger and Hub
---	---

