



ZERO CK2150 Power Timer Coffee Scale User Manual

[Home](#) » [ZERO](#) » ZERO CK2150 Power Timer Coffee Scale User Manual 

Contents

- [1 ZERO CK2150 Power Timer Coffee Scale](#)
- [2 Product Information](#)
- [3 Specifications](#)
- [4 Sign Tips](#)
- [5 Unit Conversion](#)
- [6 Timer operation](#)
- [7 Weighing Operation](#)
- [8 Documents / Resources](#)

ZERO

ZERO CK2150 Power Timer Coffee Scale



Product Information

Sign Tips

- Insert USB cable for charging, the below icon on display is blinking.
- Usually it will take 2-5 hours for full charging, the scale will show FULL as below after fully charge.
- After fully charge, pull out the USB cable, LED display as below.
- When the scale is overloaded:
- When the voltage of the battery is too low, and the scale is unable to work, please charge it in time.
- Weight unstable indication, please put it on a hard and flat surface.

Unit Conversion












- When powered on, the scale will show unit from last use.
- If the user needs to switch the unit, keep short pressing for 2s to change the unit between g-oz-ml.

Timer Operation (2 timing modes for option)

- Manual timing mode operation
 - Press “ ” to turn it on, after a full display and the scale reset to zero, it means ready for weighing.
 - Press “ ” to start timer function. The timer display from 0 to 99m:59s in cycle and will auto off.
 - On timer mode, short press “ ” to stop, touch it again to continue.

- On Timer mode, press “ ” twice to exit manual timing mode.

Specifications

1. **Default unit:** g
2. **Switch button:**  
3. **Auto off time:** about 180s without any operation or after stopped timing.
4. **Manual on/off:** Keep pressing button   for 2s
5. **Min weight indication:** 1g
6. **Capacity:** 3000g
7. **Overload value:** 3600g
8. **Graduation:** 0.1g, 0.005oz, 0.1ml
9. **Power on display:** 
10. **Power:** Lithium-ion rechargeable 3.7V 250mAh
11. **Beep sound:** Along with operation of two buttons   and  
12. **Tare Operation:** On weighing mode, press   to Tare and Zero

Sign Tips




1. Insert USB cable for charging, the below icon on display is blinking.



2. Usually it will take 2-5 hours for full charging, the scale will show FULL as below after fully charge.



3. After fully charge, pull out the USB cable, LED display as below.




4. When the scale is overloaded:



- When the voltage of the battery is too low, and the scale is unable to work, please charge it in time.
- Weight unstable indication, please put it on a hard and flat surface.



Unit Conversion



- When powered on, the scale will show unit from last use.
- If the user need to switch the unit, keep short pressing $\frac{\text{oz/ml/g}}{\text{ZERO}}$ button for 2s to change the unit between g-oz-ml.

Timer operation

Timer operation (2 timing modes for option)

Manual timing mode operation



- Press button $\frac{\text{POWER}}{\text{TIMER}}$ to turn it on, after a full display and the scale reset to zero, it means ready for weighing , press button $\frac{\text{POWER}}{\text{TIMER}}$ to start timer function, The timer display from 0 to 99m:59s in cycle and will auto off.
- On timer mode, short press button $\frac{\text{POWER}}{\text{TIMER}}$ to stop, touch it again to continue.



- On Timer mode, press button $\frac{\text{POWER}}{\text{TIMER}}$ twice to exit manual timing mode

Auto timing mode operation

- Press button $\frac{\text{POWER}}{\text{TIMER}}$ to turn it on, after a full display and the scale reset to zero, it means ready for weighing , short press $\frac{\text{oz/ml/g}}{\text{ZERO}}$ button twice to enter auto timing mode

[0:00 00.] ⇒ [Auto 00.]

- Put a hand-brewed coffee equipment on the scale for weighing, after weight stable, the scale reset to zero automatically.



[Auto 00.] [Auto 1759.] [Auto 00.]

- Load hand-brewed coffee equipment with few coffee powder, press button $\frac{\text{oz/ml/g}}{\text{ZERO}}$ to reset scale to zero.



[Auto 120.] [0:00 00.]

- Pour water into hand-brewed coffee equipment, the scale starts timing automatically.

[0:00 00.] [0:01 1759.]

- After removing all weights, the scale will reset to zero automatically.

[Auto 00.]

- The scale will be auto off after 180 seconds without any operation and stopped timing

How to exit auto timing mode

[Auto 00.] [0:00 00.]

- On auto timing mode, short press button $\frac{\text{oz/ml/g}}{\text{ZERO}}$ twice to exit auto timing mode.

Weighing Operation

[88:88 88888 $\frac{\text{oz}}{\text{ml/g}}$]



[0:00 00. $\frac{\text{g}}{\text{g}}$]

- Put the scale on the flat and hard surface, press button $\frac{\text{POWER}}{\text{TIMER}}$ for 2s to turn it on. After a full display, you will see zero, which means the scale is ready to weigh.


[2000.] ⇒ [00.]

- Put the item that you want to weigh on the scale, and the LED display will show the weight. Press the $\frac{\text{oz/ml/g}}{\text{ZERO}}$ button to reset the scale to zero.

Caution

1. DON'T disassemble this device. If you have any problems, please contact us.
 2. A 250mAh lithium-ion rechargeable battery is built in the scale.
 - Do NOT dispose of them together with the household garbage.
 - Please refer to the local ordinances and recycling instructions regarding disposal of the worn batteries.
 3. Do not use during charging.
 4. This product is powered by a lithium battery. DO NOT charge after its power is used up. It's recommended to charge it in time after it indicate low battery.
-

Documents / Resources

	<p>ZERO CK2150 Power Timer Coffee Scale [pdf] User Manual CK2150 Power Timer Coffee Scale, CK2150, Power Timer Coffee Scale, Timer Coffee Scale, Coffee Scale, Scale</p>
---	--