



ACURITE 00619 Humidity Monitor Instruction Manual

[Home](#) » [Acurite](#) » ACURITE 00619 Humidity Monitor Instruction Manual 

ACURITE 00619 Humidity Monitor Instruction Manual



Congratulations on your new AcuRite product. To ensure the best possible product performance, please read this manual in its entirety and retain it for future reference.

Contents

- [1 Unpacking Instructions](#)
- [2 Package Contents](#)
- [3 Features & Benefits](#)
- [4 SETUP](#)
- [5 OPERATION](#)
- [6 Specifications](#)
- [7 Customer Support](#)
- [8 Limited One Year Warranty](#)
- [9 Documents / Resources](#)
 - [9.1 References](#)
- [10 Related Posts](#)

Unpacking Instructions

Remove the protective film that is applied to the LCD screen prior to using this product. Locate the tab and peel off to remove.

Package Contents

1. Humidity Monitor
2. Instruction Manual


IMPORTANT PRODUCT MUST BE REGISTERED TO RECEIVE WARRANTY SERVICE



PLEASE DISPOSE OF OLD OR DEFECTIVE BATTERIES IN AN ENVIRONMENTALLY SAFE WAY AND IN ACCORDANCE WITH YOUR LOCAL LAWS AND REGULATIONS.

BATTERY SAFETY: Clean the battery contacts and also those of the device prior to battery installation. Remove batteries from equipment which is not to be used for an extended period of time. Follow the polarity (+/-) diagram in the battery compartment. Promptly remove dead batteries from the device. Dispose of used batteries properly. Only batteries of the same or equivalent type as recommended are to be used. DO NOT incinerate used batteries. DO NOT dispose of batteries in fire, as batteries may explode or leak. DO NOT mix old and new batteries or types of batteries (alkaline/standard). DO NOT use rechargeable batteries. DO NOT rechargenon-rechargeable batteries. DO NOT short-circuit the supply terminals

Features & Benefits



1. Current Humidity

2. Humidity Trend Indicator

Arrow icon indicates direction humidity is trending.

3. Current Temperature

Arrow icon indicates direction temperature is trending.

4. High Humidity Record

Highest humidity recorded over 24 hours.

5. Low Humidity Record

Lowest humidity recorded over the past 24 hours.

6. Home Comfort Icon

Indicates a high, low or ideal humidity comfort level.

7. High Temperature Record

Highest temperature recorded over 24 hours.

8. Low Temperature Record

Lowest temperature recorded over 24 hours.

SETUP

Install or Replace Batteries



Batteries must be installed for this product to operate. AcuRite recommends high quality alkaline batteries for the best product performance. Heavy duty or rechargeable batteries are not recommended.

1. Slide off the battery compartment cover.
2. Insert 1 x AA battery into the battery compartment, as shown. Follow the polarity (+/-) diagram in the battery compartment.
3. Replace the battery cover

Select Degrees Fahrenheit or Celsius

Celsius



To select between degrees Fahrenheit (°F) or Celsius (°C) temperature units, press the "°C/°F" button located on the back of the monitor

Placement for Maximum Accuracy

AcuRite product sensors are sensitive to surrounding environmental conditions. Placement in a proper location is critical to the accuracy and performance of this product. Place the monitor in a dry area free of dirt and dust. To ensure accurate temperature measurement, place monitor out of direct sunlight and away from any heat sources or vents.



The monitor comes with a magnetic backing to stick on the fridge. Use pop-out stand for tabletop use

OPERATION

Using the Humidity Monitor

Home Comfort Icon

Home comfort is determined through relative humidity (RH):

- **LOW Humidity Level**



Humidity is low relative to temperature Makes for a **DRY** environment

- **OK Humidity Level**



Humidity is OK relative to temperature Makes for an **IDEAL** environment.

- **HIGH Humidity Level**



Humidity is high relative to temperature Makes for a **HUMID** environment

Learn more at <http://www.acurite.com/humidity-health>

High/Low Records

The “**HI**” and “**LOW**” temperature and humidity records are automatically cleared every 24 hours. The time records clear each day is determined by the time the battery was installed. For example, if the battery was installed at 6:00pm, then high/low records will reset at 6:00pm daily.

Specifications

| | |
|------------------------------|----------------------------------|
| Temperature Range: | 32°F to 122°F; 0°C to 50°C |
| Humidity Range: | 16% – 98% RH (relative humidity) |
| Battery Requirements: | 1 x AA alkaline battery |

Customer Support

AcuRite customer support is committed to providing you with best-in-class service. **For assistance**, please have the model number of this product available and contact us in any of the following ways:



(877) 221-1252



info@chaney-inst.com

24/7 support at www.AcuRite.com

- Installation Videos
- Register your Product
- Instruction Manuals
- Support User Forum
- Replacement Parts
- Submit Feedback & Ideas

Limited One Year Warranty

At AcuRite, we proudly uphold our commitment to quality technology. Chaney Instrument Co. warrants that all products it manufactures to be of good material and workmanship, and to be free of defects when properly installed and operated for a period of one year from the date of purchase.

We recommend that you visit us at www.AcuRite.com for the fastest way to register your product. However, product registration does not eliminate the need to retain your original proof of purchase in order to obtain warranty benefits.

Chaney Instrument Co. warrants that all products it manufactures to be of good material and workmanship, and to be free of defects when properly installed and operated for a period of one year from the date of purchase. Remedy for breach of this warranty is limited to repair or replacement of the defective item(s). Any product which, under normal use and service, is proven to breach the warranty contained herein within ONE YEAR from date of sale will, upon examination by Chaney, and at its sole option, be repaired or replaced by Chaney. Transportation costs and charges for returned goods shall be paid for by the purchaser. Chaney hereby disclaims all responsibility for such transportation costs and charges. This warranty will not be breached, and Chaney will give no credit for products it manufactures which have received normal wear and tear, been damaged (including by acts of nature), tampered, abused, improperly installed, damaged in shipping, or repaired or altered by others than authorized representatives of Chaney

The above-described warranty is expressly in lieu of all other warranties, express or implied, and all other warranties are hereby expressly disclaimed, including without limitation the implied warranty of merchantability and the implied warranty of fitness for a particular purpose. Chaney expressly disclaims all liability for special, consequential or incidental damages, whether arising in tort or by contract from any breach of this warranty. Some states do not allow the exclusion or limitation of incidental or consequential damages, so the above limitation or exclusion may not apply to you. Chaney further disclaims all liability from personal injury relating to its

products to the extent permitted by law. By acceptance of any of Chaney's products, the purchaser assumes all liability for the consequences arising from their use or misuse. No person, firm or corporation is authorized to assume for Chaney any other liability in connection with the sale of its products. Furthermore, no person, firm or corporation is authorized to modify or waive the terms of this paragraph, and the preceding paragraph, unless done in writing and signed by a duly authorized agent of Chaney. This warranty gives you specific legal rights, and you may also have other rights which vary from state to state.

For in-warranty claims: Chaney Instrument Co. 965 Wells St., Lake Geneva, WI 53147

PRODUCT REGISTRATION

Register online to receive 1 year

warranty protection

www.AcuRite.com

- **Weather Stations**



- **Temperature & Humidity**



- **Weather Alert Radio**



- Kitchen Thermometers& Timers



- Clocks



It's More than Accurate, it's

AcuRite offers an extensive assortment of precision instruments, designed to provide you with information you can depend on to Plan your day with confidence™.

www.AcuRite.com

ACURITE®

Documents / Resources

| | |
|--|--|
| | <p>ACURITE 00619 Humidity Monitor [pdf] Instruction Manual 00619, Humidity Monitor</p> |
|--|--|

References

- [Home -](#)
- [AcuRite Weather Monitoring | #1 Weather Station Brand in North America](#)
- [How Indoor Humidity Levels Impact Our Health | AcuRite](#)

Manuals+.