

Fluke FLUKE-355

Fluke 355 True RMS Clamp-Meter User Manual

Model: FLUKE-355

INTRODUCTION

The Fluke 355 digital clamp-meter is a true RMS sensing, auto-ranging multimeter designed for precise measurement of current, voltage, frequency, and resistance in various electrical testing applications. It features a robust clamp mechanism for non-contact current measurement and a comprehensive set of functions for professional use, ensuring accurate readings for both linear and non-linear loads.

SAFETY INFORMATION

Always adhere to safety precautions when working with electrical equipment. This device is designed to meet IEC safety standard 61010-2-032.

- **CAT IV, 600V:** Suitable for measurements at the source of the low-voltage installation, such as electricity meters and primary over-current protection equipment.
- **CAT III, 1,000V:** Suitable for measurements within fixed installations, including switches and industrial equipment permanently connected to the fixed installation.

Ensure proper personal protective equipment (PPE) is used, and always follow local safety regulations when operating this device.

WHAT'S IN THE BOX

Your Fluke 355 Clamp-Meter package includes the following components:

- Fluke 355 digital clamp-meter
- Test lead set
- Test probe set
- Alligator clip set
- (6) AA batteries
- Soft carrying case
- User manual



Image: All components included with the Fluke 355 Clamp-Meter, neatly arranged.

PRODUCT FEATURES

- **True RMS Sensing:** Provides accurate readings for both linear and non-linear loads, regardless of waveform.
- **High Current Measurement:** Measures AC and DC current up to 2,000A (1,400A AC RMS).
- **Large Jaw Opening:** 58mm (2.3 inches) jaw opening accommodates large or multiple conductors for non-contact current measurement.
- **Voltage Measurement:** Measures AC voltage up to 600V and DC voltage up to 1,000V.
- **Frequency and Resistance:** Measures frequency up to 1kHz and resistance up to 400kΩ.
- **Inrush Current Function:** Analyzes surge current during motor startup and other inductive loads for stable measurements.
- **Low-Pass Filter:** Reduces high-frequency interference for accurate measurements of complex waveforms.
- **Min/Max Function:** Toggles to display lowest, highest, and average readings.
- **Data Hold:** Freezes the reading on the display for easy documentation in tight spaces.
- **Continuity Buzzer:** Confirms electrical continuity.
- **Backlit LCD:** Improves visibility in low-light conditions, with automatic backlight shut-off.
- **Auto Power Off:** Conserves battery life by automatically turning off after 20 minutes of non-use.
- **Low-Battery Indicator:** Signals when batteries need replacement.

SETUP

Battery Installation

The Fluke 355 requires six 1.5V AA batteries for operation. These are typically included with your purchase.

1. Locate the battery compartment cover on the back of the device.
2. Use a screwdriver to open the cover.
3. Insert the six AA batteries, ensuring correct polarity (+/-).
4. Replace the battery compartment cover and secure it.

Initial Inspection

Before first use, inspect the clamp-meter, test leads, and accessories for any signs of damage. Do not use the device if any damage is observed.

OPERATING INSTRUCTIONS

Powering On/Off

Turn the rotary switch to any measurement function to power on the device. Turn the rotary switch to "OFF" to power off. The device will automatically power off after 20 minutes of inactivity to conserve battery life.

Measuring AC/DC Current (Clamp Function)

1. Turn the rotary switch to the "A AC+DC" position.
2. Press the jaw release lever to open the clamp jaws.
3. Position the clamp jaws around a single conductor. Ensure the jaws are fully closed.
4. Read the current value on the LCD.



Image: The clamp jaws of the Fluke 355 securely closed around an electrical conductor for current measurement.

Measuring Voltage (AC/DC)

1. Connect the test leads to the appropriate input jacks (COM and V).
2. Turn the rotary switch to the "V AC+DC" position.
3. Connect the test probes across the circuit or component to be measured.
4. Read the voltage value on the LCD.

Measuring Resistance (Ω)

1. Connect the test leads to the appropriate input jacks (COM and Ω).
2. Turn the rotary switch to the " Ω " position.

3. Ensure the circuit is de-energized before measuring resistance.
4. Connect the test probes across the component to be measured.
5. Read the resistance value on the LCD.

Other Functions

- **RANGE:** Manually select the measurement range if auto-ranging is not desired.
- **HOLD:** Press to freeze the current reading on the display. Press again to release.
- **ZERO:** Used to zero out DC current readings or resistance readings for lead compensation.
- **Hz:** Measures frequency.
- **INRUSH:** Measures the peak current during motor startup.
- **MIN MAX:** Toggles through minimum, maximum, and average readings captured during a measurement session.
- **FILTER:** Activates a low-pass filter to reduce electrical noise for stable readings.



Image: Detailed view of the Fluke 355 Clamp-Meter's display and control panel.

MAINTENANCE

Cleaning

Clean the meter casing with a damp cloth and mild detergent. Do not use abrasives or solvents. Keep the display clean and dry.

Battery Replacement

When the low-battery indicator appears on the display, replace all six AA batteries promptly to ensure accurate measurements. Follow the battery installation steps outlined in the Setup section.

Storage

Store the clamp-meter in its soft carrying case in a dry, dust-free environment when not in use. Remove batteries if storing for extended periods to prevent leakage.

TROUBLESHOOTING

If the Fluke 355 Clamp-Meter is not functioning as expected, consider the following:

- **No Display/Power:** Check if the batteries are correctly installed and have sufficient charge. Replace batteries if necessary. Ensure the rotary switch is not in the "OFF" position.
- **Inaccurate Readings:** Verify that the correct measurement function is selected. Ensure test leads are properly connected and not damaged. For current measurements, ensure the clamp jaws are fully closed around a single conductor.
- **Continuity Buzzer Not Working:** Ensure the device is in the continuity measurement mode and the circuit is de-energized.

For persistent issues, refer to the official Fluke support resources or contact customer service.

SPECIFICATIONS

Parameter	Value
Maximum AC Current Input	2,000A (1,400A RMS)
Maximum DC Current Input	2,000A
Maximum AC Voltage Input	600V
Maximum DC Voltage Input	1,000V
Maximum Frequency Detected	1kHz
Maximum Resistance Detected	400kΩ
Installation Rating	CAT IV, 600V; CAT III, 1,000V
Standards Met	IEC safety standard 61010-2-032; CE marking; CSA; Australia N10140
Power Supply	(6) 1.5V AA batteries
Weight	0.814kg / 1.8lb



Parameter	Value
Dimensions (H x W x D)	300 x 98 x 52mm / 12 x 3.75 x 2 inches
Jaw Opening	58mm (2.3 inches)
Auto Power Off	20 minutes
Display	Backlit LCD
True RMS	Yes
Auto-Ranging	Yes
Manufacturer	Fluke Corporation
Model Number	FLUKE-355
UPC	095969401203, 785577871016

WARRANTY AND SUPPORT

Fluke Corporation provides high-quality testing tools. For warranty information, technical support, or service, please visit the official Fluke website or contact their customer service department.

You can find more information and support resources at the [Fluke Store on Amazon](#).


Related Documents - FLUKE-355

	Fluke 381 Remote Display True-rms Clamp Meter User Manual Comprehensive user manual for the Fluke 381 Remote Display True-rms Clamp Meter. Covers product features, measurement procedures for AC/DC current, voltage, resistance, frequency, inrush current, maintenance, specifications, and safety information. Includes detailed descriptions of diagrams and tables.
	Fluke 373 True-RMS AC Clamp Meter - Technical Specifications and Overview Detailed technical data, key features, product overview, specifications, and ordering information for the Fluke 373 True-RMS AC Clamp Meter, designed for AC-only current measurements up to 600 A.

	Fluke 323/324/325 Clamp Meter User Manual - Specifications & Safety Comprehensive user manual for the Fluke 323, 324, and 325 Clamp Meters. Includes safety information, electrical and mechanical specifications, and operating instructions.
	Fluke 305 Clamp Meter User Manual User manual for the Fluke 305 Clamp Meter, providing detailed safety information, product specifications, and operational guidance for accurate electrical measurements.
	Fluke 370 FC Series True-RMS Wireless AC/DC Clamp Meters User Manual & Specifications Comprehensive user manual and technical specifications for the Fluke 370 FC Series True-RMS Wireless AC/DC Clamp Meters, including models 374 FC, 375 FC, and 376 FC. Features, capabilities, comparison charts, and ordering information.
	Fluke 106/107 Palmsized Digital Multimeters: Technical Specifications and Features Detailed technical specifications, product highlights, and general information for the Fluke 106 and 107 palmsized digital multimeters. Learn about their electrical specifications, accuracy, features, and included equipment.

Documents - Fluke – FLUKE-355


[pdf] User Manual Guide Accessories Catalog



TTC 2010 Cover Backcover ENG indd dtp1 Test Tools Catalog CD ROM user s manual and technical notes operator guide Ordering Information Fluke 83V Multimeter 87V True RMS Ex 77779 cesco resources F87

Fluke. Keeping your world up and running. Fluke Corporation P.O. Box 9090 Everett, WA USA 98206 Web: www.fluke.com Fluke Europe B.V. P.O. Box 1186 5602 BD Eindhoven The Netherlands Web: www.fluke.eu For more information call: In the U.S.A. 800 443-5853 or Fax 425 446-5116 In Europe/M-East/Africa...

lang:en score:30 filesize: 6.01 M page_count: 125 document date: 2010-07-15



[\[pdf\]](#)

Fluke 355 and 353 True rms seeanco |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:29 filesize: 471.27 K page_count: 3 document date: 2015-04-05



[\[pdf\]](#) Guide Accessories

Product Guide 2023 2024 Multiproduct Solar panels Fluke Search results 220396 en product guide

complete VersionId 1wqrq56ja9Zs8943cOmv10rCZFnbJbxE dam assets fluke s3fs public 11 |||

PRODUCT GUIDE 2023-2024 Contents What s New at Fluke

ipTM Alligator Clip Set, User Manual. Ordering Information **FLUKE-353** True RMS AC/DC Clamp Meter **FLUKE-355** True RMS AC/DC Clamp Meter Contact your local distributor for price and availability. fl...

lang:de score:29 filesize: 50.07 M page_count: 196 document date: 2023-01-10


[\[pdf\]](#) User Manual Datasheet Warranty

fluke co uk comx show product.aspx pid 37803 e0305445 Fluke 355 and 353 True rms 2000 A Clamp Meters zUser manual z3 year warranty AC DC TRMS CLAMP METER 2000A Includes z355 clamp meter zC43 Soft carrying case z6 AA batteries zTL224 1 5 m silicone rubber test leads zTP2 Test Probes zAC285 Alligator Clips **FLUKE** d3fdwrtpsinh7j cloudfront net Docs datasheet

Fluke 355 and 353 True-rms 2000 A Clamp Meters Versatile and rugged tools for applications with high currents Confidently take reliable readings with the True-rms, Fluke 355 and 353 digital clamp meters; the tools of choice for high current clamp-on amp meter measurement up to 2000 A. The extrawide ...

lang:en score:28 filesize: 858.87 K page_count: 5 document date: 2008-02-05






[\[pdf\]](#) User Manual

Fluke 355 353 HINCO Micronix Includes C43 Soft Carrying Case 6 AA batteries and users manual AC DC True rms Clamp Meter 2000 A TL224 1 5 m Silicone Rubber Test Leads TP2 Probes AC285 Alligator Clips Continuity beeper only On at ≤ 30 W Off ≥ 100 Frequency measurement Amps 2000 hinc au 2015 09

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en **score:28** filesize: 297.17 K page_count: 3 document date: 2016-08-04



[\[pdf\]](#) User Manual Warranty

3m manual Fluke 355 True RMS Clamp Meter 2000 A globaltestsupply s cache |||

353/355 Clamp Meter Users Manual PN 2842223 October 2007 2007 Fluke Corporation, All rights reserved. Printed in China. All product names are trademarks of their respective companies. Find Quality Products Online at: www.GlobalTestSupply.com sales GlobalTestSupply.com LIMITED WARRANTY AND LIMI...

lang:en **score:28** filesize: 1001.01 K page_count: 23 document date: 2015-09-17




[\[pdf\]](#) Guide Accessories

Fluke 2023 2024 product guide V8 W SEA dam assets fluke s3fs public |||

PRODUCT GUIDE 2023-2024 Contents What s New at Fluke

ipTM Alligator Clip Set, User Manual. Ordering Information FLUKE-353 True RMS AC/DC Clamp Meter **FLUKE-355** True RMS AC/DC Clamp Meter Contact your local distributor for price and availability. fl...

lang:en **score:28** filesize: 24.92 M page_count: 99 document date: 2023-04-27




[pdf]

Fluke 355 True RMS 2000 A Clamp Meter ValueTesters valuetesters assets images VT |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:28 filesize: 696.02 K page_count: 3 document date: 2017-02-22




[pdf]

Fluke 355 Datenblatt deutsch fluke 353 datenblatt en cp calplus de fileuploader d 0 file custom upload |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:28 filesize: 568.62 K page_count: 3 document date: 2017-08-24



[pdf]

4596 True RMS 2000 A Clamp Meter Fluke 355 353 Fluke353 transcat ca media |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...


lang:en score:28 filesize: 661.17 K page_count: 3 document date: 2010-05-30



Fluke 355 True RMS 2000 A Clamp Meter m 19 Ampe Kìm Dòng AC DC FLUKE 2000A » BẢO ANH NTH shopdoluong 2022 12 |||


TECHNICAL DATA Fluke 355 True RMS 2000 A Clamp Meter Key features Reliably handle a wide range of hi ... 55 True RMS 2000 A Clamp Meter

https://www.fluke.com/en-vn/product/electrical-testing/clamp-meters/**fluke-355** Range 4 V / 40 V / 400 V / 600 V ac rms Voltage measurement AC 100.1 Hz to 1 kHz 600 ... lang:en **score:28** filesize: 358.43 K page_count: 6 document date: 2022-12-02



ITM Datasheet Template manual Fluke 355 True RMS Clamp Meter 2000 A itm s cache |||

353/355 Clamp Meter Users Manual PN 2842223 October 2007 2007 Fluke Corporation, All rights reserved. Printed in China. All product names are trademarks of their respective companies. 1.800.561.8187 www. .com information itm.com LIMITED WARRANTY AND LIMITATION OF LIABILITY This Fluke product... lang:en **score:27** filesize: 1017.2 K page_count: 23 document date: 2015-03-23



Fluke 355 True RMS 2000 A Clamp Meter 2000A TRMS for High Current testersandtools assets images TT |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en **score:27** filesize: 708.16 K page_count: 3 document date: 2015-09-22

[\[pdf\]](#) Specifications

Specification Sheet Fluke FLUKE 355 600 VAC 1000 VDC 2000 Amp AC DC Clamp Meter Irby 3094045

6115 ENG A W media distributordatasolutions web fluke 2020q1

1bfb433a8a087ce92f12baeca08c124c0a62bf52 |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:27 filesize: 476.42 K page_count: 3 document date: 2007-09-25

[\[pdf\]](#) User Manual Datasheet

Fluke 355 353 Includes C43 Soft Carrying Case 6 AA batteries and users manual AC DC True rms Clamp

Meter 2000 A TL224 1 5 m Silicone Rubber Test Leads TP2 Probes AC285 Alligator Clips Continuity

beeper only On at ≤ 30 W Off ≥ 100 Frequency measurement ISSheet 105502

0111201645175422013725 DATA SHEET EN datasheet bse assets azureedge net tessol data item 1683

64 2013725 instrumart

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:27 filesize: 476.34 K page count: 3 document date: 2007-09-25

[\[pdf\]](#) User Manual Tech Sheet Datasheet Accessories

8639ENEN P21 30 HR Emiel Technical Datasheet Fluke 355 353 ■■■■■■■■■■

2000 True rms Measuretronix Ltd Fluke353 measuretronix files u7

|||

350 Series AC/DC Clamp Meters New Fluke 353 Fluke 355 True RMS Included
Accessories Fluke 353: C43 Soft Meter Case, 6 AA batteries, users manual Fluke
355: C43 Soft Meter Case, 6 AA batteries, TL224 SureGrip Silicone Test Lead Set,
TP2 Slim Reach Test Probe Set 2 mm , AC285 SureGrip Alligator C...

lang:en score:26 filesize: 110.47 K page count: 1 document date: 2008-01-28



Fluke 355/353
True-rms 2000 A Clamp Meters

Technical Data

High current and a large jaw, make these clamp meters well suited for industrial and utility applications

Confidently take reliable readings with the True-rms, Fluke 355/353 Clamp Meters: the tools of choice for high-current measurements up to 2000 A. The extra-wide jaw easily clamps around large conductors, including large high-current applications. The rugged design and CAT IV 600 V, CAT III 1000 V ratings, add an extra element of protection when taking high-powered measurements.

Accurate peak measurements can be taken using the in-rush current mode, ideal for motors and inductive loads. The 355 also measures voltage and resistance, making it the most versatile tool for electric, electronic, communications, and industrial service technicians.

- Installs handles a wide range of high-current applications with 2000 A ac/dc true-rms, 1000 A ac and 1000 V dc
- The high 1000 A ac/dc jaw opening is suitable for large, or multiple conductors
- CAT IV 600 V, CAT III 1000 V rating for added user protection
- In-rush current measurement option 'Inrush-on'
- High voltage measurement of 1000 V ac/dc
- True-rms, 1000 V ac and 1000 V dc allow users to perform multiple tests with one tool (CAT III/IV)
- Resistor to 400 kΩ coupled with a continuity beeper provides the convenience of a multimeter (1500 ohm)
- Assisted measure frequency up to 1 kHz for AC
- Safety analyze readings using the MIN, MAX, and AVG function
- A large backlit display allows for easy visibility in low-light situations
- The backlit hold button to capture readings, even when the display cannot be viewed
- The low-pass filter to smooth the noisy loads and stabilize readings

1.800.561.8187 www.itm.com information@itm.com

FLUKE

Instrument Security Procedures

Model:
Fluke 353 and Fluke 355

Product Name:
High Current AC/DC Clamp Meters

Instrument Description:
353 A only.
355 A, V, Ohms.
Battery powered, true RMS multimeter, 2000A, 600V CATIV measuring capability. 4000 count main display for A, V, Ohms. Secondary display for frequency.

Memory Description:
The 353 and 355 have one memory device (IC1) on the display PCB and 15,360 13,272,80, microcontroller (U1) on the display PCB. The 353, V, Ohms, & contains operating code for the product and calibration constants.

Memory Clearing Instructions:
The user controlled storage operation, other than the calibration constants, is the storage of Min, Max, and Average, Min, Max, and Average data. When the function switch is changed to the MIN MAX function is held for more than one second.

353 - 353 0201 1 47 002287

ГК Аналитический - официальный представитель в РФ и СНГ
+7 (495) 109-02-08 sales@bbrc.ru www.bbrc.ru

FLUKE

Fluke 355/353
True-rms 2000 A Clamp Meters

Technical Data

High current and a large jaw, make these clamp meters well suited for industrial and utility applications

Confidently take reliable readings with the True-rms, Fluke 355/353 Clamp Meters: the tools of choice for high-current measurements up to 2000 A. The extra-wide jaw easily clamps around large conductors, including large high-current applications. The rugged design and CAT IV 600 V, CAT III 1000 V ratings, add an extra element of protection when taking high-powered measurements.

Accurate peak measurements can be taken using the in-rush current mode, ideal for motors and inductive loads. The 355 also measures voltage and resistance, making it the most versatile tool for electric, electronic, communications, and industrial service technicians.

- Installs handles a wide range of high-current applications with 2000 A ac/dc true-rms, 1000 A ac and 1000 V dc
- The high 1000 A ac/dc jaw opening is suitable for large, or multiple conductors
- CAT IV 600 V, CAT III 1000 V rating for added user protection
- In-rush current measurement option 'Inrush-on'
- High voltage measurement of 1000 V ac/dc
- True-rms, 1000 V ac and 1000 V dc allow users to perform multiple tests with one tool (CAT III/IV)
- Resistor to 400 kΩ coupled with a continuity beeper provides the convenience of a multimeter (1500 ohm)
- Assisted measure frequency up to 1 kHz for AC
- Safety analyze readings using the MIN, MAX, and AVG function
- A large backlit display allows for easy visibility in low-light situations
- The backlit hold button to capture readings, even when the display cannot be viewed
- The low-pass filter to smooth the noisy loads and stabilize readings

1.800.561.8187 www.itm.com information@itm.com

[pdf] Guide Declaration of Conformity Accessories Catalog

11500 eng 01 A egastel 45 Thermometer Selection Guide 46 570 Series Precision Infrared Thermometers

47 60 Fluke Test Industrial 2009 xdevs doc

riesenia na presn meranie <http://www.else.sk> <http://www.else.sk> Digital Multimeters

Clamp Meters Electrical Testers Insulation Testers Earth Ground Testers Installation Testers Portable Appliance Testers Digital Thermometers Thermal Imagers Indoor Air Quality Tools ScopeMeter Test Tools Power Qua...

lang:en score:26 filesize: 9.68 M page_count: 116 document date: 2011-12-04

[pdf] Datasheet

ITM Datasheet Template Fluke 355 353355 datasheetitm s cache itm datasheet srsitid

AfmBOooH0kLYGfn uDu2VeBflmSMTxS EX6fasO04FxPizt086oZYX 353Fluke datasheet355

EX6fasO04FxPizt086oZYXitm AfmBOooeiJ4poDpp 4ZVFJA5zziUiE5tdRP17KPz5s AKnWr1xHlclgTY

AfmBOorPUhL X0FvU9dOo7XNPaPhm k7b Eu9tsJjiPuVnFyvp2kdYZitm |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:25 filesize: 559.12 K page_count: 3 document date: 2015-03-23

[pdf] Instructions

353 355 Fluke John Hancock Instrument Security mveng0000 dam assets fluke s3fs public Erklärung zu

flüchtigen Speichern Echteffektiv Strommesszange Fluke 355 bis 2000 A |||

Instrument Security Procedures Model: Fluke 353 and Fluke 355 Product Name: High Current AC/DC Clamp Meters Instrument Description: 353 A only. 355 A, V, Ohms. Battery powered, true RMS multimeter, 2000A, 600V CATIV measuring capability. 4000 count main display for A, V, Ohms. Secondary display for ...

lang:en score:25 filesize: 16.36 K page_count: 1 document date: 2008-01-02

[pdf]

Спецификация Fluke 355 Токовые клещи купить дешево Цена отзывы технические характеристики

описание доставка фото инструкция a6527046 64c3 11e8 80d8 0cc47a1243ef c0328443 8b4f bbrc ru

upload iblock 31d ep6vr428yd3dfn86e5oitgmccq6h1oxv0 |||

7 495 109-02-08 sales bbrc.ru www.bbrc.ru Fluke 355/353 True-rms 2000 A Clamp Meters ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:25 filesize: 617.01 K page_count: 3 document date: 2018-07-19



[pdf] Guide Catalog

Fluke Catalog 2015 2016 multimeter thermal imager calibrator medical scopemeter measurement arta instrument Power Quality Tools 104 Selection Guide USESI 184450 catalog usesi media product catalogs 2015-2016 TEST TOOLS CATALOG Fluke. Keeping your world up and running.

Contents Fluke web and electronic newsletter New from

Fluke..... 2-4 Fluke Combo Kits.....

lang:en score:24 filesize: 17.17 M page_count: 164 document date: 2015-05-15



[pdf] Guide Accessories Catalog

Fluke Test Tools Catalog Product Guide 2020 2021 179 only Ordering Information FLUKE 175 True RMS Digital Multimeter 177 FLUKE78105f80 999b 4280 ba43 b1060069a5c9 original filemedia fluke 78105f80 file apr optimization false |||

PRODUCT GUIDE 2023-2024 Contents What s New at Fluke

ipTM Alligator Clip Set, User Manual. Ordering Information FLUKE-353 True RMS AC/DC Clamp Meter **FLUKE-355** True RMS AC/DC Clamp Meter Contact your local distributor for price and availability. fl...

lang:de score:23 filesize: 50.05 M page_count: 196 document date: 2023-02-08

Specificatii tehnice FLUKE 355		
Măsurare curent c.c./c.a. (10 Hz ... 100Hz)	Domeniu: 40 A Rezoluție: 10 mA / Acuratețe: 1,5 % Domeniu: 400 A Rezoluție: 100 mA / Acuratețe: 1,5 % Domeniu: 2000 A; 1000 ac rms Rezoluție: 1 A / Acuratețe: 1,5 %	
Factor de creștere (50/60 Hz)	Domeniu: 40 A Rezoluție: 10 mA / Acuratețe: 1,5 % Domeniu: 400 A Rezoluție: 100 mA / Acuratețe: 1,5 % Domeniu: 2000 A; 1000 ac rms Rezoluție: 1 A / Acuratețe: 1,5 %	Factor de creștere 2 : 30 A, 2,4 : 30 A Factor de creștere 2 : 300 A, 2,4 : 300 A Factor de creștere 2 : 3000 A, 2,4 : 300 A
Măsurare curent c.c. (100.1 Hz ... 1 kHz)	Domeniu: 40 A Rezoluție: 10 mA / Acuratețe: 1,5 % Domeniu: 400 A Rezoluție: 100 mA / Acuratețe: 1,5 % Domeniu: 2000 A; 1000 ac rms Rezoluție: 1 A / Acuratețe: 1,5 %	
Măsurare tensiune c.c./c.a. 10 Hz ... 100 Hz	Domeniu: 2 V Rezoluție: 100 mV / Acuratețe: 1 % Domeniu: 40 V Rezoluție: 10 mV / Acuratețe: 1 % Domeniu: 400 V Rezoluție: 100 mV / Acuratețe: 1 % Domeniu: 1000 V ac Rezoluție: 1 V / Acuratețe: 1 %	
Măsurare tensiune c.a. 100.1 Hz ... 1 kHz	Domeniu: 2 V Rezoluție: 100 mV / Acuratețe: 1 % Domeniu: 40 V Rezoluție: 10 mV / Acuratețe: 1 % Domeniu: 400 V Rezoluție: 100 mV / Acuratețe: 1 % Domeniu: 1000 V ac Rezoluție: 1 V / Acuratețe: 1 %	
Măsurare rezistență	Domeniu: 400 Ω Rezoluție: 10 Ω / Acuratețe: 1 % Domeniu: 4000 Ω Rezoluție: 100 Ω / Acuratețe: 1 % Domeniu: 40 kΩ Rezoluție: 1 kΩ / Acuratețe: 1,5 % Domeniu: 400 kΩ Rezoluție: 10 kΩ / Acuratețe: 1,5 %	
Continuitate	De la 0 Ω la 50 Ω Rezoluție: 0,1 Ω / Acuratețe: 1,5 %	
Măsurare frecvență	Domeniu: 50 Hz ... 1 kHz Rezoluție: 0,1 Hz / Acuratețe: 1,5 %	

[pdf]

Tatiana Kubanda Fluke 355 cleste de curent AC DC masoara pana la 2000A CAT IV 600 V III 1000 ARC

BrasovFisa tehnica 355arc ro userfiles docs FLUKE Files 1 Masuratori Uz General Clamp Meters Fise

tehnice Fisa |||


Specificatii tehnice FLUKE 355 M surare curent cc/ca 10 Hz 100Hz Factor de creast 50/60 Hz M surare curent ca 100.1 Hz 1 kHz M surare tensiune cc/ca 10 Hz ... 100 Hz M surare tensiune c.a. 100.1 Hz 1 kHz M surare rezisten e Continuitate M surare frecven Domeniu : 40 A ...

lang:es score:23 filesize: 203.61 K page_count: 2 document date: 2015-09-22



[\[pdf\]](#) User Manual Reference Guide Guide Catalog

FLUKE Test Tools Catalog Thermo Fisher Scientific HART communication for testing smart transmitters
For more Manual and Quick Reference Guide Optional magnetic hanger easy setup fluke g test tools
assets thermofisher TFS Assets ANZ Catalogs information on the Fluke 87V MAX True RMS Digital
Multimeter see page 17 simple thermostatic switch a Calibration Field Metrology TEST TOOLS
CATALOGUE ||| 2020 TEST TOOLS CATALOGUE About Fluke Dedicated to your safety, driven by your
success At Fluke, we re working every day so you can do your essential work with confidence. We are d
2020 TEST TOOLS CATALOGUE About Fluke Dedicated to your safety, driven by
your success At Fluke, w ... ipTM Alligator Clip Set, User Manual. Ordering
Information FLUKE-353 True RMS AC/DC Clamp Meter **FLUKE-355** True RMS
AC/DC Clamp Meter Contact your local distributor for price and availability. ww...
lang:en score:23 filesize: 37.5 M page_count: 184 document date: 2020-03-25



[\[pdf\]](#) User Manual Declaration of Conformity

Microsoft Word chapt x doc rocknrol 353 355 Manual do UsuárioAlicate Amperímetro True RMS 2000 A
Fluke Alicates Flukef003643c 5379 4777 872a b2e30170feba original filemedia fluke f003643c file |||
355 Clamp Meter Manual do Usu rio October 2007 Rev. 2, 5/25 Portugu s 2007-2025
Fluke Corporation. All rights reserved. All rights reserved. Especifica es sujeitas a
altera es sem aviso pr vio. All product names are trademarks of their respective
companies. GARANTIA LIMITADA E LIMITA...
lang:pt score:23 filesize: 938.78 K page_count: 20 document date: 2025-05-20

[\[pdf\]](#) Guide Accessories Catalog

Fluke Bahasa Indonesia Alat dan Perangkat Lunak Pengujian Pengukurana6e760f6 182f 4de8 a020
b30f014297c4 original filemedia fluke a6e760f6 file PengukuranFluke Test Measurement Tools
Softwarea6e760f6 filea6e760f6 PRODUCT GUIDE 2025 2026 PT Tunas Dielektrika NusantaraMake
decisions quicker than before by viewing temperature mechanical electrical and vibration measurements
from one location Page 5 7 6 air unobstructed Fluke Softwarev1a6e760f6 filetunasdielektrika v2 Pdfs
catalogs GUIDEmedia NusantaraPRODUCT unobstructed The 3000 FC Wireless Digital Multimeter
displays its own readings plus up to three wireless modules The 173X Power Loggers 174X Power Fluke
Softwarev1Fluke GUIDEa6e760f6 GUIDEtunasdielektrika ||| ||| PRODUCT GUIDE 2025-2026 Content
Fluke ConnectTM2 Selection Guide5 Wireless Current Clamp Modules 6-7 Wireless Voltage Modules8
Wireless K-Type Temperature Module9 Fluke Connect Accessories.10 Digital Multimeters11 Selection
Guide12 Wireless ||| PRODUCT GUIDE 2025-2026 Content Fluke ConnectTM2 Selection Guide5
Wireless Current Clamp Modules 6-7 Wireless Voltage Modules8 Wireless K-Type Temperature Module9
Fluke Connect Accessories.10 Digital Multimeters11 Selection Guide12 Wireless
PRODUCT GUIDE 2025-2026 Content Fluke ConnectTM2 Selection Guide5 Wireless
Current Clamp Modules 6-7 Wireless Voltage Modules8 Wireless K-Type
Temperature Module9 Fluke Connect Accessories.10 Digital Multimeters11 Selection
Guide12 Wireless Digital Multimeter13 True-RMS Logging Multimeters 14-15 ...
lang:en score:22 filesize: 43.79 M page_count: 101 document date: 2025-06-06




[\[pdf\]](#) User Manual Guide Accessories Catalog

Fluke 2017 2018 Test Tools Catalog Manual focus Connect app compatible Yes blended visual and infrared images 902 Included accessories Soft carrying case users manual catalog assets testequity te1 Documents fluke

CONTENTS What is Fluke surement to 1 kHz Selectable low-pass filter mode Min/Max/Avg Ordering information True Models **FLUKE-355** AC/DC True-rms Clamp Meter **FLUKE-353** AC/DC True-rms Clamp Meter Included accessories Sof...

lang:fr **score:22** filesize: 13.97 M page_count: 100 document date: 2016-11-10



[\[pdf\]](#) User Manual Declaration of Conformity

Microsoft Word chapt x doc rocknrol 353 355 Manual del usuarioPinza amperimétrica Fluke de verdadero valor eficaz 2000 A Flukeb9b449c8 8987 4ba3 ad35 b2e3017100ab original filemedia fluke b9b449c8 file usuario353 FlukePinza Fluke355 umspa0200b9b449c8 filedam assets s3fs public umspa0200 VersionId 7npxErzDOuolH5cUhtJqGFvb4Zikm4Dmedia ||| ||| 355 Clamp Meter Manual de uso October 2007 Rev. 2, 5/25 Espaol 2007-2025 Fluke Corporation. All rights reserved. Especificaciones sujetas a cambios sin previo aviso. All product names are trademarks of their respective companies. GARANTA LI 355 Clamp Meter Manual de uso October 2007 Rev. 2, 5/25 Espaol 2007-2025 Fluke Corporation. All rights reserved. Especificaciones sujetas a cambios sin previo aviso. All product names are trademarks of their respective companies. GARANTA LIMITADA Y LIMITACIN DE RESPONSABILIDAD Se garantiza que ...

lang:es **score:22** filesize: 916.64 K page_count: 20 document date: 2025-05-20




[\[pdf\]](#)

Fluke multi clamp 355 cp GALCO industrial electronics fluke galco techdoc flke |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en **score:20** filesize: 471.8 K page_count: 3 document date: 2015-08-11



[pdf] Instructions

353 355 SOMV R0 ENG Fluke John Hancock Verklaring vluchtigheid geheugenFluke True rms 2000 A

stroomtangen Fluked6d12074 6a7f 46e1 b86e b10800c19aa4 original filemedia fluke d6d12074 file

geheugen353 Statement of memory volatilityFluke FlukeFluke RMS Clamp Meter filed6d12074

Declaración de volatilidad la memoria353 volatilityPinza amperimétrica verdadero valor eficaz Fluke353

mveng0000d6d12074 filedam assets s3fs public mveng0000 VersionId bmAik

jpgkBZxYL7bEieonR79ILf9S6pmedia ||| ||| Instrument Security Procedures Model: Fluke 353 and Fluke 355

Product Name: High Current AC/DC Clamp Meters Instrument Description: 353 A only. 355 A, V, Ohms.

Battery powered, true RMS multimeter, 2000A, 600V CATIV measuring capability. 40


Instrument Security Procedures Model: Fluke 353 and Fluke 355 Product Name: High

Current AC/DC Clamp Meters Instrument Description: 353 A only. 355 A, V, Ohms.

Battery powered, true RMS multimeter, 2000A, 600V CATIV measuring capability.

4000 count main display for A, V, Ohms. Secondary display for ...

lang:en score:20 filesize: 22.45 K page_count: 1 document date: 2023-03-09



[pdf] User Manual

8639DEDE P21 30 HR Emiel Fluke 350 Serie Katalogserie 355 fluke serie katalogseite de cp calplus

fileuploader d 0 file custom upload |||


Serie 350 Gleich-/ Wechselstrommesszangen Neu Fluke 353 Fluke 355 Echteffektiv

Lieferumfang Fluke 353: C43 Gepolsterte MultimeterTragetasche, 6 Batterien, Typ

AA, Benutzerhandbuch Fluke 355: C43 Gepolsterte MultimeterTragetasche, 6

Batterien, Typ AA, TL224 SureGrip Silikon-Messleitungssatz, TP2 Mes...

lang:de score:20 filesize: 180.23 K page_count: 1 document date: 2017-08-24



[pdf]


Каталог измерительных приборов Fluke 2009 Corporation Рекламный проспект на токовые клещи

355 РУСРекламные проспекты аппаратуры355 rpiva telecom org SHOP FILES FLUKE rp 353

РУСРекламный аппаратурыРекламные аппаратуры353 rp355 |||

350 Fluke 353 True-RMS 2000 ...

lang:i-klngon score:20 filesize: 480.77 K page_count: 1 document date: 2009-08-28



[pdf]

True rms 2000 A Clamp Meters Models May 9 2025 — Confidently take reliable readings with the true Fluke 355 353 tools of choice for high current measurements tocimages files 296262 633253 cms katranji web content 627809 |||

True-rms 2000 A Clamp Meters Models: 353,355 High current and a large jaw, make these clamps well suited for industrial and utility applications Confidently take reliable readings with the true-rms, Fluke 355/353 Clamp Meters; the tools of choice for high-current measurements up to 2000 A. The ext...

lang:en score:20 filesize: 636.88 K page_count: 3 document date: 2023-10-20



[pdf]

Fluke 353 355 assets testequity te1 Documents |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:20 filesize: 477.61 K page_count: 3 document date: 2009-12-17




[pdf] Specifications Accessories

Fluke 353 355 AC DC True rms Clamp meters FLUKE primebuy product |||

Fluke 353/355 AC/DC True-rms Clamp Meters Versatile, professional, accurate Confidently take reliable readings with the true-rms Fluke 355 and 353 Clamp Meters—the tools of choice for high current clamp-on amp meter measurements up to 2000 A. Reliably handle a wide range of high-current applicatio...

lang:en score:20 filesize: 329.73 K page_count: 1 document date: 2012-03-08




[pdf]

Fluke 353 355 Clamp Meter fluke clamp meter test and measurement instruments c tmi t m i Test Measurement Instruments C instrumentsgroup co za index files |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:20 filesize: 445.12 K page_count: 3 document date: 2013-05-11




[pdf]

Fluke 353 True RMS 2000 A Clamp Meter ValueTesters valuetesters assets images VT |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en **score:19** filesize: 696.03 K page_count: 3 document date: 2017-02-22




[pdf] Datasheet

Untitled Fluke 353 355 1000 Volts Clamp Meter New valuetronics media vti datasheets |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en **score:19** filesize: 219.95 K page_count: 3 document date: 2016-08-24



[pdf]

untitled Adam Karta katalogowa Miernik cęgowy Fluke 353 2000A DC 1400A AC Merazet Poznań

8715c2d2 merazet pl img |||

Mierniki cęgowe prądu przemiennego i stałego serii 350 Fluke 353 Mierniki cęgowe rzeczywistej wartości skutecznej prądu stałego i przemiennego o nateniu do 2000 A do zastosowa w przemyśle i energetyce Dokładne pomiary rzeczywistej wartości skutecznej dziki miernikom cęgowym Fluke 353/355 najlepszym przy...

lang:pl **score:19** filesize: 309.04 K page_count: 1 document date: 2013-04-15

Fluke 355/353

True-rms 2000 A Clamp Meters

Technical Data

High current and a large jaw, make these clamps well suited for industrial and utility applications

Confidence take reliable readings with the Fluke 355/353 Clamp Meters, the tools of choice for high-current measurements up to 2000 A. The extra-wide jaw easily clamps around large conductors typically found in high-current applications. The rugged design and CAT IV 600 V, CAT II 1000 V ratings, add an extra element of protection when using high-powered measurements.

Accurate peak measurements can be taken using the true-rms current mode, ideal for motors and inductive loads. The 355 also measures voltage and resistance, making this the most versatile tool for utilities, electrical contractors, and industrial service technicians.

- Instantly reads a wide range of high-current applications with 2000 A ac/dc true-rms, 1000 V ac/dc 2000 V ac
- The large 58 mm (2.3 in) jaw capacity is suitable for large, industrial conductors
- CAT IV 600 V, CAT II 1000 V rating for added user protection
- True-rms current measurement captures "system" or average current with accuracy and immediacy
- High voltage measurement at 1000 V ac/dc
- Resistance measurement at 200 Ω ac/dc
- Non-invasive, 300 V ac/dc 1000 V ac/dc clamp design performs multiple tests with only one tool (200 only)
- Insensitive to 50/60 Hz magnetic fields, a readability booster, provides the convenience of a multimeter (200 only)
- Continuously measures frequency up to 1 kHz for system troubleshooting
- Quick capture readings using the hold, MAX, and MIN buttons
- A large backlit display allows for easy visibility in low-light areas
- Use the display hold button to capture readings even when the display cannot be viewed
- Use the freeze button to freeze not only reads and statistic readings

1.800.561.8187 www.itm.com information@itm.com

[pdf] Datasheet

ITM Datasheet Template datasheet Fluke 353 True RMS Clamp Meter 2000 A itm s cache |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:19 filesize: 559.12 K page_count: 3 document date: 2015-03-23

Fluke 355/353

True-rms 2000 A Clamp Meters

Technical Data

High current and a large jaw, make these clamps well suited for industrial and utility applications

Confidence take reliable readings with the Fluke 355/353 Clamp Meters, the tools of choice for high-current measurements up to 2000 A. The extra-wide jaw easily clamps around large conductors typically found in high-current applications. The rugged design and CAT IV 600 V, CAT II 1000 V ratings, add an extra element of protection when using high-powered measurements.

Accurate peak measurements can be taken using the true-rms current mode, ideal for motors and inductive loads. The 355 also measures voltage and resistance, making this the most versatile tool for utilities, electrical contractors, and industrial service technicians.

- Instantly reads a wide range of high-current applications with 2000 A ac/dc true-rms, 1000 V ac/dc 2000 V ac
- The large 58 mm (2.3 in) jaw capacity is suitable for large, industrial conductors
- CAT IV 600 V, CAT II 1000 V rating for added user protection
- True-rms current measurement captures "system" or average current with accuracy and immediacy
- High voltage measurement at 1000 V ac/dc
- Resistance measurement at 200 Ω ac/dc
- Non-invasive, 300 V ac/dc 1000 V ac/dc clamp design performs multiple tests with only one tool (200 only)
- Insensitive to 50/60 Hz magnetic fields, a readability booster, provides the convenience of a multimeter (200 only)
- Continuously measures frequency up to 1 kHz for system troubleshooting
- Quick capture readings using the hold, MAX, and MIN buttons
- A large backlit display allows for easy visibility in low-light areas
- Use the display hold button to capture readings even when the display cannot be viewed
- Use the freeze button to freeze not only reads and statistic readings

1.800.544.2843 www.calcert.com sales@calcert.com

[pdf] Datasheet

ITM Datasheet Template datasheet Fluke 353 True RMS Clamp Meter 2000 A calcert s cache |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en score:19 filesize: 567.17 K page_count: 3 document date: 2022-03-29

Fluke 353

True-rms 2000 A Clamp Meter

Technical Data

High current and a large jaw, make these clamps well suited for industrial and utility applications

Confidence take reliable readings with the Fluke 353 Clamp Meter, the tool of choice for high-current measurements up to 2000 A. The extra-wide jaw easily clamps around large conductors typically found in high-current applications. The rugged design and CAT IV 600 V, CAT II 1000 V ratings, add an extra element of protection when using high-powered measurements.

Accurate peak measurements can be taken using the true-rms current mode, ideal for motors and inductive loads. The 353 also measures voltage and resistance, making this the most versatile tool for utilities, electrical contractors, and industrial service technicians.

- Instantly reads a wide range of high-current applications with 2000 A ac/dc true-rms, 1000 V ac/dc 2000 V ac
- The large 58 mm (2.3 in) jaw capacity is suitable for large, industrial conductors
- CAT IV 600 V, CAT II 1000 V rating for added user protection
- True-rms current measurement captures "system" or average current with accuracy and immediacy
- High voltage measurement at 1000 V ac/dc
- Resistance measurement at 200 Ω ac/dc
- Non-invasive, 300 V ac/dc 1000 V ac/dc clamp design performs multiple tests with only one tool (200 only)
- Insensitive to 50/60 Hz magnetic fields, a readability booster, provides the convenience of a multimeter (200 only)
- Continuously measures frequency up to 1 kHz for system troubleshooting
- Quick capture readings using the hold, MAX, and MIN buttons
- A large backlit display allows for easy visibility in low-light areas
- Use the display hold button to capture readings even when the display cannot be viewed
- Use the freeze button to freeze not only reads and statistic readings


1.800.544.2843 www.calcert.com sales@calcert.com

[pdf]

Fluke 353 Datenblatt deutsch fluke datenblatt de cp calplus fileuploader d 0 file custom upload |||

Technische daten Echteffektiv-Strommesszange Fluke 353 bis 2000 A Wichtigste Merkmale Bewltigen Sie zuverlssig Aufgaben im Hochstrombereich mit 2000 A Wechsel- und Gleichstrom Echteffektivwert, 1400 A Wechselstrom und 2000 A Gleichstrom. Die Zange mit einer ffnung von 58 mm eignet sich fr dicke oder...

lang:de score:19 filesize: 228.33 K page_count: 5 document date: 0000-00-00




[\[pdf\]](#) User Manual Specifications Accessories

8639ENEN P21 30 HR Emiel Download Fluke 353 2000A AC DC Clamp Meter specFLU353 instrotech
pub media specifications |||

350 Series AC/DC Clamp Meters New Fluke 353 Fluke 355 True RMS Included
Accessories Fluke 353: C43 Soft Meter Case, 6 AA batteries, users manual Fluke
355: C43 Soft Meter Case, 6 AA batteries, TL224 SureGrip Silicone Test Lead Set,
TP2 Slim Reach Test Probe Set 2 mm , AC285 SureGrip Alligator C...

lang:en **score:19** filesize: 108.9 K page_count: 1 document date: 2008-01-28



[\[pdf\]](#) User Manual Accessories

8639ENEN P21 30 HR Emiel fluke353 355 en 5b5708e98065fmikroprinc store products 5b5708e98065f


Fluke cleste de curent AC DC masoara pana la 2000A CAT IV 600 V III 1000 ARC Brasovfluke353

5b5708e98065fFluke Specificatii Tehnice ENmikroprinc 5b5708e98065farc ro userfiles docs FLUKE Files

1 Masuratori Uz General Clamp Meters EN |||

350 Series AC/DC Clamp Meters New Fluke 353 Fluke 355 True RMS Included
Accessories Fluke 353: C43 Soft Meter Case, 6 AA batteries, users manual Fluke
355: C43 Soft Meter Case, 6 AA batteries, TL224 SureGrip Silicone Test Lead Set,
TP2 Slim Reach Test Probe Set 2 mm , AC285 SureGrip Alligator C...

lang:en **score:19** filesize: 110.47 K page_count: 1 document date: 2008-01-28



[\[pdf\]](#) User Manual Borchure


8639DEDE P21 30 HR Emiel Fluke 350 series AC DC ClampMeters brochure D Linktronix 1445330849

5625ffa173283 linktronix ch resources public liveedit media |||

Serie 350 Gleich-/ Wechselstrommesszangen Neu Fluke 353 Fluke 355 Echteffektiv
Lieferumfang Fluke 353: C43 Gepolsterte MultimeterTragetasche, 6 Batterien, Typ
AA, Benutzerhandbuch Fluke 355: C43 Gepolsterte MultimeterTragetasche, 6
Batterien, Typ AA, TL224 SureGrip Silikon-Messleitungssatz, TP2 Mes...

lang:de **score:19** filesize: 114.05 K page_count: 1 document date: 2008-01-28

lang:fr score:19 filesize: 608.22 K page_count: 1 document date: 2015-10-06



[pdf] Datasheet

3m datasheet Fluke 353 True RMS Clamp Meter 2000 A globaltestsupply s cache |||

Fluke 355/353 True-rms 2000 A Clamp Meters Technical Data High current and a large jaw, make these ... s Clamp Meter, 2000 A, Amps only Includes: C43 Soft Carrying Case, 6 AA batteries, and users manual **Fluke-355** AC/DC True-rms Clamp Meter, 2000 A Includes: C43 Soft Carrying Case, 6 AA batteries, TL224...

lang:en **score:19** filesize: 548.56 K page_count: 3 document date: 2015-09-17



[pdf]

Strommesszangen und Elektro Tester Flexible Stromzange iFlex™ 45 cm Fluke 381 Messleitungen gepolsterte Tragetasche Anweisungskarte Sicherheitsinformationen zwei Alkali Batterien Typ fluke
ubersicht stromzangen katalogseiten de calplus fileuploader d 0 file custom upload |||

Strommesszangen und Elektro-Tester Die ergonomischen Strommesszangen sind mit weit ffnenden Klemm backen fr sichere und schnelle Strommessungen ohne Auftrennung der Leitungen geeignet. Die Leckstrommesszange 360 ist ideal fr die Messung von Leckstrmen ohne Unterbrechung des Stromkreises. Die neuen f...
lang:de **score:19** filesize: 1.01 M page_count: 8 document date: 2016-03-07