

## Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

manuals.plus /

- › [Camco](#) /
- › [Camco No Insect RV Bumper Cap \(Model 40325\) Instruction Manual](#)

### Camco 40325

# Camco No Insect RV Bumper Cap (Model 40325) Instruction Manual

## 1. PRODUCT OVERVIEW

The Camco No Insect RV Bumper Cap (Model 40325) is designed to replace lost or damaged RV bumper caps. These caps feature strategically placed vent holes that allow for essential air circulation within your RV's 4-inch square bumper, while simultaneously preventing insects from nesting inside. Constructed from durable polyethylene, they offer a secure fit and are built for longevity. The integrated squeeze grip design facilitates easy installation and removal.



Image 1.1: Two Camco No Insect RV Bumper Caps, showing their design with vent holes and squeeze grip.

### Key Features:

- **Insect Prevention:** Smaller vent holes keep nesting insects out.
- **Ventilation:** Allows air flow to prevent moisture buildup and odors, especially when storing sewer hoses.
- **Easy Installation & Removal:** Features a squeeze grip for convenient handling.
- **Compatibility:** Designed to fit standard OEM 4-inch square RV bumpers.
- **Durable Construction:** Made from robust polyethylene for extended use.

---

## 2. WHAT'S IN THE BOX

---

Each package of Camco No Insect RV Bumper Caps contains the following:

- (2) Camco No Insect RV Bumper Caps



Image 2.1: Packaging for the Camco No Insect RV Bumper Cap, indicating a 2-count pack.

### 3. INSTALLATION

---

Follow these steps to install the Camco No Insect RV Bumper Caps:

1. **Prepare the Bumper:** Ensure your RV's 4-inch square bumper opening is clean and free from debris.
2. **Align the Cap:** Hold the bumper cap with the "SQUEEZE" text facing outwards.
3. **Insert the Cap:** Gently push the ribbed side of the cap into the bumper opening.
4. **Secure the Cap:** Apply firm pressure, squeezing the grip area if necessary, until the cap is fully seated and secure within the bumper. The flexible polyethylene material and grip ribs will create a snug fit.



Image 3.1: A hand demonstrating the installation of the Camco No Insect RV Bumper Cap into a standard RV bumper.

#### Video: Camco No Insect RV Bumper Cap Overview

Your browser does not support the video tag.

Video 3.1: This video provides a detailed overview of the Camco No Insect RV Bumper Cap, highlighting its features and installation process.

---

### 4. OPERATION

The primary function of the Camco No Insect RV Bumper Cap is to secure the contents within your RV's

square bumper, typically a sewer hose, while providing necessary ventilation and preventing insect entry.

- **Sewer Hose Storage:** The bumper is a common place to store a sewer hose. The caps ensure the hose remains contained.
- **Ventilation:** The small holes in the cap allow air to circulate, which is crucial for drying out the sewer hose and preventing unpleasant odors or moisture buildup inside the bumper.
- **Insect Barrier:** The small size of the vent holes effectively blocks flying insects, such as wasps or mud daubers, from entering and nesting within the bumper, protecting your stored items and preventing potential blockages.

## Removal:

To remove the cap, firmly grasp the squeeze grip area and pull outwards. The flexible material is designed to allow for easy removal when needed.

---

## 5. MAINTENANCE

---

The Camco No Insect RV Bumper Caps require minimal maintenance:

- **Cleaning:** Periodically inspect and clean the caps with mild soap and water to remove any dirt or debris that may accumulate in the vent holes.
- **Inspection:** Check the caps regularly for any signs of wear, cracking, or damage. While made of durable polyethylene, extreme weather conditions or prolonged exposure may eventually affect the material. Replace if significant damage is observed to maintain optimal function.

---

## 6. TROUBLESHOOTING

---

- **Cap is Difficult to Install:** Ensure the bumper opening is clean. Apply even pressure and slightly squeeze the grip area to compress the ribs for easier insertion.
- **Cap is Difficult to Remove:** Firmly grasp the squeeze grip and pull directly outwards. If the cap has been in place for a long time, the material might have settled. A slight twisting motion while pulling may help.
- **Insects are Still Entering:** Verify that the caps are fully seated and there are no gaps around the edges. The vent holes are designed to be small enough to prevent most common nesting insects.

---

## 7. SPECIFICATIONS

---

<b>Brand</b>	Camco
<b>Model Number</b>	40325
<b>Material</b>	Polyethylene
<b>Color</b>	Black
<b>Item Weight</b>	5.8 ounces (approx. per pair)

<b>Product Dimensions</b>	10"D x 11"W x 11"H (packaging dimensions, actual cap fits 4" square bumper)
<b>Compatibility</b>	Standard OEM 4-inch square RV bumpers
<b>Vehicle Service Type</b>	RVs, Campers, Trailers

---

## 8. WARRANTY AND SUPPORT

---

For warranty information, product support, or to explore other Camco products, please visit the official Camco website or contact their customer service. You can find more information at the [Camco Store on Amazon](#).

---