

[Manuals+](#)

[Q & A](#) | [Deep Search](#) | [Upload](#)

**Moen 3814ORB**

## Moen Brantford 1/2-Inch Diverter Tub Spout

MODEL: 3814ORB - USER MANUAL

### Product Overview

The Moen 3814ORB Brantford Diverter Tub Spout is designed to restore your bathing area's functionality and aesthetic. Featuring an Oil-Rubbed Bronze finish, it offers a rich, dark brown appearance with striking light and dark accents, complementing traditional bathroom designs. This tub spout includes a lift rod for diverting water flow between the tub and a showerhead, ensuring versatile use.

Constructed from corrosion-resistant metal, this spout is built for durability and designed for straightforward installation. It accommodates most bathtubs with its 7.25-inch length.



Image: Moen Brantford 1/2-Inch Diverter Tub Spout, Oil Rubbed Bronze finish.

### Setup and Installation

This section provides general guidance for installing the Moen 3814ORB tub spout. While designed for hassle-free installation, professional plumbing assistance is recommended if you are unfamiliar with plumbing work.

#### Important Note on Connection Type:

Please be aware that despite the product title, this tub spout features a threaded connection, not a slip-fit connection. Ensure your existing plumbing is compatible or prepared for a threaded installation. This may require a brass nipple and appropriate coupler if replacing a rear-threaded spout.

- 1. Prepare the Area:** Turn off the main water supply to your bathroom. Drain any remaining water from the pipes by opening the existing tub spout and shower valve.
- 2. Remove Old Spout:** Depending on your current spout type, you may need to unscrew it or loosen a set screw underneath. Clean the pipe and wall area thoroughly.
- 3. Prepare the Pipe:** Ensure the pipe extending from the wall is clean and free of debris. For threaded connections, apply plumber's tape (Teflon tape) clockwise around the threads of the pipe to ensure a watertight seal.
- 4. Install New Spout:** Carefully thread the Moen 3814ORB tub spout onto the pipe. Turn clockwise until it is hand-tight, then use a wrench to tighten it an additional quarter to half turn, ensuring the spout is level and facing forward. Do not overtighten.
- 5. Test for Leaks:** Slowly turn the main water supply back on. Check for any leaks around the base of the new tub spout. If leaks occur, turn off the water, tighten slightly, and re-test.

## Operating Instructions

- The Moen Brantford Diverter Tub Spout is designed for simple operation to switch between tub filling and showering.
- Tub Filling:** To fill the bathtub, ensure the diverter lift rod on top of the spout is in the down position. Water will flow directly from the spout into the tub.
  - Showering:** To divert water to your showerhead, pull the lift rod upwards. This will redirect the water flow from the tub spout to the connected showerhead. Once you are finished showering, push the lift rod back down to resume water flow to the tub spout.

## Maintenance and Care

- To maintain the beauty and functionality of your Moen Brantford Oil-Rubbed Bronze tub spout, follow these care guidelines:
- Regular Cleaning:** Clean the spout regularly with a soft, damp cloth. For stubborn spots, use a mild soap and water solution. Rinse thoroughly and dry with a soft cloth to prevent water spots.
  - Avoid Harsh Cleaners:** Do not use abrasive cleaners, harsh chemicals, ammonia-based products, or polishing agents, as these can damage the Oil-Rubbed Bronze finish and void the warranty.
  - Protect the Finish:** The Oil-Rubbed Bronze finish is designed to be durable and corrosion-resistant. Avoid scratching the surface with sharp objects or abrasive materials.
  - Check for Leaks:** Periodically inspect the connection point for any signs of leaks. Address any leaks promptly to prevent water damage.

## Troubleshooting

This section addresses common issues you might encounter with your tub spout.

Problem	Possible Cause	Solution
Water leaks from the base of the spout.	Loose connection or insufficient plumber's tape.	Turn off water supply, remove spout, reapply plumber's tape to pipe threads, and re-install, ensuring a snug fit. Do not overtighten.

Problem	Possible Cause	Solution
Water does not fully divert to the showerhead.	Diverter mechanism issue or low water pressure.	Ensure the lift rod is fully pulled up. Check household water pressure. If the issue persists, the diverter mechanism may need inspection by a qualified plumber.
Spout is difficult to install due to connection type.	Misunderstanding of threaded vs. slip-fit connection.	This model is <b>threaded</b> . If your existing plumbing requires a slip-fit, you will need to adapt the pipe (e.g., by adding a brass nipple) or consider a different product. Consult a plumber for assistance.

## Specifications

- **Brand:** Moen
- **Model Name:** Brantford
- **Part Number:** 3814ORB
- **Color:** Oil Rubbed Bronze
- **Material:** Metal
- **Mounting Type:** Wall Mount
- **Spout Length:** 7.25 inches (accommodates most bathtubs)
- **Connection Type:** Threaded (1/2-Inch)
- **Included Components:** Tub Spout
- **Item Weight:** 1.37 pounds
- **Product Dimensions:** 11.75 x 5.88 x 3.69 inches
- **Special Features:** Intricate Architectural Details, Diverter Function
- **UPC:** 026508251065





## Warranty and Support

The Moen 3814ORB Brantford Diverter Tub Spout is backed by Moen's Limited Lifetime Warranty. This warranty covers defects in material and manufacturing for the original consumer purchaser.


For detailed warranty information, product support, or to contact customer service, please visit the official Moen website or refer to the warranty documentation included with your purchase.

**Moen Official Website:** [www.moen.com](http://www.moen.com)

## Related Documents

	<p><a href="#">Moen Faucet Finish Care and Cleaning Guide</a></p> <p>Comprehensive guide to cleaning and maintaining Moen faucet finishes, including LifeShine® and Non-LifeShine® types, with instructions for general cleaning, removing water spots, and warranty information.</p>
	<p><a href="#">Moen EVA™ Two-Handle Widespread Lavatory Faucet Trim Illustrated Parts</a></p> <p>Detailed illustrated parts list for the Moen EVA™ Two-Handle Widespread Lavatory Faucet Trim. Includes part numbers, finishes (Chrome, Brushed Nickel, Oil Rubbed Bronze), and descriptions for Handle Kits, Lift Rod Kits, Spout Kits, Aerators, and Pop-Up Plug &amp; Seat assemblies. Features ordering information and contact details for Moen.</p>
	<p><a href="#">MOEN VOSS™ Roman Tub Faucet Trim T694 Series Specifications &amp; Warranty</a></p> <p>Detailed specifications, operation, flow rates, standards, and warranty information for the MOEN VOSS™ Two Handle Roman Tub Faucet Trim with Diverter Valve, Model Series T694. Includes critical dimensions and WaterSense certification.</p>
	<p><a href="#">Moen Chateau Tub Filler Spout 1/2" CC Specifications</a></p> <p>Detailed specifications for the Moen Chateau Tub Filler Spout 1/2" CC, including description, standards, warranty, and critical dimensions. Models: 3829 series.</p>

Documents - Moen – 3814ORB




[pdf] Specifications Dimension Guide Declaration of Conformity Warranty

3814sp Moen® 3814ORB Thos Somerville Co Moen 3814BN Specification Sheet assets unilogcorp 2  
ITEM DOC |||

S p e c i f i c a t i o n s DESCRIPTION Metal construction with various finishes identified by suffix Designed to be installed on a 1/2 pipe IPS connection STANDARDS Third party certified to meet ASME A112.18.1/ CSA B125.1 and all applicable requirements referenced therein WARRANTY Lifetime limited...

lang:i-klngon score:20 filesize: 104.62 K page\_count: 1 document date: 2015-09-10




[\[pdf\]](#) Catalog

2017 MF36 BOOK v5 1227 GS safosstudio Moen® Full Line MOEN Catalog Pricing studiohausinc catalog  
|||  
Moen Full Line Residential and Commercial Price Catalog Effective February 1, 2017  
..... 3804 3804CBN 3805 3806 3806W 3807 3807BN 3807CP 3808 3808BN  
3808ORB 3808P 3808WR 3810PM 3814 3814BN **3814ORB** 3828 3829 LIST PRICE  
PAGE NO. UNIVERSAL PRODUCT CODE CASE QTY 35.20 51 026508072158 1...  
lang:en **score:13** filesize: 22.45 M page\_count: 516 document date: 2017-06-20



[\[pdf\]](#) Catalog

2017 MF36 BOOK v5 1227 GS null safosstudio Moen® Full Line Moen snowcrest net thriftysupply |||  
Moen Full Line Residential and Commercial Price Catalog Effective February 1, 2017  
..... 3804 3804CBN 3805 3806 3806W 3807 3807BN 3807CP 3808 3808BN  
3808ORB 3808P 3808WR 3810PM 3814 3814BN **3814ORB** 3828 3829 LIST PRICE  
PAGE NO. UNIVERSAL PRODUCT CODE CASE QTY 35.20 51 026508072158 1...  
lang:en **score:13** filesize: 25.48 M page\_count: 516 document date: 2016-12-29



[\[pdf\]](#)

Moen 2018 One Handle Pulldown Kitchen Faucet 7882SRS Please see moen consumer bath faucets  
This solution helps save valuable time for plumbers and DIY snowcrest net thriftysupply |||  
Contents Innovations 26 MotionSense™ 28 MotionSense Wave™ 30 Spot  
Resist™ Stainless Finish 30 P ... 6 6 6 12 12 12 12 12 12 12 12 12 MODEL  
NUMBER 3808 3808BN 3808ORB 3808P 3808WR 3809BN 3814 3814BN **3814ORB**  
3828 3829 3829BC 3829BN 3829ORB 3830 3830P 3839 3839BN 3853 3853BN  
3853BRB 3853ORB 3853SRN 3...  
lang:en **score:13** filesize: 18.16 M page\_count: 548 document date: 2018-02-07



[\[pdf\]](#) Price List

Moen Price List 2024 pages Zen Supply Faucets Weymouth® Arris® Flara™ Colinet™ 90°® Doux™  
Greenfield™ Wynford® Align® Rizon® Belfield Cia™ Voss™ Dartmoor® Glyde™ Brantford® Eva®  
srsLtd AfmBOoqKtKTEiOQw1vBNHiUYIhOdyZi129ZwqmfzDR6f19mKhf U30K zensupply content moen  
|||  
Transforming and creating a meaningful difference in your personal experience with  
water. At Moen, ... EP 3670EPBN 3670EPBL 3671EP 3671EPBN 3671EPBL 3737  
3737BN 3737BL 3737ORB 3800 3801 3806 3814 3814BN **3814ORB** 3828 3829  
3829BN 3829BL 3829ORB 3839 3839BN 3839BL 3853 3853BRB LIST PRICE  
229.85 212.60 26...  
lang:en **score:11** filesize: 26.82 M page\_count: 684 document date: 2024-01-16



[\[pdf\]](#) Accessories Catalog Price List

Moen 154795 Catalog Thos Somerville Co Service Kit For Use With 12 in Stem Sillcock Import assets  
03160eb054 cdn insitecloud net 7c16c5f7231976f |||  
Moen U.S. Wholesale Products Price List Residential and Commercial - Effective  
February 1, 2015 Cu ... 344112SL 344112SRS 344112V 344112W 344113 344114  
344114CSL 344114ORB 344114SL 344114SRS 3814 3814BN **3814ORB** 3919  
3919AZ 3919BN 3919CSL 3919ORB 3919P 3919SLP 3919W 3919WR 3924 3924P  
416 416711 416P 441...  
lang:de **score:10** filesize: 2.78 M page\_count: 68 document date: 2015-01-20

