



Manuals.plus /

› AIRCARE /

› AIRCARE 1043 Replacement Space Saver Wick User Manual

AIRCARE 1043

AIRCARE 1043 Replacement Space Saver Wick User Manual

Model: 1043

INTRODUCTION

This manual provides essential information for the proper use, installation, and maintenance of your AIRCARE 1043 Replacement Space Saver Wick. This evaporative humidifier wick is designed to ensure optimal moisture output and efficiency in compatible AIRCARE humidifiers. Please read these instructions carefully before installation and retain them for future reference.

PRODUCT OVERVIEW

The AIRCARE 1043 Super Wick is a high-quality evaporative wick designed for specific AIRCARE humidifier models. It features advanced paper construction for superior absorbency and a longer operational lifespan, contributing to efficient humidification.



Image 1: The AIRCARE 1043 Replacement Space Saver Wick, showing its pleated design for increased surface area.

Key Features:

- High-quality paper construction for enhanced absorbency.
- Designed for extended lifespan and efficient moisture output.
- AHAM certified output and energy consumption.
- Manufactured under Essick Air's quality control standards.

COMPATIBILITY

The AIRCARE 1043 Super Wick is compatible with various AIRCARE and Essick Air humidifier models. Refer to your humidifier's manual for specific wick requirements. Common compatible models include:

AIRCARETM EVAPORATIVE

1043 SUPER WICK^{®/MC}



For use with: | Pour utilisation avec: | Para usar con:

AIRCARE^{®/MC} & Essick Air^{®/MC}

821000	826000	831000
821001	826800	SS390DWHT
EP9 Series/Séries		

For a list of legacy models, visit: | Pour une liste des modèles existants, visitez: | Para obtener una lista de los modelos heredados, visite:
aircareproducts.com/1043.html • 1.800.547.3888

California residents; Résidents Californiens; Residentes de California

- ⚠ **WARNING:** Cancer and Reproductive Harm - www.P65Warnings.ca.gov
- ⚠ **AVERTISSEMENT:** Cancer et dommages à la reproduction - www.P65Warnings.ca.gov
- ⚠ **ADVERTENCIA:** Cáncer and daño reproductivo - www.P65Warnings.ca.gov

*In head-to-head tests conducted to AHAM test standard HU-1-2016. Tests accomplished in AIRCARE's model 831000.

*Dans les essais en tête-à-tête menés selon la norme d'essai AHAM HU-1-2016. Tests réalisés dans le modèle 831000 d'AIRCARE.

*En pruebas de cabeza a cabeza llevadas a cabo con el estándar de prueba AHAM HU-1-2016. Pruebas realizadas en el modelo de AIRCARE 831000.

1043 SUPER WICK^{®/MC}



CONTAINS 1 WICK



Image 2: Packaging of the AIRCARE 1043 Super Wick, listing compatible humidifier models such as 821000, 826000, 831000, 826800, and SS390DWHT. For a complete list of legacy models, visit aircareproducts.com/1043.html.

- AIRCARE & Essick Air models: 821000, 826000, 831000, 826800, SS390DWHT.
- For a comprehensive list of compatible legacy models, please visit the official AIRCARE website.

SETUP AND INSTALLATION (WICK REPLACEMENT)

Follow these steps to replace the wick in your compatible AIRCARE humidifier:

1. **Power Off and Unplug:** Ensure your humidifier is turned off and unplugged from the power outlet before beginning.
2. **Access Wick Compartment:** Remove the humidifier's top cover and water reservoir(s) to access the wick compartment. Refer to your specific humidifier's manual for detailed instructions on accessing this area.
3. **Remove Old Wick:** Carefully lift out the old, used wick. Dispose of it properly.
4. **Clean Humidifier Base:** While the wick is removed, it is recommended to clean the humidifier's base and water tray to prevent mineral buildup and mold growth. Use a mild cleaning solution and rinse thoroughly.
5. **Install New Wick:** Place the new AIRCARE 1043 Replacement Space Saver Wick into the wick frame or designated slot in the humidifier base. Ensure it is seated correctly and securely.
6. **Reassemble Humidifier:** Replace the water reservoir(s) and the top cover.
7. **Refill and Power On:** Fill the reservoir(s) with fresh water, plug in the humidifier, and turn it on. The new wick will begin to absorb water and humidify the air.

Note: It may take a few hours for the new wick to become fully saturated and for the humidifier to reach optimal performance.

OPERATION

The AIRCARE 1043 wick operates as part of an evaporative humidification system. Water is drawn up through the wick, and a fan blows dry air through the saturated wick, causing the water to evaporate into the air as invisible moisture. This process naturally humidifies the environment without producing white dust.

MAINTENANCE

Regular maintenance of your wick and humidifier is crucial for optimal performance and hygiene.

- **Wick Lifespan:** The lifespan of the wick varies depending on water quality and usage. It is generally recommended to replace the wick every 1 to 3 months, or when you notice a decrease in humidifier output or a hardened, discolored wick.
- **Flipping the Wick:** To extend the wick's life and ensure even saturation, consider flipping the wick upside down every 1-2 weeks.
- **Cleaning:** Wicks cannot be effectively cleaned for reuse. Attempting to clean a wick can damage its structure and reduce its effectiveness. Always replace with a new wick when necessary.
- **Humidifier Cleaning:** Regularly clean your humidifier's water tank and base to prevent mineral buildup and bacterial growth. Refer to your humidifier's specific cleaning instructions.

TROUBLESHOOTING

If your humidifier's performance decreases after wick replacement, consider the following:

- **Low Moisture Output:**

- Ensure the new wick is fully saturated. It may take a few hours.
- Check if the wick is installed correctly and seated firmly.
- Verify that the humidifier's fan is operating properly.
- Consider the room size and ambient humidity; very dry conditions may require more time to reach desired humidity levels.

- **Unpleasant Odor:**

- An odor may indicate bacterial growth. Replace the wick and thoroughly clean the humidifier base and water tank.
- Use fresh, clean water.

- **Wick Hardening/Discoloration:**

- This is normal mineral buildup. Replace the wick.
- Using distilled or demineralized water can reduce mineral buildup, but is not typically required for evaporative humidifiers.

SPECIFICATIONS

AIRCARE 1043 Replacement Space Saver Wick

Attribute	Detail
Model Name	AIRCARE 1043 Replacement Space Saver Wick
Model Number	1043
Brand	AIRCARE
Product Dimensions	Approximately 11"D x 4"W x 12"H (28cm D x 10cm W x 30.5cm H)
Item Weight	Approximately 16 ounces (1 pound)
Operation Mode	Evaporative
UPC	043129256699, 043129062597 (and others)




Image 3: Dimensional view of the AIRCARE 1043 wick, indicating approximate measurements of 12cm height, 4cm width, and 11cm depth.

SAFETY INFORMATION

WARNING: This product can expose you to chemicals including benzene which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65Warnings.ca.gov.

Always handle the wick with clean hands. Do not ingest any part of the wick. Keep out of reach of children and pets.

WARRANTY AND SUPPORT

For specific warranty information regarding your AIRCARE humidifier or replacement parts, please refer to the documentation included with your humidifier or visit the official AIRCARE website. For further assistance, contact AIRCARE customer support.

Online Support: www.aircareproducts.com

