

[Manuals.plus](#) /

› [Quicksilver](#) /

› Quicksilver OEM Part # 22-77863 Fitting Instruction Manual

Quicksilver 22-77863

Quicksilver OEM Part # 22-77863 Fitting Instruction Manual

Model: 22-77863

Brand: Quicksilver

1. PRODUCT OVERVIEW

The Quicksilver OEM Part # 22-77863 is a genuine Mercury Marine Elbow Fitting, designed as a factory original equipment part. It is not an aftermarket component. This fitting is crucial for various Mercury and MerCruiser engine models, facilitating fluid transfer within the engine system. It is essential to verify fitment for your specific engine model before installation.



Image: A genuine Quicksilver OEM Part # 22-77863 Elbow Fitting, showcasing its design and construction. This component is vital for maintaining the integrity of marine engine fluid systems.

2. TECHNICAL SPECIFICATIONS

Specification	Detail
Manufacturer	Mercury Marine
Brand	Quicksilver
Model	Mercury
Manufacturer Part Number	22-77863
Item Weight	4 pounds
Product Dimensions (L x W x H)	1 x 1 x 1 inches
ASIN	B017GH89FW
UPC	745061178977
Date First Available	November 16, 2012

3. INSTALLATION GUIDE

This elbow fitting is a critical component of your marine engine system. Proper installation is essential for safe and reliable operation. If you are not experienced with marine engine maintenance, it is highly recommended to seek assistance from a qualified marine technician.

General Installation Steps:

- Safety First:** Ensure the engine is turned off, cooled down, and the battery is disconnected before beginning any work.
- Identify Location:** Locate the existing fitting or the designated installation point for the new elbow fitting on your engine. Refer to your engine's specific service manual for precise diagrams and instructions.
- Remove Old Part (if applicable):** Carefully remove the old fitting, if present, using appropriate tools. Be prepared for potential fluid leaks and have a catch pan ready.
- Clean Surfaces:** Thoroughly clean the mating surfaces where the new fitting will be installed. Remove any old sealant, debris, or corrosion to ensure a proper seal.
- Apply Sealant (if required):** Apply a marine-grade thread sealant or gasket compound as specified by your engine's service manual or the fitting manufacturer.
- Install New Fitting:** Carefully thread the new Quicksilver Part # 22-77863 fitting into place. Hand-tighten first to ensure it is not cross-threaded.
- Torque to Specification:** Use a torque wrench to tighten the fitting to the manufacturer's specified torque settings. Overtightening can damage the fitting or engine components, while undertightening can lead to leaks.
- Reconnect and Test:** Reconnect any hoses or lines to the new fitting. Reconnect the battery. Start the engine and carefully inspect the newly installed fitting for any signs of leaks or improper function.

Important: Always verify your own fitment and consult your engine's specific service manual for detailed, model-specific installation procedures.

4. FUNCTION AND OPERATION

The Quicksilver OEM Part # 22-77863 Elbow Fitting serves as a critical connection point within the fluid systems of Mercury and MerCruiser engines. Its primary function is to redirect the flow of fluids (such as fuel, oil, or coolant) at an angle, allowing for efficient routing of lines and hoses in confined engine spaces. Once properly installed, the fitting operates passively, ensuring a sealed and unobstructed pathway for fluid transfer, which is essential for the engine's performance and cooling.

5. MAINTENANCE

As a static component, the elbow fitting requires minimal routine maintenance beyond regular inspection. However, its integrity is vital for preventing leaks and maintaining system pressure.

Maintenance Tips:

- **Regular Visual Inspection:** During routine engine checks, visually inspect the fitting and its connections for any signs of leaks, cracks, corrosion, or damage. Look for discoloration around the fitting, which may indicate a slow leak.
- **Check for Tightness:** Periodically, and especially after any engine work, gently check the tightness of the fitting. Do not overtighten.
- **Cleanliness:** Keep the area around the fitting clean and free of dirt, salt, and other contaminants that could accelerate corrosion or obscure signs of leakage.
- **Hose Condition:** Ensure that any hoses connected to the fitting are in good condition, free from cracks, hardening, or swelling, as a faulty hose can put undue stress on the fitting.

6. TROUBLESHOOTING COMMON ISSUES

While the elbow fitting itself is a robust component, issues can arise from improper installation or wear over time.

Common Problems and Solutions:

- **Leakage at the Fitting:**
 - **Cause:** Improper torque, damaged threads, worn sealant/gasket, or a crack in the fitting.
 - **Solution:** First, ensure the fitting is torqued to specification. If leakage persists, remove the fitting, inspect threads for damage, replace sealant/gasket, and re-install. If the fitting itself is cracked, it must be replaced.
- **Difficulty Installing:**
 - **Cause:** Cross-threading, incorrect part for the application, or debris in threads.
 - **Solution:** Ensure threads are clean and free of debris. Verify that you have the correct part number for your engine model. If cross-threaded, do not force it; remove and inspect threads on both the fitting and the engine component.
- **Restricted Fluid Flow:**
 - **Cause:** Internal blockage (unlikely for a new fitting), or a kinked/obstructed hose connected to the fitting.
 - **Solution:** Inspect connected hoses for kinks or blockages. If the fitting is suspected, remove and inspect for any internal obstructions.

If you are unable to resolve an issue, or if you suspect a more serious problem, consult a certified marine mechanic.

7. WARRANTY INFORMATION

Warranty coverage for the Quicksilver OEM Part # 22-77863 Fitting is provided by the manufacturer, Mercury Marine, or the authorized seller from whom the part was purchased. Specific warranty terms, conditions, and duration may vary. Please retain your proof of purchase and contact the seller or Mercury Marine directly for detailed warranty information and claims procedures.

8. CUSTOMER SUPPORT

For further assistance, technical inquiries, or support regarding the Quicksilver OEM Part # 22-77863 Fitting, please utilize the following resources:

- **Manufacturer's Website:** Visit the official Mercury Marine or Quicksilver website for product information, service manuals, and contact details.
- **Authorized Dealers:** Contact an authorized Quicksilver or Mercury Marine dealer for expert advice, genuine parts, and professional service.
- **Seller Support:** If you purchased the part online, refer to the seller's customer support channels for assistance with your order or product-related questions.

This manual is intended for informational purposes only. Always consult a qualified professional for complex installations or repairs.

© 2024 Quicksilver. All rights reserved.