

Skyjacker 8009

Skyjacker 8009 Steering Stabilizer Installation and Operation Manual

Model: 8009 | Brand: Skyjacker

INTRODUCTION

This manual provides essential instructions for the proper installation, operation, and maintenance of your Skyjacker 8009 Steering Stabilizer. Please read this manual thoroughly before beginning installation or use to ensure safe and correct application. This steering stabilizer is designed to enhance vehicle handling and reduce driver fatigue by dampening steering system harshness and shimmy, particularly with larger tires.

SAFETY INFORMATION

- Always wear appropriate personal protective equipment (PPE) during installation, including safety glasses and gloves.
- Ensure the vehicle is securely supported on jack stands or a lift before working underneath it. Never rely solely on a jack.
- Refer to your vehicle's service manual for specific torque specifications and procedures.
- Improper installation can lead to steering system failure, resulting in loss of vehicle control. If you are unsure about any step, consult a qualified mechanic.
- Keep hands and clothing clear of moving parts.

PACKAGE CONTENTS

Verify that all components are present before beginning installation.

- Skyjacker 8009 Steering Stabilizer (Black)
- Mounting Hardware Kit (bushings, washers, nuts, bolts/studs as applicable)



Image: Skyjacker 8009 Steering Stabilizer (black body with red and white logo, black boot) and associated mounting hardware including bushings, washers, and nuts/bolts.

SETUP AND INSTALLATION

This section outlines the general steps for installing the Skyjacker 8009 Steering Stabilizer. Specific vehicle applications may vary. Always refer to your vehicle's service manual for detailed instructions.

1. **Prepare Vehicle:** Park the vehicle on a level surface. Engage the parking brake. If lifting the vehicle, ensure it is securely supported by jack stands.
2. **Identify Mounting Location:** Locate the existing steering stabilizer (if applicable) or the designated mounting points on your vehicle's steering linkage and frame. The Skyjacker 8009 is an OEM replacement, designed to fit factory mounting locations.
3. **Remove Old Stabilizer (if applicable):** If replacing an existing stabilizer, carefully remove the mounting bolts and detach the old unit. Retain any reusable hardware if instructed by your vehicle's manual.
4. **Install Bushings:** Insert the provided bushings into the eyelets of the new Skyjacker 8009 Steering Stabilizer. Ensure they are seated correctly.
5. **Mount Stabilizer:** Position the new stabilizer and attach it to the vehicle's mounting points using the supplied hardware (washers, nuts, bolts/studs). Do not fully tighten hardware at this stage.
6. **Center Stabilizer:** With the stabilizer loosely mounted, cycle the steering from full left lock to full right lock. Ensure the stabilizer does not bind or extend/compress beyond its operational limits. Adjust its position as necessary to ensure it is centered within its travel range at the vehicle's straight-ahead steering position.
7. **Tighten Hardware:** Once centered, tighten all mounting hardware to the vehicle manufacturer's recommended torque specifications. Over-tightening can damage components; under-tightening can lead to failure.
8. **Final Check:** Re-check all connections for tightness. Cycle the steering again to confirm smooth operation and no interference.

OPERATING PRINCIPLES

The Skyjacker 8009 Steering Stabilizer functions as a hydraulic dampener, similar to a shock absorber. It is designed to:

- **Dampen Steering Harshness:** Reduces the impact of road irregularities and vibrations transmitted through the steering wheel, leading to a smoother driving experience.
- **Reduce Driver Fatigue:** By minimizing constant steering corrections and road feedback, it helps lessen driver effort.

over long distances.

- **Control Tire Shimmy:** Effectively dampens unwanted steering wheel oscillations or "shimmy" often associated with larger or aggressive tires, improving control and stability.

The stabilizer operates passively, reacting to steering inputs and road conditions to provide consistent dampening.

MAINTENANCE

The Skyjacker 8009 Steering Stabilizer is designed for durability and requires minimal maintenance. However, regular inspection is recommended:

- **Visual Inspection (Every 3,000-5,000 miles or during routine service):**
 - Check for any signs of fluid leaks around the stabilizer body or seals.
 - Inspect the rubber bushings for cracks, tears, or excessive wear.
 - Verify that all mounting hardware is securely tightened.
 - Look for any physical damage to the stabilizer body, such as dents or bends.
- **Functionality Check:** With the vehicle on the ground, turn the steering wheel from lock to lock. The stabilizer should offer consistent resistance throughout its travel. Any noticeable free play, binding, or lack of resistance may indicate a need for replacement.
- **Cleaning:** Keep the stabilizer free from excessive dirt and debris. A simple wash with soap and water is sufficient. Avoid harsh chemicals that could damage seals or finishes.

TROUBLESHOOTING

Symptom	Possible Cause	Solution
Steering still feels loose or exhibits shimmy after installation.	• Loose mounting hardware. • Worn vehicle steering components (e.g., tie rod ends, ball joints, track bar). • Improper tire balance or alignment. • Stabilizer not centered correctly.	• Re-check and tighten all mounting hardware to specifications. • Inspect other steering and suspension components for wear and replace as needed. • Have tires balanced and vehicle alignment checked by a professional. • Re-center the stabilizer as per installation instructions.
Stabilizer makes noise (e.g., clunking, squeaking).	• Loose mounting hardware. • Worn or damaged bushings. • Interference with other vehicle components.	• Check and tighten all mounting hardware. • Inspect and replace bushings if worn. • Verify proper clearance around the stabilizer throughout the steering range.
Fluid leakage from stabilizer.	Damaged seal or internal component failure.	Stabilizer requires replacement.

SPECIFICATIONS

- **Model:** 8009
- **Brand:** Skyjacker
- **Type:** HD OEM Replacement Steering Stabilizer
- **Color:** Black
- **Exterior Finish:** Machined
- **Item Weight:** Approximately 3.52 pounds (1.6 kg)
- **Product Dimensions:** Approximately 9.99 x 9.99 x 9.99 inches (25.37 x 25.37 x 25.37 cm) *Note: These dimensions may refer to packaging or overall product, actual stabilizer length will vary based on application.*
- **Part Numbers:** Manufacturer Part Number: 8009, OEM Part Number: 8009

WARRANTY AND SUPPORT

For specific warranty information regarding your Skyjacker 8009 Steering Stabilizer, please refer to the official Skyjacker website or contact Skyjacker customer support directly. Warranty terms and conditions may vary.



For technical assistance or further inquiries, please visit the official Skyjacker website or contact their customer service department.


Note: This manual provides general guidance. Always consult a qualified professional for installation if you are not confident in your mechanical abilities.



© 2023 Skyjacker. All rights reserved. Information subject to change without notice.

Related Documents - 8009

	Skyjacker Suspensions 2014-2015 Master Catalog: Lift Kits & Performance Parts Explore the comprehensive Skyjacker Suspensions 2014-2015 Master Catalog. Discover a wide range of lift kits, leveling kits, shocks, and suspension components for Chevrolet, GMC, Ford, Jeep, Toyota, Dodge, and more. Enhance your vehicle's performance and off-road capability with Skyjacker's quality aftermarket parts.
	Skyjacker 2004-2008 Ford F-150 4WD 6" Suspension Lift Installation Instructions Detailed installation instructions for the Skyjacker 6" Suspension Lift Kit for 2004-2008 Ford F-150 4WD vehicles. Includes required tools, parts list, front and rear installation steps, and final notes with torque specifications.

 GENERAL MOTORS 1988 and 1990 Full-Size 4WD INSTALLATION INSTRUCTIONS SKYJACKER These instructions are for the installation of the SKYJACKER lift kit on 1988 and 1990 Full-Size 4WD vehicles. The vehicle must be on a level surface and the suspension must be in good condition before installation. PRE-INSTALLATION NOTES: - Check the vehicle's weight and distribution. The vehicle must be within the weight and distribution limits specified in the SKYJACKER lift kit instructions. - Check the vehicle's suspension components. The vehicle must have good condition suspension components before installation. - Check the vehicle's frame. The vehicle must have a good condition frame before installation. - Check the vehicle's tires. The vehicle must have good condition tires before installation. INSTALLATION NOTES: - Follow the SKYJACKER lift kit instructions for front and rear suspension modifications. - Use the correct tools and techniques for installation. - Check the vehicle's alignment after installation. - Check the vehicle's ride quality after installation. © 1992 Skyjacker, Inc.	SKYJACKER Lift Kit Installation Instructions for 1988-1992 GM Full-Size 4WD Trucks Comprehensive installation guide for SKYJACKER lift kits (C4626K, C4636K series) designed for 1988 and newer General Motors Full-Size 4WD vehicles. Covers front and rear suspension disassembly, installation, and final checks.
 SKYJACKER 1980-1996 Ford F-150 Bronco 4WD INSTALLATION INSTRUCTIONS SKYJACKER These instructions are for the installation of the SKYJACKER lift kit on 1980-1996 Ford F-150 Bronco 4WD vehicles. The vehicle must be on a level surface and the suspension must be in good condition before installation. PRE-INSTALLATION NOTES: - Check the vehicle's weight and distribution. The vehicle must be within the weight and distribution limits specified in the SKYJACKER lift kit instructions. - Check the vehicle's suspension components. The vehicle must have good condition suspension components before installation. - Check the vehicle's frame. The vehicle must have a good condition frame before installation. - Check the vehicle's tires. The vehicle must have good condition tires before installation. INSTALLATION NOTES: - Follow the SKYJACKER lift kit instructions for front and rear suspension modifications. - Use the correct tools and techniques for installation. - Check the vehicle's alignment after installation. - Check the vehicle's ride quality after installation. © 1992 Skyjacker, Inc.	Skyjacker 8" Suspension Lift Installation Instructions for 1980-1996 Ford F-150 Bronco 4WD Detailed installation instructions for the Skyjacker 8-inch suspension lift kit designed for 1980-1996 Ford F-150 and Bronco 4WD vehicles. Includes step-by-step guidance for front and rear suspension modifications, important notes, and safety precautions.
 SKYJACKER 2021-2022 Ford Bronco 4WD INSTALLATION INSTRUCTIONS SKYJACKER These instructions are for the installation of the SKYJACKER lift kit on 2021-2022 Ford Bronco 4WD vehicles. The vehicle must be on a level surface and the suspension must be in good condition before installation. PRE-INSTALLATION NOTES: - Check the vehicle's weight and distribution. The vehicle must be within the weight and distribution limits specified in the SKYJACKER lift kit instructions. - Check the vehicle's suspension components. The vehicle must have good condition suspension components before installation. - Check the vehicle's frame. The vehicle must have a good condition frame before installation. - Check the vehicle's tires. The vehicle must have good condition tires before installation. INSTALLATION NOTES: - Follow the SKYJACKER lift kit instructions for front and rear suspension modifications. - Use the correct tools and techniques for installation. - Check the vehicle's alignment after installation. - Check the vehicle's ride quality after installation. © 1992 Skyjacker, Inc.	Skyjacker 3" Suspension Lift Installation Instructions for 2021-2022 Ford Bronco 4WD Detailed installation guide for the Skyjacker 3-inch suspension lift kit for 2021-2022 Ford Bronco 4WD models equipped with Bilstein struts. Includes component breakdown, required tools, and step-by-step instructions for front and rear suspension modifications.
 SKYJACKER 1999-2004 Ford F250/F350 Super Duty & Excursion INSTALLATION INSTRUCTIONS SKYJACKER These instructions are for the installation of the SKYJACKER lift kit on 1999-2004 Ford F250/F350 Super Duty & Excursion vehicles. The vehicle must be on a level surface and the suspension must be in good condition before installation. PRE-INSTALLATION NOTES: - Check the vehicle's weight and distribution. The vehicle must be within the weight and distribution limits specified in the SKYJACKER lift kit instructions. - Check the vehicle's suspension components. The vehicle must have good condition suspension components before installation. - Check the vehicle's frame. The vehicle must have a good condition frame before installation. - Check the vehicle's tires. The vehicle must have good condition tires before installation. INSTALLATION NOTES: - Follow the SKYJACKER lift kit instructions for front and rear suspension modifications. - Use the correct tools and techniques for installation. - Check the vehicle's alignment after installation. - Check the vehicle's ride quality after installation. © 1992 Skyjacker, Inc.	Skyjacker 4"-8" Suspension Lift Installation Guide for 1999-2004 Ford F250/F350 Super Duty & Excursion Detailed installation instructions for the Skyjacker 4-inch to 8-inch suspension lift kit designed for 1999-2004 Ford F250, F350 Super Duty, and Excursion vehicles. Includes front and rear installation steps, torque specifications, and accessory information.

Documents - Skyjacker – 8009

[\[pdf\]](#) Catalog

Skyjacker Performance Suspension Systems Catalog performance suspension struts shocks coil springs leaf lift kits lowering sway bars bushings air CARiD 1972 82 International Lift 1 S24 32 2 Front Leaf Springs S20FS Rear S20RS catalog images carid skyjacker info

2 and 4 Scout II, Terra and Traveler Lifts Skyjacker produces 2 and 4 lifts for the Scout Lover. Sky ... k Bar JKRTBA717 Rear Adjustable Track Bar NOTE: ALL SHOCKS MUST BE ORDERED SEPARATELY 7009 7219 **8009** 8219 9009 9219 H7016 H7018 N8016 N8018 B8516 B8518 M9516 M9518 4 7009 7009 7009 7009 7219 8...

lang:en score:19 filesize: 13.32 M page_count: 118 document date: 2017-02-08



[\[pdf\]](#) Catalog

Skyjacker Performance Suspension Parts Catalog performance suspension shocks struts coilovers lift kits lowering handling leveling alignment conversion air coil springs leaf helper torsion bars sway bushings braces traction panhard torque arms 4 link frames ball joints steering dampers bump stops skid plates car truck suv CARiD skyjacker catalog images carid info |||

Black MAX twin tube shock absorbers have increased fluid capacity and utilize foam-cell technology ... g Stabilizer Kit, WHITE w/Red Boot 1 7209 Dual Steering Stabilizer Kit, Black MAX w/Black Boot 1 **8009** Dual Steering Stabilizer Kit, SILVER w/Black Boot 1 9219 Long Arm Upgrade 3.5-6 Lift Jeep W...

lang:en score:18 filesize: 23.12 M page_count: 119 document date: 2018-01-31

[illegible]

[Kubota RTV Utility Vehicles and Other Heavy Equipment Auction Catalog](#)

Comprehensive catalog of Kubota RTV utility vehicles, compact track loaders, telehandlers, forklifts, and other heavy equipment available at the Ritchie Bros. auction in Orlando, FL.

lang:de score:13 filesize: 1.25 M page_count: 363 document date: 2024-08-14

[illegible]

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export Feb 26 2024 — Manual Stabilizers IMT 3016 6000 lb 3 Section Star 4700SB

6x4 Vacuum Excavator Truck S N pressure pump Usage 483 423 Mi 141 2020 Peterbilt 389 248 pages
Catalog Ontario Regional ON CAN 2024290 assets ctfassets net ueyxw0p8lpyv C7D54C13 54A5 F9CE
7900 47A25E8B0750 0b5e86ba8a9ff9b0567602697240e4f4 |||

Page 1 of 248 Ontario Regional Event, ON, CAN - Mar 6, 2024 Lot # 1 2 3 4 5 Details
2014 Ford F-5 ... o-date information. Page 195 of 248 Lot # 7998 7999 8000 8001
8002 8003 8004 8005 8006 8007 8008 **8009** Details 9 ft One-Way 9 ft Mini Storage
Container S/N: Not Available C/W: 7 ft 4 in Wide, 8 ft ...

lang:de score:13 filesize: 956.12 K page count: 248 document date: 2024-02-26

[illegible]

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export 39 minutes ago — Manual Stabilizers Hydraulic Lift Gate Venturo ET10KX 3200

lb 3 Section IMT 2015 2500 2 Crane Wired Catalog Ontario Regional CAN 2024294 assets ctfassets net

Page 1 of 346 Ontario Regional Event, CAN - Oct 23, 2024 Lot # 1B 1A 1 2A Details
2011 Ford F-550 ... Not Available Notes: LOCATED-IN-BOLTON-ON Asset located
in: Bolton, ON Page 299 of 346 Lot # 8008 **8009** 8010 8011 8012 8013 8014 8015
8016 Details 2024 Kit Containers QT-SP-8-23 88 in Skid Steer Sno...

lang:de score:12 filesize: 1.22 M page count: 346 document date: 2024-10-19

[illegible]

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export 11 hours ago — Manual Stabilizers 2012 Cobra 4400 kg 2 Section Electric
Crane 1600 lb Wired Remote Control Usage 179 510 Km Catalog Ontario Regional CAN 2024295 assets
ctfassets.net ueyxw0p8lpyv 169BD9DE 436B 17A3 AA3A 910B25E8CB41

Page 1 of 272 Ontario Regional Event, CAN - Dec 4, 2024 Lot # 1 2 4 Details 2021 International CV ... sage: Not Available Asset located in: Bolton, ON Clarke Encore Ride-On Electric Floor Sweeper S/N: **180095** C/W: 40 in Working Width, Water System, Rear Squeegee Usage: Not Available Asset located in: B...

lang:en score:12 filesize: 1002.42 K page_count: 272 document date: 2024-12-01

[illegible]

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export 11 hours ago — Manual Coupler 74 in Bucket Usage 3 528 Hr Asset located Newnan GA 4 80 235 Catalog Southeast Regional USA 2024149 assets ctfassets net ueyxw0p8lpyv 8F848351 FE2B 95E8 1362 D89834441417 f4ae0107126de394951f6b6ee6407819 |||

Page 1 of 286 Southeast Regional Event, USA - Dec 5, 2024 Lot # 1 2 3 4 5 6 7

Details 2018 Bobcat ... r website for the most accurate and up-to-date information.

Page 230 of 286 Lot # 8006 8007 8008 **8009** 8010 8011 Details 2019 Kubota RTV-

X1100C Utility Vehicle S/N: A5KC2GDBHKG047801 C/W: Enclosed ...

lang:nl score:12 filesize: 1016.72 K page_count: 286 document date: 2024-12-01

[illegible]

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export 2 days ago — Manual Stabilizers Cobra 4400 lb 3 Section Hydraulic Crane
Wired Transmission 10000 Front Axle 19000 Rears 91 1 Ratio Catalog Ontario Regional CAN 2024294
assets ctfassets net ueyxw0p8lpyv 4CE0FB8F 9A25 699B CFD0 0D50B79F66DF

d862670e5fd4927344f48f41d1b0c99f |||

Page 1 of 372 Ontario Regional Event, CAN - Oct 23, 2024 Lot # 1D 1C 1B Details
2012 Ford F-550 X ... N-BOLTON-ON Asset located in: Bolton, ON Page 320 of 372
Lot # 8002 8003 8004 8005 8006 8007 8008 **8009** 8010 Details 2024 Kit Containers
QT-SP-12-23 0 ft 136 in Skid Steer Snow Pusher Unused S/N: ...

lang:en score:12 filesize: 1.31 M page_count: 372 document date: 2024-10-24

lang:en score:12 filesize: 889.09 K page_count: 240 document date: 2024-11-28

This catalog was created at November 26, 2024 11:25:16 AM GMT.
Please check our website for the most accurate and up-to-date information

This catalog was created at November 30, 2024 05:25:17 PM GMT.
Please check our website for the most accurate and up-to-date information

lang:en score:12 filesize: 981.86 K page_count: 265 document date: 2024-11-30

This catalog was created at November 30, 2024 12:25:05 AM GMT.
Please check our website for the most accurate and up-to-date information.

Page 1 of 413	
 RITCHIE BROS. Antennas Southeast Regional Event, USA - Mar 13, 2025	
Lot #	Details
2021 ARCO 2750 Gal Trailer	S/N: 142224100305 Usage: Not Available Lot closing time: Fri, Mar 14, 07:00 PM EDT Asset located in: Newnan, GA
1	2019 Case 9750 High Flow Wheel Loader S/N: J447302JAN00000 C/W: Enclosed Cab, Rear mounting, Air Conditioning, Air Ride Seat, Joystick Steering, Hydraulic Coupler, 66 in Bucket Usage: 5243 Hr Notes: PLEASE NOTE: ISSUE IN DEFICIENCIES SECTION Asset located in: Newnan, GA
2	2019 Kubota SRV75 Two-Speed Wheel Loader S/N: K6C0575JANUC4582 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 72 in Bucket Usage: 2203 Hr Notes: SPECIAL MOBILE EQUIPMENT - NO TITLE AVAILABLE - SOLD WITH BILL OF SALE ONLY Asset located in: Newnan, GA
3	2017 Bobcat 953D Wheel Loader S/N: ALJ02023 C/W: Open Operator Station, 2017 US EPA Label, Manual Coupler, 64 in Bucket Usage: 242 Hr Asset located in: Newnan, GA
4	2019 Case 9750 Wheel Loader S/N: J447302JAN00000 C/W: Open Operator Station, Manual Coupler Usage: 5243 Hr Asset located in: Lebanon, TN
5	2019 Bobcat 9750 Wheel Loader S/N: ALJ02023 C/W: Enclosed Cab, Joystick Steering, Air Conditioning, Air Ride Seat, Joystick Steering, Hydraulic Coupler, 66 in Bucket Usage: 5243 Hr Notes: PLEASE NOTE: ISSUE IN DEFICIENCIES SECTION Asset located in: Lebanon, TN
The catalog was created at March 11, 2025 10:25:32 PM GMT. Please check our website for the most accurate and up-to-date information.	

[pdf] User Manual Catalog Label

RB Auction Event Export Mar 11 2025 — Manual Coupler 72 in Bucket Usage 2 909 Hr Notes SPECIAL

MOBILE EQUIPMENT Pilot Controls Control Pattern Changer Auxiliary Hydraulics Catalog Southeast

Regional USA 2025136 assets ctfassets net ueyxw0p8lpyv 85E91C6B 66BF 721F AEF9 3A6347D13A80

5b451e356c03aec9ac5375ace2042fc8 |||

Page 1 of 413 Southeast Regional Event, USA - Mar 13, 2025 Lot # 1 2 3 4 4A 5

Details 2021 ARCO 2 ... osing time: Fri, Mar 14, 02:32 PM EDT Asset located in:

Lebanon, TN Lot # 8004 8005 8006 8007 8008 **8009** 8010 Details 2018 Club Car

Precedent Electric Golf Cart S/N: JE1823879230 C/W: 36 Volt Battery...

lang:nl score:10 filesize: 1.4 M page_count: 413 document date: 2025-03-11

Page 1 of 390	
 RITCHIE BROS. Antennas Southeast Regional Event, USA - Mar 13, 2025	
Lot #	Details
2021 ARCO 2750 Gal Trailer	S/N: 142224100305 Usage: Not Available Lot closing time: Fri, Mar 14, 07:00 PM EDT Asset located in: Newnan, GA
1	2019 Case 9750 High Flow Wheel Loader S/N: J447302JAN00000 C/W: Enclosed Cab, Rear mounting, Air Conditioning, Air Ride Seat, Joystick Steering, Hydraulic Coupler, 66 in Bucket Usage: 5243 Hr Notes: PLEASE NOTE: ISSUE IN DEFICIENCIES SECTION Asset located in: Newnan, GA
2	2019 Kubota SRV75 Two-Speed Wheel Loader S/N: K6C0575JANUC4582 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 72 in Bucket Usage: 2203 Hr Notes: SPECIAL MOBILE EQUIPMENT - NO TITLE AVAILABLE - SOLD WITH BILL OF SALE ONLY Asset located in: Newnan, GA
3	2017 Bobcat 953D Wheel Loader S/N: ALJ02023 C/W: Open Operator Station, 2017 US EPA Label, Manual Coupler, 64 in Bucket Usage: 242 Hr Asset located in: Newnan, GA
4	2019 Case 9750 Wheel Loader S/N: J447302JAN00000 C/W: Open Operator Station, Joystick Steering, Manual Coupler Usage: 5243 Hr Asset located in: Lebanon, TN
5	2019 Bobcat 9750 Wheel Loader S/N: ALJ02023 C/W: Enclosed Cab, Joystick Steering, Air Conditioning, Air Ride Seat, Joystick Steering, Hydraulic Coupler, 66 in Bucket Usage: 5243 Hr Notes: PLEASE NOTE: ISSUE IN DEFICIENCIES SECTION Asset located in: Lebanon, TN
CHOICE OF 2 - Lot #s 4, 7	
6	2019 Galb R150 Wheel Loader S/N: 0140100000190300 Usage: Not Available Asset located in: Lebanon, TN
The catalog was created at March 7, 2025 07:25:31 AM GMT. Please check our website for the most accurate and up-to-date information.	

[pdf] User Manual Catalog Label

RB Auction Event Export 10 hours ago — Manual Coupler 72 in Bucket Usage 2 909 Hr Notes SPECIAL

MOBILE EQUIPMENT NO TITLE AVAILABLE SOLD WITH BILL OF SALE ONLY Asset located Newnan

Catalog Southeast Regional USA 2025136 assets ctfassets net ueyxw0p8lpyv 85E91C6B 66BF 721F

AEF9 3A6347D13A80 79f0462c6106ae0191bdec653cc41396 |||

Page 1 of 390 Southeast Regional Event, USA - Mar 13, 2025 Lot # 1 2 3 4 5 Details

2021 ARCO 2750 ... ble Lot closing time: Fri, Mar 14, 02:33 PM EDT Asset located in:

Lebanon, TN Lot # 8006 8007 8008 **8009** 8010 8011 8012 8013 8014 Details 2009 40

ft High Cube Refrigerated Storage Container S/N: TRIU...

lang:nl score:10 filesize: 1.33 M page_count: 390 document date: 2025-03-07

Page 1 of 405	
 RITCHIE BROS. Antennas Southeast Regional Event, USA - Mar 13, 2025	
Lot #	Details
2021 ARCO 2750 Gal Trailer	S/N: 142224100305 Usage: Not Available Lot closing time: Fri, Mar 14, 07:00 PM EDT Asset located in: Newnan, GA
1	2019 Case 9750 High Flow Wheel Loader S/N: J447302JAN00000 C/W: Enclosed Cab, Rear mounting, Air Conditioning, Air Ride Seat, Joystick Steering, Hydraulic Coupler, 66 in Bucket Usage: 5243 Hr Notes: PLEASE NOTE: ISSUE IN DEFICIENCIES SECTION Asset located in: Newnan, GA
2	2019 Kubota SRV75 Two-Speed Wheel Loader S/N: K6C0575JANUC4582 C/W: Open Operator Station, Joystick Steering, Manual Coupler, 72 in Bucket Usage: 2203 Hr Notes: SPECIAL MOBILE EQUIPMENT - NO TITLE AVAILABLE - SOLD WITH BILL OF SALE ONLY Asset located in: Newnan, GA
3	2017 Bobcat 953D Wheel Loader S/N: ALJ02023 C/W: Open Operator Station, 2017 US EPA Label, Manual Coupler, 64 in Bucket Usage: 242 Hr Asset located in: Newnan, GA
4	2019 Case 9750 Wheel Loader S/N: J447302JAN00000 C/W: Open Operator Station, Joystick Steering, Manual Coupler Usage: 5243 Hr Asset located in: Lebanon, TN
5	2019 Bobcat 9750 Wheel Loader S/N: ALJ02023 C/W: Enclosed Cab, Joystick Steering, Air Conditioning, Air Ride Seat, Joystick Steering, Hydraulic Coupler, 66 in Bucket Usage: 5243 Hr Notes: PLEASE NOTE: ISSUE IN DEFICIENCIES SECTION Asset located in: Lebanon, TN
CHOICE OF 2 - Lot #s 4, 7	
6	2019 Galb R150 Wheel Loader S/N: 0140100000190300 Usage: Not Available Asset located in: Lebanon, TN
The catalog was created at March 10, 2025 09:26:36 PM GMT. Please check our website for the most accurate and up-to-date information.	

[pdf] User Manual Catalog Label

RB Auction Event Export 2025 03 10 — Manual Coupler 72 in Bucket Usage 2 909 Hr Notes SPECIAL

MOBILE EQUIPMENT Briggs Stratton CR950 1 Cylinder 208 cc Gasoline Engine Catalog Southeast

Regional USA 2025136 assets ctfassets net ueyxw0p8lpyv 85E91C6B 66BF 721F AEF9 3A6347D13A80

757a146f311e06e3baf4ee7cb8fd54dd |||

Page 1 of 405 Southeast Regional Event, USA - Mar 13, 2025 Lot # 1 2 3 4 4A 5

Details 2021 ARCO 2 ... nit Usage: Not Available Lot closing time: Fri, Mar 14, 02:33

PM EDT Asset located in: Lebanon, TN **8009** 2009 40 ft High Cube Refrigerated

Storage Container S/N: TRIU8611246 C/W: Carrier Reefer Unit ...

lang:nl score:10 filesize: 1.38 M page_count: 405 document date: 2025-03-10

Page 1 of 404 Southeast Regional Event, USA - Mar 13, 2025 Lot # 1 2 3 4 4A 5
Details 2021 ARCO 2 ... osing time: Fri, Mar 14, 02:32 PM EDT Asset located in:
Lebanon, TN Lot # 8004 8005 8006 8007 8008 **8009** 8010 Details 2018 Club Car
Precedent Electric Golf Cart S/N: JE1823879230 C/W: 36 Volt Battery...
lang:nl **score:10** filesize: 1.37 M page_count: 404 document date: 2025-03-11

RB Auction Event Export Mar 21 2025 3 hours ago — Manual Transmission Diesel Engine Electric Start
Broom 540 PTO Point Hitch 6 5 16LT Front Tires 13 6x28 Rear Usage 123 Hr Asset located Catalog
Pacific Northwest Regional USA 2025162 assets ctfassets net ueyxw0p8lpyv B7B781AC B475 6400 4688
282A37F4BE88 b678998b2918afcc93225d63064f31dc |||

Page 1 of 302 Pacific Northwest Regional Event, USA - Mar 21, 2025 Lot # Details
2015 Ford F-450 ... International 4300 SBA 4x2 Van Truck S/N:
1HTMMML3HH677092 C/W: Cummins 6 Cylinder Diesel Engine, **8009** Engine hrs,
Automatic Transmission, 10000 lb Front Axle, 17500 lb Rears, 26000 lb GVWR, 295
/75...

lang:en score:10 filesize: 1.02 M page_count: 302 document date: 2025-03-13

RB Auction Event Export 15 hours ago — Manual Coupler 72 in Bucket Usage 2 909 Hr Notes SPECIAL
MOBILE EQUIPMENT NO TITLE AVAILABLE SOLD WITH BILL OF SALE ONLY Asset located Newnan
Catalog Southeast Regional USA 2025136 assets ctfassets net ueyxw0p8lpyv 85E91C6B 66BF 721F
AEF9 3A6347D13A80 ba11738090a71acaf38b77a02db4f11b |||
Page 1 of 413 Southeast Regional Event, USA - Mar 13, 2025 Lot # 1 2 3 4 4A 5
Details 2015 Case S ... for the most accurate and up-to-date information. Page 347 of
413 Lot # 8004 8005 8006 8007 8008 **8009** 8010 Details 2018 Club Car Precedent
Electric Golf Cart S/N: JE1823879230 C/W: 36 Volt Battery...
lang:de score:10 filesize: 1.4 M page_count: 413 document date: 2025-03-12

This catalog was created at March 14, 2025 04:27:34 PM OMT.
Please check our website for the most accurate and up-to-date information

This catalog was created at March 19, 2025 03:27:41 PM GMT.
Please check our website for the most accurate and up-to-date information.

This catalog was created at March 13, 2025 11:25:06 PM GMT.
Please check our website for the most accurate and up-to-date information.

lang:en score:10 filesize: 1.04 M page count: 307 document date: 2025-03-13

[illegible][illegible][illegible]

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export 10 mars 2025 — Manual Coupler 72 in Bucket Usage 2 909 Hr Notes SPECIAL
MOBILE EQUIPMENT GMC Sierra 2500HD 4x2 Crew Cab Utility Truck S N 1GD11REG8GF228858 C
Catalog Southeast Regional USA 2025136 assets ctfassets net ueyxw0p8lpyv 85E91C6B 66BF 721F
AEF9 3A6347D13A80 a78c5adc3331724b73cd46a97d5be629 |||

Page 1 of 408 Southeast Regional Event, USA - Mar 13, 2025 Lot # 1 2 3 4 4A 5
Details 2021 ARCO 2 ... nit Usage: Not Available Lot closing time: Fri, Mar 14, 02:33
PM EDT Asset located in: Lebanon, TN **8009** 2009 40 ft High Cube Refrigerated
Storage Container S/N: TRIU8611246 C/W: Carrier Reefer Unit ...

lang:nl score:10 filesize: 1.39 M page_count: 408 document date: 2025-03-10

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export Houston TX USA 1 day ago — Manual Coupler 60 in Bucket Usage Not
Available Asset located Humble TOY HAULER 21 852 Mi Page 124 Catalog 2025208 assets ctfassets net
ueyxw0p8lpyv 680C983A A5D3 5AC5 2C37 BA14BAADFAAD 519f9613191885815e208416202a7431 |||
Page 1 of 469 Houston, TX, USA - Feb 11, 2025 Lot # 1 2 3 4 5 6 Details 2023 John
Deere 330G Skid ... Livingston, LA Lot # 565 Details 2018 Mack CXU613 6x4 T/A
Day Cab Truck Tractor S/N: 1M1AW02Y5JM08**8009** C/W: Mack MP7 6 Cylinder 10.8
L Diesel 395 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust...

lang:af score:10 filesize: 1.62 M page_count: 469 document date: 2025-02-07

[\[pdf\]](#) User Manual Catalog Label

RB Auction Event Export Houston TX USA 12 hours ago — Manual Coupler 60 in Bucket Usage Not Available Asset located Humble TOY HAULER 21 852 Mi 1177 2001 Catalog 2025208 assets ctfassets net ueyxw0p8lpyv 680C983A A5D3 5AC5 2C37 BA14BAADFAAD 2b7042bbf41a7afa727dffe4fda857c8

|||

Page 1 of 468 Houston, TX, USA - Feb 11, 2025 Lot # 1 2 3 4 5 6 Details 2023 John Deere 330G Skid ... set located in: Livingston, LA 565 2018 Mack CXU613 6x4 T/A Day Cab Truck Tractor S/N: 1M1AW02Y5JM08**8009** C/W: Mack MP7 6 Cylinder 10.8 L Diesel 395 hp Engine, 2017 US EPA Label, Requires Diesel Exhaust...

lang:af score:10 filesize: 1.61 M page_count: 468 document date: 2025-02-07

Lot #		Details	Lot #	Details
1	1998 Case 570L-XT 4x4 Landscape Loader	S/N: J4003262 C/W: 1000 Operator Station, 80 in Bucket, 85 in Rear Blade Usage: 2719 Hr Name: LOCATED-IN FORT WORTH, TX Asset located in: Lake Worth, TX	2018 Case 880N Backhoe Loader	S/N: J4003091, J7003094 Asset located in: Humble, TX
2	2011 Case 420PDT 4x4 Backhoe Loader	S/N: CAT420PDT00000000 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 890N 4x4 Loader Backhoe Backhoe Loader	S/N: J4003091, J7003094 Asset located in: Humble, TX
3	2011 Case 420PDT 4x4 Backhoe Loader	S/N: CAT420PDT00000000 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 890N 4x4 Backhoe Loader	S/N: J4003091, J7003094 Asset located in: Humble, TX
4	2011 Case 420PDT 4x4 Backhoe Loader	S/N: CAT420PDT00000000 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 890N 4x4 Backhoe Loader	S/N: J4003091, J7003094 Asset located in: Humble, TX
5	2014 Case 410P Backhoe Loader	S/N: CAT410P00000000 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 890N 4x4 Backhoe Loader	S/N: J4003091, J7003094 Asset located in: Humble, TX
6	2019 Case 900N 4x4 Backhoe Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 890N 4x4 Backhoe Loader	S/N: J4003091, J7003094 Asset located in: Humble, TX
7	2019 Case 900N 4x4 Backhoe Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 890N 4x4 Backhoe Loader	S/N: J4003091, J7003094 Asset located in: Humble, TX

This catalog was created on October 31, 2024 03:03:03 PM (GMT)
Please check our website for the most accurate and up-to-date information.

[pdf] User Manual Catalog

RB Auction Event Export of 424 20 hours ago — Manual Coupler 81 in Loader Bucket Quick 24 Backhoe Digging Rear Auxiliary Hydraulics Usage 1 127 Hr Asset located Humble TX 11 Catalog Houston USA 2024248 assets ctfassets net ueyxw0p8lpyv C6C92DB1 FBFF 1246 8AD9 6BEB85A9AC63 5e070fe241185ed1ecb174d42ed41fae ||| Page 1 of 424 Houston, TX, USA - Nov 5, 2024 Lot # 1 2 3 4 5 6 7 Details 1998 Case 570L-XT 4x4 La ... he most accurate and up-to-date information. Page 280 of 424 Lot # 8003 8004 8005 8006 8007 8008 **8009** Details 2013 Skyjack SJ66T 4WD Diesel Telescopic Boom Lift S/N: 970000552 C/W: 60 ft Max Platfo... lang:nl **score:10** filesize: 1.5 M page_count: 424 document date: 2024-10-31

Lot #		Details	Lot #	Details
1	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
2	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
3	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
4	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
5	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX

This catalog was created on March 12, 2025 10:26:01 AM (GMT)
Please check our website for the most accurate and up-to-date information.

[pdf] User Manual Catalog Label

RB Auction Event Export Mar 12 2025 — Operator Station 2017 US EPA Label Manual Coupler 84 in Bucket Usage 243 Hr Asset located Newnan GA 4 2013 Case SV250 Skid Steer Loader S N Catalog Southeast Regional USA 2025136 assets ctfassets net ueyxw0p8lpyv 85E91C6B 66BF 721F AEF9 3A6347D13A80 95af554bda4353f3de309b203b0d2c1a ||| Page 1 of 414 Southeast Regional Event, USA - Mar 13, 2025 Lot # 1 2 3 4 4A 5 Details 2015 Case S ... for the most accurate and up-to-date information. Page 348 of 414 Lot # 8004 8005 8006 8007 8008 **8009** 8010 Details 2018 Club Car Precedent Electric Golf Cart S/N: JE1823879230 C/W: 36 Volt Battery... lang:de **score:10** filesize: 1.4 M page_count: 414 document date: 2025-03-12

Lot #		Details	Lot #	Details
1	2023 John Deere 950N Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2017 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
2	2021 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2017 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
3	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2017 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
4	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2017 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX
5	2011 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX	2017 Case 910SD High-Flow Mid-Boiler Loader	S/N: J4003091, J7003094 C/W: 1000 Operator Station, Backhoe Pilot Controls, Hydraulic Quick Coupler, 24 in Loader Bucket, 24 in Backhoe Digging Bucket Usage: 1679 Hr Asset located in: Humble, TX

This catalog was created on February 7, 2025 03:26:18 AM (GMT)
Please check our website for the most accurate and up-to-date information.

[illegible][illegible]

lang:de **score:9** filesize: 906.75 K page_count: 261 document date: 2024-12-10

[illegible]

This catalog was created at March 19, 2025 12:25:05 AM GMT.
Please check our website for the most accurate and up-to-date information

[\[pdf\]](#) User Manual Catalog

RB Auction Event Export Mar 21 2025 Quick Coupler 60 in Bucket 540 PTO 3 Point Hitch 215 65 14 Front

Tires Start Weights Auxiliary Hydraulics 6 5 165 Tires 11 hours ago — Manual Outriggers Frame

Leveling 360 85 28 10 00 Solid Usage 4 070 Hr Asset located Chehalis WA 13 2020 JLG 1255

Telehandler S N Catalog Pacific Northwest Regional USA 2025162 assets ctfassets net ueyxw0p8lpyv

```
B7B781AC B475 6400 4688 282A37F4BE88 eff40959eb03b02df44a97b595e4ad99 |||
```

Page 1 of 324 Pacific Northwest Regional Event, USA - Mar 21, 2025 Lot # Details
2015 Ford F-450 ... mins ISX15 6 Cylinder 15 L Diesel 450 hp Engine, 2015 US EPA
Label, Requires Diesel Exhaust Fluid, **28009** Engine hrs, Engine Brake, Automated
Transmission, 12350 lb Front Axle, 40000 lb Rears, 52350 lb...

lang:en score:9 filesize: 1.09 M page_count: 324 document date: 2025-03-19