

APDTY 028473

APDTY 028473 Engine Oil Dip Stick User Manual

Brand: APDTY

Model: 028473

INTRODUCTION

This manual provides comprehensive instructions for the installation, operation, and maintenance of your APDTY 028473 Engine Oil Dip Stick. This product is designed for specific vehicle compatibility to ensure accurate engine oil level measurement.

Compatible Vehicles:

- 1997-2001 Toyota Camry
- 1999-2001 Toyota Solara

1. INSTALLATION

1.1 Vehicle Compatibility Verification

Before installation, ensure your vehicle matches the compatible models listed in this manual. Incorrect fitment can lead to inaccurate readings or damage.

1.2 Locating the Dipstick Tube

Identify the engine oil dipstick tube in your vehicle's engine bay. Refer to your vehicle's owner's manual for the exact location if needed. The tube is typically marked with a cap or handle.

1.3 Installing the New Dipstick

Carefully insert the APDTY 028473 Engine Oil Dip Stick into the designated dipstick tube. Ensure it slides in smoothly and seats fully. Do not force the dipstick into the tube.



Image 1: The APDTY 028473 Engine Oil Dip Stick. This image shows the full length of the dipstick with its yellow handle and measurement markings.

2. OPERATING INSTRUCTIONS: CHECKING ENGINE OIL LEVEL

2.1 Preparation

1. **Warm the Engine:** Operate the vehicle until the engine reaches its normal operating temperature.
2. **Park on Level Ground:** Ensure the vehicle is parked on a flat, level surface to obtain an accurate reading.
3. **Turn Off Engine:** Switch off the engine and wait approximately 5-10 minutes to allow the oil to drain back into the oil pan.

2.2 Checking Procedure

4. **Remove Dipstick:** Pull the APDTY 028473 Engine Oil Dip Stick completely out of its tube.
5. **Wipe Clean:** Use a clean cloth or paper towel to thoroughly wipe all oil from the dipstick blade.
6. **Reinsert Dipstick:** Fully reinsert the clean dipstick into the tube until it is seated correctly.
7. **Remove and Read:** Pull the dipstick out again and observe the oil level on the blade. The oil level should be between the "FULL" and "ADD" marks (or equivalent markings).



Image 2: Close-up view of the APDTY 028473 Engine Oil Dip Stick's measurement markings. This image highlights the specific indicators on the dipstick used to determine the engine oil level.

2.3 Interpreting Readings

- If the oil level is below the "ADD" mark, add the recommended type and amount of engine oil.
- If the oil level is above the "FULL" mark, consult a qualified mechanic as overfilling can cause engine damage.
- Ensure the dipstick is fully reinserted after checking the oil level to prevent oil leaks and contamination.

3. MAINTENANCE

3.1 Regular Checks

It is recommended to check your engine oil level at least once a month, or before long trips, to ensure proper lubrication and engine health.

3.2 Cleaning

Periodically clean the dipstick with a clean cloth to remove any accumulated grime or debris, ensuring clear and accurate readings.

3.3 Proper Seating

Always ensure the dipstick is fully seated in its tube after checking the oil. A loose or improperly seated dipstick can lead to oil leaks or allow contaminants into the engine.

4. TROUBLESHOOTING

4.1 Inaccurate Readings

If you suspect inaccurate readings:

- Verify the vehicle is on level ground.
- Ensure the engine has been off for sufficient time (5-10 minutes) for oil to drain.
- Confirm the dipstick is fully inserted and removed correctly.
- Check for any obstructions in the dipstick tube.

4.2 Difficulty Inserting/Removing

If the dipstick is difficult to insert or remove:

- Inspect the dipstick tube for bends, damage, or debris.

- Ensure you are using the correct dipstick for your vehicle model.
- Do not force the dipstick; consult a mechanic if resistance persists.

5. SPECIFICATIONS

Feature	Detail
Brand	APDTY
Model Number	028473
Manufacturer Part Number	028473
OEM Part Number	1530174110
Item Weight	1.76 ounces
Product Dimensions	23 x 3.3 x 0.25 inches
UPC	401000135691
Compatible Vehicles	1997-2001 Toyota Camry, 1999-2001 Toyota Solara

6. WARRANTY AND SUPPORT

Warranty information for the APDTY 028473 Engine Oil Dip Stick is not provided within this manual. For details regarding warranty coverage or technical support, please contact APDTY directly through their official website or authorized retailers.

You can visit the APDTY store for more information:[APDTY Store on Amazon](#)

CALIFORNIA PROPOSITION 65 WARNING

This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm.