

Manuals+

[Q & A](#) | [Deep Search](#) | [Upload](#)

manuals.plus /

› [Autel](#) /

› [Autel MaxiCOM MK808S-TS Scanner User Manual](#)

Autel MK808S-TS

Autel MaxiCOM MK808S-TS Scanner User Manual

Model: MK808S-TS | Brand: Autel

1. INTRODUCTION

The Autel MaxiCOM MK808S-TS is a comprehensive diagnostic tablet designed for automotive professionals and enthusiasts. This device integrates advanced diagnostic functionalities with complete Tire Pressure Monitoring System (TPMS) capabilities. It features a fast processor, Android 11.0 operating system, and extensive vehicle coverage, making it a versatile tool for vehicle maintenance and repair.



Image 1.1: Autel MaxiCOM MK808S-TS scanner displaying its main interface and key features.

2. SETUP AND INITIAL USE

2.1 Package Contents

Verify that all components are present in the package:

- Autel MaxiCOM MK808S-TS Tablet
- MaxiVCI Mini (Bluetooth Vehicle Communication Interface)
- Main Cable
- USB Cable
- Power Adapter
- User Manual (this document)
- Quick Reference Guide
- Carrying Case

2.2 Device Activation and Updates

Upon first use, power on the device and follow the on-screen instructions to register your tool and connect to a Wi-Fi network. Regular software updates are crucial for optimal performance and to access the latest features and vehicle coverage. Updates are available via Wi-Fi.

For language changes or specific support, contact Autel customer service.

2.3 Connecting to a Vehicle

1. Locate the vehicle's OBD-II port (typically under the dashboard).
2. Connect the MaxiVCI Mini to the vehicle's OBD-II port.
3. Ensure the MaxiVCI Mini is paired with the MK808S-TS tablet via Bluetooth.
4. Turn the vehicle's ignition to the ON position (engine off).
5. On the tablet, select "Diagnostics" to begin vehicle communication.

3. OPERATING THE DEVICE

3.1 All Systems Diagnostics

The MK808S-TS can access all available electronic control units (ECUs) in a vehicle to read and clear Diagnostic Trouble Codes (DTCs), view live data, and retrieve ECU information. This provides a comprehensive overview of the vehicle's health.

- **Engine System:** Monitor parameters like RPM, coolant temperature, airflow, and O2 sensor voltage.
- **Anti-lock Braking System (ABS):** Check wheel speed, brake pressure, and steering angle sensor data.
- **Supplemental Restraint System (SRS):** Diagnose issues related to airbags, seat belt sensors, and occupancy sensors.
- **Transmission System:** View transmission input speed, gearshift lever position, and clear faulty codes.
- And many more vehicle-specific systems.



Image 3.1: The MK808S-TS displaying diagnostic results for various vehicle systems.

3.2 Bi-Directional Control (Active Test)

This function allows the diagnostic tool to send commands to the vehicle's ECUs and receive responses, enabling direct control over various components. This helps in quickly identifying faults by testing specific actuators without manual vehicle controls.

- Turn on/off radiator fan, lights, horn, fuel pump.
- Modulate the throttle.
- Open/close windows.
- Operate mirrors.
- Test injectors, solenoids, and relays.



Image 3.2: Examples of bi-directional control functions, such as activating vehicle components.

3.3 Complete TPMS Functions

The MK808S-TS integrates comprehensive TPMS capabilities, functioning as a professional TPMS tool.

- **TPMS Check & Sensor Activation:** Activate 98% of known OEM TPMS sensors and view sensor data including ID, tire pressure, temperature, battery condition, and location.
- **TPMS Diagnostics:** Read and clear TPMS-related DTCs, view live data, and perform active tests for accurate fault analysis.
- **TPMS Relearn:** Access over 3000 relearn procedures to write newly programmed sensor IDs into the vehicle ECU.
- **MX-Sensor Programming:** Program Autel MX-Sensors to replace faulty sensors using four methods:
 - **Copy by Activation:** Program a new MX-Sensor using IDs retrieved from activated sensors.
 - **Copy by OBD:** Program sensor IDs retrieved from the vehicle's ECU.
 - **Copy by Input:** Manually input an original TPMS sensor ID to program a new MX-Sensor.
 - **Auto Create:** Generate a random sensor ID for a new MX-Sensor.
- **TPMS Retrofitting:** Guide to install and program a TPMS module into vehicles that did not originally have one, enabling tire pressure monitoring on the dashboard.



Image 3.3: The MK808S-TS demonstrating professional TPMS functions, including sensor activation and data display.




Image 3.4: Illustrating MX-Sensor programming methods and the TPMS retrofitting process.

3.4 Special Services (28+ Reset Functions)

The device offers over 28 maintenance and reset functions for various vehicle systems, covering a wide range of models.

- **Oil Reset:** Reset the oil light and service mileage after an oil change.

- **EPB (Electronic Parking Brake):** Reset brake pads after replacement and diagnose related issues.
- **SAS (Steering Angle Sensor):** Read, erase, and overwrite steering angle sensor records.
- **BMS (Battery Management System):** Reset the battery after replacement.
- **IMMO (Immobilizer/Anti-Theft Matching):** Program replacement key fobs and reset data if a key is lost.
- **Injector Service:** Diagnose and adjust injector-related problems.
- **DPF (Diesel Particulate Filter):** Support forced DPF regeneration.
- **Throttle:** Relearn/reset throttle body positions.
- Other functions include Seat Calibration, Adjust A/F, Windows Calibration, Cylinder Service, Trans Adaption, CHG Tire Size, Language Change, Odometer, Headlamp Calibration, and ABS Bleeding.

Note: The availability of specific functions varies by vehicle make, model, and year.



Image 3.5: Overview of the 28+ maintenance and reset functions available on the device.

4. MAINTENANCE

4.1 Software Updates

The MK808S-TS receives automatic system and software updates via Wi-Fi. Ensure your device is connected to a stable internet connection to download and install the latest updates. Updating regularly ensures access to new features, vehicle models, and performance enhancements.

4.2 Device Care

- Keep the device clean and free from dust and moisture.
- Store the device in its protective carrying case when not in use.
- Avoid exposing the device to extreme temperatures.
- Use only the provided power adapter for charging.

5. TROUBLESHOOTING

5.1 Common Issues and Solutions

- **Device not powering on:** Ensure the battery is charged or connect the power adapter.
- **No communication with vehicle:**
 - Verify the MaxiVCI Mini is securely connected to the OBD-II port.
 - Confirm the MaxiVCI Mini is paired via Bluetooth with the tablet.
 - Ensure the vehicle ignition is ON.
 - Check for blown fuses in the vehicle's OBD-II circuit.
- **Software update failure:** Ensure a stable Wi-Fi connection and sufficient storage space on the device. Try restarting the device and the update process.
- **Specific function not available:** Functionality can vary by vehicle make, model, and year. Refer to the vehicle coverage list and ensure the software is up to date.

5.2 Technical Support

For further assistance, please contact Autel customer support. Provide your device's serial number and a detailed description of the issue for efficient service.

6. SPECIFICATIONS

Feature	Specification
Model	Autel MaxiCOM MK808S-TS
Operating System	Android 11.0
Processor	1.8GHz Cortex-A55 Quad-core
Memory	4GB RAM, 64GB On-board ROM
Display	7-inch LCD, 1024x600 Resolution Touchscreen
Connectivity	Bluetooth 2.1 EDR (MaxiVCI Mini), Wi-Fi
Battery	5000mAh Lithium-Polymer (7 hours continuous use)
Dimensions	10 x 6.9 x 1.4 inches
Item Weight	5.41 pounds
Special Features	Activate 98% of known TPMS sensors, Bi-directional control, 28+ Reset functions, TPMS retrofitting, FCA AutoAuth support (requires registration), Digital Inspection Camera support (MV105/108, sold separately), Battery Testing (with Autel BT506, sold separately).

2025 NEWEST MK808S-TS



	MK808S-TS	MK808TS	MK808
Cost	649	649	449
Processor	Cortex-A55 Quad-core Processor	Cortex-A9 Quad-core Processor	Cortex-A9 Processor
OS	Android 11	Android 4.4.4	Android 4.4.4
RAM/ROM	4G/64G	1G/64G	1G/64G
Wi-Fi	2.4 & 5GHz	2.4GHz	2.4GHz
BT Connection	√	√	×
Bi-Directional Control	√	√	√
All System Diagnostics	√	√	√
Special Function	28+	28+	28+
TPMS Retrofit	√	√	×
TPMS Programming	√	√	×
1000+ TPMS Relearn	√	√	×
Sensor Data Reading	√	√	×

Image 6.1: Comparison of Autel MK808S-TS with previous models, highlighting hardware and feature upgrades.

7. VEHICLE COVERAGE

The Autel MaxiCOM MK808S-TS supports over 150 US, Asian, and European vehicle makes and models, primarily those manufactured after 1996 (US-based) and after 2000 (EU/Asia-based).

Supported Regions and Examples:

- **Asia:** Acura, Daewoo, Honda, Hyundai, Infiniti, Isuzu, Kia, Lexus, Mazda, Mitsubishi, Nissan, Scion, SsangYong, Subaru, Suzuki, Toyota, BYD, Chery, DFM, FAW, Foton, Geely, GreatWall, Haval, JAC, Lifan, Luxgen, MG, Zotye.
- **Europe:** Abarth, Alfa Romeo, Alpina, Aston Martin, Audi, Bentley, Benz, BMW, Citroen, Dacia, Ferrari, Fiat, Jaguar, Lamborghini, Lancia, Land Rover, Lotus, Maserati, Maybach, Mini, Opel, Peugeot, Porsche, Renault, Rolls-Royce, SAAB, Skoda, Smart, Sprinter, Volvo, Volkswagen.
- **USA:** Buick, Cadillac, Chevrolet, Chrysler, Dodge, Ford, GMC, Hummer, Jeep, Lincoln, Mercury, Oldsmobile, Pontiac, Saturn, Tesla, Workhorse.

- **Australia:** Ford Australia, Holden.

For a complete and up-to-date list of supported vehicles, refer to the official Autel website or the device's software.

EXTENSIVE VEHICLES COVERAGE

Superior Hardware Equipped, 13 Languages Supported

Asia

Acura, Daewoo, Honda, Hyundai, Infiniti, Isuzu, Kia, Lexus, Mazda, Mitsubishi, Subaru, Suzuki, Tisuzu, Daihatsu

Europe

Abarth, Alfa Romeo, Bugatti, Dacia, Ford EU, Fiat, Jaguar, Lancia, Mercedes, Mini, Opel, Peugeot, Porsche, Renault, Saab, Seat, Skoda, Smart, Sprinter, Land Rover, Citroen, Volvo, VW, Vauxhall, Bentley, Rolls-Royce, FIAT, Lamborghini, Maybach

USA

Buick, Cadillac, Chevrolet, Dodge, Ford, GM, Chrysler, Jeep, Lincoln, Hummer, Pontiac, Saturn, Scion, Workhorse

Australia

Ford Australia, Holden

English, Chinese, French, German, Spanish, Portuguese, Dutch, Polish, Swedish, Korean, Japanese, Russian, Italian.

Android 11
NEW

Cortex-A55 Quad-core Processor
NEW

4G/64G Memory
NEW

7" LCD touchscreen

3.7 V/5000 mAh lithium-polymer battery

Image 7.1: Visual representation of the extensive vehicle coverage and supported languages.

8. WARRANTY AND SUPPORT

Autel provides ongoing software updates and technical support for the MaxiCOM MK808S-TS. For warranty information, please refer to the documentation included with your purchase or visit the official Autel website. For specific inquiries, language changes, or technical assistance, please contact Autel customer service directly.








© 2024 Autel. All rights reserved. Information subject to change without notice.

Related Documents - MK808S-TS

[Autel Quick Reference Guide for Diagnostic Tools](#)

A concise quick reference guide for Autel diagnostic tools, including setup, software updates, firmware updates for MaxiVCI Mini, and wireless printing instructions. Covers regulatory information for FCC and Industry Canada.


	Autel MaxiCheck MX808S-TS Quick Reference Guide Quick reference guide for the Autel MaxiCheck MX808S-TS diagnostic tool, covering getting started, software updates, firmware updates, and wireless printing.
	Autel MaxiCOM MK808S-TS User Manual: Comprehensive Automotive Diagnostics and TPMS Guide This comprehensive user manual for the Autel MaxiCOM MK808S-TS provides detailed instructions on automotive diagnostics, special functions, TPMS services, and battery testing. Learn to effectively use your diagnostic tool.
	Autel MaxiCOM MK808Z User Manual: Comprehensive Guide to Automotive Diagnostics Explore the Autel MaxiCOM MK808Z User Manual for detailed instructions on automotive diagnostics, special functions, maintenance, and troubleshooting. Learn to use Autel's advanced diagnostic tool effectively.
	Autel MaxiCOM MK900-TS Quick Reference Guide Quick start guide for the Autel MaxiCOM MK900-TS diagnostic tool, covering initial setup, power on, registration, and VCI connection.
	AUTEL MaxiCOM MK906S Pro & MK906S Pro-TS User Manual Comprehensive user manual for the AUTEL MaxiCOM MK906S Pro and MaxiCOM MK906S Pro-TS advanced smart wireless automotive diagnostic devices. Covers setup, diagnostics, TPMS, service functions, and maintenance.



[Autel MaxiCOM MK808S-TS User Manual: Comprehensive Automotive Diagnostics and TPMS Guide](#)

This comprehensive user manual for the Autel MaxiCOM MK808S-TS provides detailed instructions on automotive diagnostics, special functions, TPMS services, and battery testing. Learn to effectively use your diagnostic tool.

lang:en score:45 filesize: 8.13 M page_count: 147 document date: 2024-04-23



[\[pdf\] User Manual Specifications](#)

MaxiCOM MK808S TS User Manual EN Index of 2023 03 autel co in |||

Trademarks Autel, MaxiSys, MaxiDAS, MaxiPRO, MaxiRecorder, MaxiCOM, MaxiTPMS, and MaxiCheck are trad ...

.....3 2.1 MAXICOM MK808S-TS
TABLET3 2.1.1 F...

lang:en score:44 filesize: 2.59 M page_count: 155 document date: 2023-03-30



[\[pdf\] User Manual Specifications](#)

MaxiCOM MK808S TS User Manual EN Download MK808Z Autel 31033540g814 autel u cms www
202210 |||

Trademarks Autel, MaxiSys, MaxiDAS, MaxiPRO, MaxiRecorder, MaxiCOM, MaxiTPMS, and MaxiCheck are trad ...

.....3 2.1 MAXICOM MK808S-TS
TABLET3 2.1.1 F...

lang:en score:44 filesize: 8.08 M page_count: 155 document date: 2022-09-15



[\[pdf\]](#) User Manual Specifications

MaxiCOM MK808S TS User Manual EN Autel 1 4M Autel MK808Z All System Bidirectional Tool
TPMS Relearn Programming Scanner 23120417016801197375 carobd de upload pro |||
Trademarks Autel, MaxiSys, MaxiDAS, MaxiPRO, MaxiRecorder, MaxiCOM,
MaxiTPMS, and MaxiCheck are trad ...

.....3 2.1 MAXICOM **MK808S-TS**
TABLET3 2.1.1 F...

lang:en **score:40** filesize: 1.41 M page_count: 155 document date: 2022-09-15




[\[pdf\]](#) User Manual Specifications

MaxiCOM MK808S TS User Manual EN Autel 1 4MAutel MK808Z Bi Directional Control Scan Tool
with Full TPMS Function23120417016800865282AutelTools eu upload pro 23120417016800865282 |||
Trademarks Autel, MaxiSys, MaxiDAS, MaxiPRO, MaxiRecorder, MaxiCOM,
MaxiTPMS, and MaxiCheck are trad ...

.....3 2.1 MAXICOM **MK808S-TS**
TABLET3 2.1.1 F...

lang:en **score:40** filesize: 1.41 M page_count: 155 document date: 2022-09-15



[\[pdf\]](#) User Manual Specifications

MaxiCOM MK808S TS User Manual US 21 mag 2024 — There are various procedures techniques
tools and parts required for servicing vehicles as well the skills of person doing work 21040940zuz1
auteltech u cms www 202405 |||

USER MANUAL MaxiCOM **MK808S-TS** Trademarks Autel, MaxiSys, MaxiDAS,
MaxiPRO, MaxiRecorder, MaxiCOM, MaxiTPMS, and MaxiCheck are trademarks of
Autel Intelligent Technology Corp., Ltd., registered in China, the United States, and
other countries. All other marks are trademarks or registered trademark...

lang:en **score:35** filesize: 7.87 M page_count: 149 document date: 2024-04-23

EMTEK
ADVANCE TO THE WORLD

TEST REPORT

Product Name : AUTOMOTIVE DIAGNOSIS & ANALYSIS SYSTEM
MaxiCheck MX808S-TS, MaxiCOM MK808S-TS,
Model Number : MaxiTPMS TS608S, MaxiDAS DS808S-TS, MaxiPRO
MP808S-TS, MaxiPRO MK808BT Pro, MaxiDAS
FCC ID : DS808S-BT, MaxiPRO MP808BT Pro
WQ8- MX808S-TS2152

Prepared for
Address : Autel Intelligent Technology Corp., Ltd.
7th-8th, 10th Floor, Building B1, Zhiyuan, Xueyuan Rd, Xili,
Nanshan, Shenzhen 518055 China

Prepared by
Address : EMTEK (SHENZHEN) CO., LTD.
Building B9, Mapalang Industry Zone, Nanshan District,
Shenzhen, Guangdong, China
Tel: (0755) 26954280
Fax: (0755) 26954282

Report Number : ENS22021703MW0120R
Date(s) of Tests : February 22, 2022 to March 14, 2022
Date of Issue : May 26, 2022

Report No. EN0212021703MW0120R Page 1 of 60 Ver 2.0

[pdf] Test Report

ELECTROMAGNETIC EMISSIONS COMPLIANCE REPORT fly TR DTS Autel Intelligent Tech Corp Ltd

MX808S TS2152 MaxiPro TS WQ8 WQ8MX808STS2152 mx808s ts2152

TEST REPORT Product Name AUTOMOTIVE DIAGNOSIS ANALYSIS SYSTEM
MaxiCheck MX808S-TS, MaxiCOM **MK808S-TS**, Model Number MMaPx8i0T8PSM-
TSST, SM6a0x8iPSR, MOaMxiKD8A0S8BDTS8P0r8oS, M-TaSx,iMDAaxSiPRO
DS808S-BT, MaxiPRO MP808BT Pro FCC ID WQ8- MX808S-TS2152 Prepared for
Address Prepared by Address ...

lang:en score:25 filesize: 3.74 M page_count: 60 document date: 2022-05-26

SDoC Attestation Letter

To: Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD

FCC ID: WQ8- MX808S-TS2152
Product description: AUTOMOTIVE DIAGNOSIS & ANALYSIS SYSTEM
Type designation: MaxiPro MX808S-TS, MaxiPro MK808S-TS, MaxiPro TS608S, MaxiPro DS808S-
TS, MaxiPro MP808-TS, MaxiPro MP808S-BT, MaxiPro DS808S-BT, MaxiPro
MP808S-BT

Trademark: AUTEL

To Whom It May Concern:

Has been the units used for conducting FCC compliance testing, the SDoC part will be
issued by EMTEK (SHENZHEN) CO., LTD.

If you have any question or concerns, pls. contact us.

Client's Signature:


Frank Li
Date: 2022.4.18
Autel Intelligent Technology Corp., Ltd.

[pdf]

Date siemic SDoC Attestation Letter Autel Intelligent Tech Corp Ltd MX808S TS2152 MaxiPro TS WQ8
WQ8MX808STS2152 mx808s ts2152

SDoC Attestation Letter To: Federal Communications Commission 7435 Oakland
Mills Road Columbia, MD FCC ID: WQ8- MX808S-TS2152 Product description:
AUTOMOTIVE DIAGNOSIS ANALYSIS SYSTEM Type designation: MaxiPro
MX808S-TS, MaxiPro **MK808S-TS**, MaxiPro TS608S, MaxiPro DS808S- TS, MaxiPro
MP808- TS, Max...

lang:fr score:24 filesize: 58.9 K page_count: 1 document date: 2022-04-21

Model Declaration Letter

We
Name: Autel Intelligent Technology Corp., Ltd.
Address: 7th-8th, 10th Floor, Building B1, Zhiyuan, Xueyuan Rd, Xili, Nanshan,
Shenzhen 518055 China

Certify that:
Product name: AUTOMOTIVE DIAGNOSIS & ANALYSIS SYSTEM
MaxiPro MX808S-TS, MaxiPro MK808S-TS, MaxiPro TS608S, MaxiPro
DS808S-TS, MaxiPro MP808-TS, MaxiPro MP808S-BT, MaxiPro DS808S-BT
Model No.: MaxiPro MP808S-BT

The 3 models are only different for model name, the others are the same

as our label:
Client's Signature:



Frank Li
Contact: (0755) 89167779 Extension:
Company Name: Autel Intelligent Technology Corp., Ltd.
Date: 2022.4.18

[pdf] Declaration of Conformity

Model Confirmation Letter susie yin Declaration Autel Intelligent Tech Corp Ltd MX808S TS2152 MaxiPro
TS WQ8 WQ8MX808STS2152 mx808s ts2152

Model Declaration Letter We Name: Address: Autel Intelligent Technology Corp.,Ltd.
7th-8th,10th Floor, Building B1, Zhiyuan, Xueyuan Rd, Xili, Nanshan,
Shenzhen,518055 China Certify that Product name: Model No.: AUTOMOTIVE
DIAGNOSIS ANALYSIS SYSTEM MaxiPro MX808S-TS, MaxiPro **MK808S-TS**,
MaxiPro...

lang:it score:24 filesize: 102.27 K page_count: 1 document date: 2022-04-21




[\[pdf\]](#) Frequently Asked Questions

FAQ for Diag Diagnostic Device 18 Nov 2022 end user Autel Intelligent Technology Corp Ltd
8117331975 support autel helpdesk attachments |||

- 1 - FAQ for Diagnostic Device Revision Date: 2022-11-18 Version Number: V1.0
version number ver ... MP808Z-TS, MP808TS, MP808S, MP808, DS808S-TS,
DS808TS, DS808 K , MX808S-TS, MX808TS, MX808S, MX808, **MK808S-TS**,
MK808Z-TS, MK808TS, MK808BT PRO, MK808Z-BT, MK808S, MK808BT, MK808
APP Series AP200, HT...

lang:nl **score:23** filesize: 6.56 M page_count: 94 document date: 2022-11-18




[\[pdf\]](#) Test Report SAR Rating

SAR Report BVADT Roy Wu Autel Intelligent Tech Corp Ltd MX808S TS2152 MaxiPro TS WQ8
WQ8MX808STS2152 mx808s ts2152

TEST REPORT Product Name AUTOMOTIVE DIAGNOSIS ANALYSIS SYSTEM
MaxiCheck MX808S-TS, MaxiCOM **MK808S-TS**, Model Number MMaPx8i0T8PSM-
TSST, SM6a0x8iPSR, MOaMxiKD8A0S8BDTS8P0r8oS, M-TaSx,iDMAaxSiPRO
DS808S-BT, MaxiPRO MP808BT Pro FCC ID WQ8- MX808S-TS2152 Prepared for
Address Prepared by Address ...

lang:en **score:20** filesize: 886.38 K page_count: 40 document date: 2022-05-30



[\[pdf\]](#) Test Report

ELECTROMAGNETIC EMISSIONS COMPLIANCE REPORT fly TR BT DSS Autel Intelligent Tech Corp
Ltd MX808S TS2152 MaxiPro TS WQ8 WQ8MX808STS2152 mx808s ts2152

TEST REPORT Product Name AUTOMOTIVE DIAGNOSIS ANALYSIS SYSTEM
MaxiCheck MX808S-TS, MaxiCOM **MK808S-TS**, Model Number
MMaaxxiTPPRMOSMTPS860088SS-T, SM,aMxiaDxAiPSRDOSM80K88S0-8TBST,
Pro, MaxiDAS DS808S-BT, MaxiPRO MP808BT Pro FCC ID WQ8- MX808S-TS2152
Prepared for Address Prepared by Address ...

lang:en **score:20** filesize: 3.51 M page_count: 64 document date: 2022-05-26




[pdf]

12 3 UPDATE AUTEL dic 2022 — Supports scan and basic diagnostic functions for all systems new C Class 206 S 223 SL 232 EQE 295 EQS 297 12030051y1ck autel u cms www 202212 ||| DIAGNOSTIC TOOLS SOFTWARE UPDATE Update for MaxiSYS Ultra, Ultra EV, MS919, MS909, MS909EV, MS906 PR ... the following models: NY-Ypsilon 2011-2018 , and LX-Thema 2012-2016 . Update for MaxiCOM MK808S, **MK808S-TS**, MK808BT PRO, MK808Z, MK808Z-TS, MK808Z-BT RENAULT Version: V3.50- 1. Adds special functi... lang:en **score:19** filesize: 716.48 K page_count: 10 document date: 2022-12-05



[pdf]

Test Report ELECTROMAGNETIC EMISSIONS COMPLIANCE REPORT fly TR WiFi 5G Part 1 Autel Intelligent Tech Corp Ltd MX808S TS2152 MaxiPro TS WQ8 WQ8MX808STS2152 mx808s ts2152 TEST REPORT Product Name AUTOMOTIVE DIAGNOSIS ANALYSIS SYSTEM MaxiPro MX808S-TS, MaxiPro **MK808S-TS**, MaxiPro Model Number TMSa6x0iP8rSo, MaxiPro DS808S-TS, MaxiPro MP808- TS, MK808S-BT, MaxiPro DS808S-BT, MaxiPro MP808S-BT FCC ID WQ8- MX808S-TS2152 Prepared for Address Prepared by Address ... lang:en **score:18** filesize: 4.99 M page_count: 67 document date: 2022-05-30



[pdf]


SAR Rating Per Servizi e Supporto Informazioni sul diritto Esclusione di garanzie ID FCC WQ8 MX808S Conformità TS2152 Page 154 Consultare il rivenditore o un tecnico radio TV esperto per assistenza Cambiamenti modifiche non B1K5sG8KbL m media amazon images I ||| Marchi Autel, MaxiSys, MaxiDAS, MaxiPRO, MaxiRecorder, MaxiCOM, MaxiTPMS e MaxiCheck sono marchi di ... 3 2.1 TABLET MAXICOM **MK808S-TS**3 2.1.1 Descr... lang:it **score:17** filesize: 2.08 M page_count: 155 document date: 2023-05-22



[Autel Diagnostic Tools Software Update Release Notes - Latest Vehicle Coverage & Features](#)

Comprehensive release notes for Autel diagnostic tools software updates. Discover new vehicle coverage, enhanced functions, and improved compatibility for brands like Benz, VW, Audi, BMW, Toyota, and more, detailing specific version updates and features.

lang:en score:16 filesize: 3 M page_count: 19 document date: 2023-12-22



[\[pdf\] User Manual](#)

1 UPDATE AUTEL auteltech â° cms www 22070540qewm u 202403 |||

DIAGNOSTIC TOOLS SOFTWARE UPDATE MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS91 ... and Active Test and Oil Reset function. MaxiCheck MX808S, MX808S-TS, MaxiCOM MK808S, MK808BT Pro, **MK808S-TS**... VW Version: V4.00- 1. Upgrades coverage of model year, supporting models up to 2024. A...

lang:en score:14 filesize: 3.04 M page_count: 27 document date: 2024-03-08


DIAGNOSTIC TOOLS NORTH AMERICA V2401-2401		
Model	Version	Update Highlights
MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS919, MS909, MS909EV, MS908SP II, MS908S II, MS908S3, Elite II, Elite II Pro, MS906 Pro, MS906 Pro-TS, MaxiCOM MK908P II, MK906 Pro, MK906S Pro, MK906 Pro-TS, MK906S Pro-TS.	2401	1. Support Programming/Setting function for models with integrated level up to March 2024. 2. Update coverage of model year for basic functions including Throttle Control, Live Data, and Active Test, supporting models up to March 2024. 3. Add coverage for models with integrated level up to March 2024. 4. Add coverage for models with integrated level up to March 2024. 5. Add coverage for models with integrated level up to March 2024. 6. Add coverage for models with integrated level up to March 2024. 7. Add coverage for models with integrated level up to March 2024. 8. Add coverage for models with integrated level up to March 2024. 9. Add coverage for models with integrated level up to March 2024. 10. Add coverage for models with integrated level up to March 2024.
MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS919, MS909, MS909EV, MS908SP II, MS908S II, MS908S3, Elite II, Elite II Pro, MS906 Pro, MS906 Pro-TS, MaxiCOM MK908P II, MK906 Pro, MK906S Pro, MK906 Pro-TS, MK906S Pro-TS.	2401	1. Support Programming/Setting function for models with integrated level up to March 2024. 2. Update coverage of model year for basic functions including Throttle Control, Live Data, and Active Test, supporting models up to March 2024. 3. Add coverage for models with integrated level up to March 2024. 4. Add coverage for models with integrated level up to March 2024. 5. Add coverage for models with integrated level up to March 2024. 6. Add coverage for models with integrated level up to March 2024. 7. Add coverage for models with integrated level up to March 2024. 8. Add coverage for models with integrated level up to March 2024. 9. Add coverage for models with integrated level up to March 2024. 10. Add coverage for models with integrated level up to March 2024.
MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS919, MS909, MS909EV, MS908SP II, MS908S II, MS908S3, Elite II, Elite II Pro, MS906 Pro, MS906 Pro-TS, MaxiCOM MK908P II, MK906 Pro, MK906S Pro, MK906 Pro-TS, MK906S Pro-TS.	2401	1. Support Programming/Setting function for models with integrated level up to March 2024. 2. Update coverage of model year for basic functions including Throttle Control, Live Data, and Active Test, supporting models up to March 2024. 3. Add coverage for models with integrated level up to March 2024. 4. Add coverage for models with integrated level up to March 2024. 5. Add coverage for models with integrated level up to March 2024. 6. Add coverage for models with integrated level up to March 2024. 7. Add coverage for models with integrated level up to March 2024. 8. Add coverage for models with integrated level up to March 2024. 9. Add coverage for models with integrated level up to March 2024. 10. Add coverage for models with integrated level up to March 2024.

[\[pdf\]](#)

DIAGNOSTIC TOOLS SOFTWARE UPDATE 2405 AUTEL autel â° cms www 30091450av9d u 202409 |||

Product MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS919, MS909, MS909EV, MS908S ... software structure. 8 MaxiCheck MX808S, MS808S-TS, MX900, MX900-TS, MaxiCOM MK808S, MK808BT PRO, **MK808S-TS**, MK900, MK900-BT, MK900-TS... Dodge DIAGNOSTIC TOOLS SOFTWARE UPDATE-2405 V2.10 1. Add...

lang:en score:14 filesize: 182.13 K page_count: 15 document date: 2024-08-29



[\[pdf\] User Manual](#)

10 12102511lmh1 autel u cms www 202312 |||

DIAGNOSTIC TOOLS SOFTWARE UPDATE MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS91 ... alibration. 23/25 MaxiCheck MX808S, MX808S-TS, MaxiCOM MK808S, MK808BT Pro, MK808Z-BT, MK808K-BT, **MK808S-TS**, MK808Z-TS Peugeot Version: V2.20- 1. Upgrades coverage of model year for the following 2...

lang:en score:14 filesize: 3.04 M page_count: 25 document date: 2023-11-28



[pdf]

4 UPDATE AUTEL autel â° cms www 04013540o3aq u 202406 |||

DIAGNOSTIC TOOLS SOFTWARE UPDATE MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS91 ... 900, MP900-BT, MP900-TS, MaxiCheck MX808S, MS808S-TS, MX900, MX900-TS, MaxiCOM MK808S, MK808BT PRO, **MK808S-TS**, MK900, MK900-BT, MK900-TS... Kaweiauto Version: V1.20- 1. Releases overseas version for ...

lang:en score:14 filesize: 391.56 K page_count: 37 document date: 2024-05-24



[pdf]

8 23084223wk12 auteltech u cms www 202309 |||

DIAGNOSTIC TOOLS SOFTWARE UPDATE MaxiSYS Ultra, Ultra EV, Ultra ADAS, Ultra Lite, Ultra Lite S, MS91 ... an. 16/17 MaxiCheck MX808S, MX808S-TS, MaxiCOM MK808S, MK808Z, MK808BT Pro, MK808Z-BT, MK808K-BT, **MK808S-TS**, MK808Z-TS Nissan Version: V3.00- 1. Adds coverage for 56 models from 2022 to the first ...

lang:en score:11 filesize: 2.99 M page_count: 17 document date: 2023-09-21