



[Manuals.plus](#) /

> [Ferrean](#) /

> Ferrean OEM GE Microwave Grease Filter Installation and Maintenance Guide for PVM9215SK2SS, PVM9215SK3SS

## Ferrean PVM9215SK2SS, PVM9215SK3SS

# Ferrean OEM GE Microwave Grease Filter User Manual

Models: PVM9215SK2SS, PVM9215SK3SS

## INTRODUCTION

---

This manual provides essential instructions for the proper installation, function, and maintenance of your Ferrean OEM GE Microwave Grease Filter. This filter is designed to capture grease and other airborne particles generated during cooking, protecting your microwave's internal components and maintaining air quality. It is compatible with GE microwave models PVM9215SK2SS and PVM9215SK3SS.

## SETUP: INSTALLATION INSTRUCTIONS

---

**Safety First: Always unplug your microwave oven from the power outlet before performing any installation or maintenance procedures to prevent electrical shock.**

- 1. Locate Existing Filter:** Identify the current grease filter(s) on your microwave oven. These are typically located on the underside of the microwave, above the cooking surface. They may be held in place by small clips or tabs.
- 2. Remove Old Filter:** Carefully disengage any clips or tabs holding the old filter. Gently pull the old filter downwards or slide it out, depending on its design. Dispose of the old filter responsibly.
- 3. Unpack New Filter:** Remove the new Ferrean OEM GE Microwave Grease Filter from its packaging. Inspect it for any damage.
- 4. Insert New Filter:** Align the new filter with the opening. Ensure the filter's mesh side faces downwards towards the cooking surface. Slide the filter into the designated slots or push it upwards until it clicks into place.
- 5. Secure Filter:** Confirm that the filter is securely seated and that any clips or tabs are engaged to hold it firmly. It should not hang loosely.
- 6. Restore Power:** Once the new filter is securely installed, plug your microwave oven back into the power outlet.



Image: Ferrean OEM GE Microwave Grease Filter. This image shows the rectangular metal mesh filter, which is designed to fit into the underside of compatible GE microwave models to trap cooking grease.

---

## OPERATING: FILTER FUNCTION

---

The grease filter functions passively by trapping airborne grease particles and other contaminants that are drawn into the microwave's ventilation system during cooking. This process helps to keep the microwave's interior components clean, prevents grease buildup in the exhaust ductwork, and contributes to a cleaner kitchen environment. The filter does not require active operation; its effectiveness relies on proper installation and regular maintenance.

---

## MAINTENANCE AND CLEANING

---

Regular maintenance of your grease filter is crucial for optimal performance and longevity of your microwave oven. A clogged filter can reduce airflow, decrease ventilation efficiency, and potentially lead to grease accumulation within the appliance.

- **Inspection:** Inspect the grease filter monthly. If it appears heavily soiled, discolored, or clogged with grease, it is time for cleaning or replacement.
- **Cleaning:** This filter is typically washable. To clean, remove the filter as described in the 'Installation

Instructions'. Wash the filter in hot water with a mild detergent or in a dishwasher. Allow the filter to dry completely before reinstalling it.

- **Replacement:** Even with regular cleaning, grease filters can degrade over time. It is recommended to replace the grease filter every 6 to 12 months, or more frequently depending on cooking habits, to ensure maximum efficiency.

---

## TROUBLESHOOTING

---

- **Filter Does Not Fit:**

*Possible Cause:* Incorrect filter model for your microwave.

*Solution:* Verify that your microwave model (PVM9215SK2SS or PVM9215SK3SS) matches the compatibility listed for this filter. Double-check the orientation of the filter during installation.

- **Reduced Airflow/Ventilation:**

*Possible Cause:* The filter is clogged with grease or debris.

*Solution:* Remove and clean the filter thoroughly. If cleaning does not restore airflow, the filter may need to be replaced.

- **Filter Falls Out:**

*Possible Cause:* Filter not properly secured.

*Solution:* Ensure all clips or tabs are fully engaged and the filter is seated correctly in its designated slots.

---

## PRODUCT SPECIFICATIONS

---

- **Brand:** Ferrean
- **Item Weight:** 2.08 ounces
- **Package Dimensions:** 8 x 4 x 2 inches
- **Compatibility:** GE Microwave Models PVM9215SK2SS, PVM9215SK3SS
- **Material:** Metal Mesh

---

## WARRANTY AND CUSTOMER SUPPORT

---

For specific warranty information regarding your Ferrean OEM GE Microwave Grease Filter, please refer to the documentation provided at the time of purchase or contact the seller directly. If you have questions about installation, compatibility, or require further assistance, please reach out to the retailer or manufacturer's customer support channels.