

Vortex DFCCW-MGD3

Vortex Optics Defender-CCW Micro Red Dot Sights User Manual

Brand: Vortex | Model: Defender-CCW Micro Red Dot Sights (DFCCW-MGD3)

1. PRODUCT OVERVIEW

The Vortex Optics Defender-CCW Micro Red Dot Sight is engineered for compact everyday carry, offering a blend of concealment, reliability, and rapid target acquisition. It features a class-leading window size with minimal optical distortion, providing a clear and true sight picture. Adjustable brightness lets you find the perfect setting for your eye, while a button lockout feature prevents unintended adjustments. With motion activation and an auto-shutoff function, the Defender-CCW is designed to be ready when needed while conserving battery life.



Figure 1.1: Front-side view of the Vortex Optics Defender-CCW Micro Red Dot Sight.

2. WHAT'S IN THE BOX

Your Defender-CCW package includes the following components:

- Red Dot Sight
- 1° Shim Plate
- Picatinny Rail Mount
- Rubber Cover
- Lens Cloth
- CR1632 Battery
- Tool for installation and adjustments
- Most Common Mounting Screw Sets (various sizes for different firearms)
- Product Manual (this document)



Figure 2.1: All included components in the Defender-CCW package.

3. KEY FEATURES

- **Compact Design:** Micro-sized for maximum concealment and a smooth, no-snag draw.
- **Broad Compatibility:** Fits all Shield RMS and Shield RMSc footprints without modification.
- **Motion Activation:** Automatically wakes up the red dot for immediate use.
- **Auto-Shutoff:** 14-hour auto-shutoff feature to preserve battery life.
- **Fast-Rack Texturing:** Textured front face provides enhanced grip for racking the slide off various surfaces.
- **Aspherical Lens:** Large, aspherical lens offers a class-leading sight window with minimal distortion and true color representation.
- **Durability:** Waterproof, shockproof, and features ArmorTek coating for lens protection.
- **ShockShield Polymer Insert:** Absorbs everyday impacts for increased toughness.



Figure 3.1: Annotated diagram of the Defender-CCW highlighting its key features.

4. SETUP AND INSTALLATION

The Defender-CCW is designed for straightforward installation on compatible firearms. Ensure your firearm is unloaded and safe before beginning any installation procedures.

1. **Prepare Firearm:** Ensure the firearm is completely unloaded and the chamber is clear. Always follow your firearm manufacturer's safety guidelines.
2. **Identify Footprint:** The Defender-CCW is compatible with Shield RMS and Shield RMSc footprints. Verify your firearm's slide or mounting plate matches this footprint.
3. **Select Screws:** Use the provided screw sets to find the correct length and thread pitch for your specific firearm model. Each bag is clearly labeled for compatibility (e.g., M3 x 0.5, M4 x 0.7).
4. **Mounting:**
 - Place the Defender-CCW onto the designated mounting area on your firearm's slide or adapter plate.
 - Align the screw holes on the sight with those on the firearm.
 - Insert the appropriate screws and tighten them evenly using the provided tool. Do not overtighten; refer to your firearm's manual for specific torque specifications if available.
5. **Battery Installation:** The Defender-CCW uses a CR1632 battery. The battery compartment is typically located on the side or bottom of the unit. Use the provided tool to open the compartment, insert the battery with the positive (+) side facing up, and secure the cover.
6. **Initial Check:** Once mounted, ensure the sight is securely attached and does not wobble. Activate the sight to confirm the dot appears.



Figure 4.1: Underside of the Defender-CCW, illustrating mounting points.

5. OPERATING INSTRUCTIONS

Familiarize yourself with the controls and functions of your Defender-CCW Micro Red Dot Sight.

5.1. Power On/Off and Brightness Adjustment

- The Defender-CCW features motion activation. When motion is detected, the red dot will automatically power on.
- To manually adjust brightness, use the large, positive-click buttons located on the sides of the sight. One button increases brightness, and the other decreases it.
- The sight will automatically shut off after 14 hours of no motion to conserve battery life.

5.2. Button Lockout Feature

To prevent accidental adjustments while carrying, the Defender-CCW includes a button lockout feature. Consult the detailed product manual for specific instructions on how to activate and deactivate this feature.

5.3. Windage and Elevation Adjustments

The sight features clearly marked windage and elevation adjustment turrets. Use the provided tool to make precise adjustments for zeroing your sight. Each click typically corresponds to 1 MOA (Minute of Angle) of adjustment.






Figure 5.1: Brightness adjustment buttons (left) and windage/elevation adjustment points (right).

6. MAINTENANCE

Proper maintenance ensures the longevity and optimal performance of your Defender-CCW sight.

- **Lens Cleaning:** Use the provided lens cloth to gently wipe the optical surfaces. For stubborn smudges, a small amount of lens cleaning solution designed for optics can be applied to the cloth, not directly to the lens. Avoid using harsh chemicals or abrasive materials.
- **Battery Replacement:** When the dot dims or fails to illuminate, replace the CR1632 battery. Use the included tool to access the battery compartment. Ensure proper polarity when inserting the new battery.
- **General Cleaning:** Wipe down the exterior of the sight with a soft, damp cloth to remove dirt and debris.
- **Storage:** Store the sight in a cool, dry place, ideally in its rubber cover, when not in use.

7. TROUBLESHOOTING

If you encounter issues with your Defender-CCW, refer to the following common troubleshooting steps:

Problem	Possible Cause	Solution
---------	----------------	----------

Problem	Possible Cause	Solution
Dot does not appear or is dim.	Low or dead battery; incorrect battery installation; auto-shutoff activated.	Replace battery (CR1632) ensuring correct polarity. Move the sight to activate motion sensor. Adjust brightness settings.
Dot flickers or appears inconsistent.	Low battery; refresh rate characteristic; extreme temperature.	Replace battery. Some red dot sights may exhibit a slight flicker at certain brightness settings or refresh rates, which is often normal operation. If persistent and disruptive, contact support.
Sight loses zero.	Improper mounting; loose screws; extreme impact.	Check mounting screws and re-tighten to manufacturer specifications. Re-zero the sight. If issue persists after re-zeroing and checking mounting, contact support.
Buttons are unresponsive.	Button lockout feature engaged; debris obstructing buttons.	Refer to the operating instructions to disengage the button lockout. Clean around the buttons to ensure no debris is interfering.

If these steps do not resolve the issue, please contact Vortex Optics customer support for further assistance.

8. SPECIFICATIONS

Brand	Vortex
Model Name	Defender-CCW Micro Red Dot Sights
Part Number	DFCCW-MGD3
Color	Black
Style	3 MOA - Green Dot
Item Weight	0.5 Pounds
Material	Aluminum
Compatible Devices	Handgun, Rifle, Shotgun, and other firearms with compatible mounting systems
Mounting Type	Picatinny Mount (adapter included)
Reticle Type	MOA - Green Dot
UPC	843829146418
Date First Available	April 21, 2025

9. WARRANTY AND SUPPORT

Vortex Optics stands behind its products with an industry-leading warranty:

VIP Warranty: The Defender-CCW Micro Red Dot Sight is backed by Vortex's unlimited, unconditional, lifetime, VIP Warranty. This is a fully transferable promise to repair or replace your item if it becomes damaged or defective. Please note that this warranty does not cover loss, theft, deliberate damage, or cosmetic damage that does not hinder performance.

For more information, visit: www.vortexoptics.com

[\[pdf\]](#)

63602 \$4 799 99 63601 11002 \$3 999 11001 myvendorlink external vfile d vrf s 178276 v 26771 sv 0 i

178 ft b |||

42708 RZR-42707 RZR-16009 RZR-16 ... CF-GD2 DFXL-MRD8 DFXL-MRD5 DFXL-

DFCCW-MRD3 **DFCCW-MGD3** VPR-SGMRD3-MR-E VPR-SGMRD3-E V6XM V3XM

VMX-3T MT-5108 SF-UH1 ARD35 SF-OBC SF-OC SPC-C RZB...

lang:da score:21 filesize: 273.64 K page_count: 9 document date: 2025-05-13

SKU	QTY	DESCRIPTION	NEW	MRP
REPLACEMENT PARTS				
Accessories and Spare Parts				
2200-0000		Replaces the 2200-0000 PFP for 2200-01-0000		\$4,750.00
2200-0001		Replaces the 2200-0001 PFP for 2200-01-0000		\$4,750.00
2200-0002		Replaces the 2200-0002 PFP for 2200-01-0000		\$4,750.00
2200-0003		Replaces the 2200-0003 PFP for 2200-01-0000		\$4,750.00
2200-0004		Replaces the 2200-0004 PFP for 2200-01-0000		\$4,750.00
2200-0005		Replaces the 2200-0005 PFP for 2200-01-0000		\$4,750.00
2200-0006		Replaces the 2200-0006 PFP for 2200-01-0000		\$4,750.00
2200-0007		Replaces the 2200-0007 PFP for 2200-01-0000		\$4,750.00
2200-0008		Replaces the 2200-0008 PFP for 2200-01-0000		\$4,750.00
2200-0009		Replaces the 2200-0009 PFP for 2200-01-0000		\$4,750.00
2200-0010		Replaces the 2200-0010 PFP for 2200-01-0000		\$4,750.00
2200-0011		Replaces the 2200-0011 PFP for 2200-01-0000		\$4,750.00
2200-0012		Replaces the 2200-0012 PFP for 2200-01-0000		\$4,750.00
2200-0013		Replaces the 2200-0013 PFP for 2200-01-0000		\$4,750.00
2200-0014		Replaces the 2200-0014 PFP for 2200-01-0000		\$4,750.00
2200-0015		Replaces the 2200-0015 PFP for 2200-01-0000		\$4,750.00
2200-0016		Replaces the 2200-0016 PFP for 2200-01-0000		\$4,750.00
2200-0017		Replaces the 2200-0017 PFP for 2200-01-0000		\$4,750.00
2200-0018		Replaces the 2200-0018 PFP for 2200-01-0000		\$4,750.00
2200-0019		Replaces the 2200-0019 PFP for 2200-01-0000		\$4,750.00
2200-0020		Replaces the 2200-0020 PFP for 2200-01-0000		\$4,750.00
2200-0021		Replaces the 2200-0021 PFP for 2200-01-0000		\$4,750.00
2200-0022		Replaces the 2200-0022 PFP for 2200-01-0000		\$4,750.00
2200-0023		Replaces the 2200-0023 PFP for 2200-01-0000		\$4,750.00
2200-0024		Replaces the 2200-0024 PFP for 2200-01-0000		\$4,750.00
2200-0025		Replaces the 2200-0025 PFP for 2200-01-0000		\$4,750.00
2200-0026		Replaces the 2200-0026 PFP for 2200-01-0000		\$4,750.00
2200-0027		Replaces the 2200-0027 PFP for 2200-01-0000		\$4,750.00
2200-0028		Replaces the 2200-0028 PFP for 2200-01-0000		\$4,750.00
2200-0029		Replaces the 2200-0029 PFP for 2200-01-0000		\$4,750.00
2200-0030		Replaces the 2200-0030 PFP for 2200-01-0000		\$4,750.00
2200-0031		Replaces the 2200-0031 PFP for 2200-01-0000		\$4,750.00
2200-0032		Replaces the 2200-0032 PFP for 2200-01-0000		\$4,750.00
2200-0033		Replaces the 2200-0033 PFP for 2200-01-0000		\$4,750.00
2200-0034		Replaces the 2200-0034 PFP for 2200-01-0000		\$4,750.00
2200-0035		Replaces the 2200-0035 PFP for 2200-01-0000		\$4,750.00
2200-0036		Replaces the 2200-0036 PFP for 2200-01-0000		\$4,750.00
2200-0037		Replaces the 2200-0037 PFP for 2200-01-0000		\$4,750.00
2200-0038		Replaces the 2200-0038 PFP for 2200-01-0000		\$4,750.00
2200-0039		Replaces the 2200-0039 PFP for 2200-01-0000		\$4,750.00
2200-0040		Replaces the 2200-0040 PFP for 2200-01-0000		\$4,750.00
2200-0041		Replaces the 2200-0041 PFP for 2200-01-0000		\$4,750.00
2200-0042		Replaces the 2200-0042 PFP for 2200-01-0000		\$4,750.00
2200-0043		Replaces the 2200-0043 PFP for 2200-01-0000		\$4,750.00
2200-0044		Replaces the 2200-0044 PFP for 2200-01-0000		\$4,750.00
2200-0045		Replaces the 2200-0045 PFP for 2200-01-0000		\$4,750.00
2200-0046		Replaces the 2200-0046 PFP for 2200-01-0000		\$4,750.00
2200-0047		Replaces the 2200-0047 PFP for 2200-01-0000		\$4,750.00
2200-0048		Replaces the 2200-0048 PFP for 2200-01-0000		\$4,750.00
2200-0049		Replaces the 2200-0049 PFP for 2200-01-0000		\$4,750.00
2200-0050		Replaces the 2200-0050 PFP for 2200-01-0000		\$4,750.00
2200-0051		Replaces the 2200-0051 PFP for 2200-01-0000		\$4,750.00
2200-0052		Replaces the 2200-0052 PFP for 2200-01-0000		\$4,750.00
2200-0053		Replaces the 2200-0053 PFP for 2200-01-0000		\$4,750.00
2200-0054		Replaces the 2200-0054 PFP for 2200-01-0000		\$4,750.00
2200-0055		Replaces the 2200-0055 PFP for 2200-01-0000		\$4,750.00
2200-0056		Replaces the 2200-0056 PFP for 2200-01-0000		\$4,750.00
2200-0057		Replaces the 2200-0057 PFP for 2200-01-0000		\$4,750.00
2200-0058		Replaces the 2200-0058 PFP for 2200-01-0000		\$4,750.00
2200-0059		Replaces the 2200-0059 PFP for 2200-01-0000		\$4,750.00
2200-0060		Replaces the 2200-0060 PFP for 2200-01-0000		\$4,750.00
2200-0061		Replaces the 2200-0061 PFP for 2200-01-0000		\$4,750.00
2200-0062		Replaces the 2200-0062 PFP for 2200-01-0000		\$4,750.00
2200-0063		Replaces the 2200-0063 PFP for 2200-01-0000		\$4,750.00
2200-0064		Replaces the 2200-0064 PFP for 2200-01-0000		\$4,750.00
2200-0065		Replaces the 2200-0065 PFP for 2200-01-0000		\$4,750.00
2200-0066		Replaces the 2200-0066 PFP for 2200-01-0000		\$4,750.00
2200-0067		Replaces the 2200-0067 PFP for 2200-01-0000		\$4,750.00
2200-0068		Replaces the 2200-0068 PFP for 2200-01-0000		\$4,750.00
2200-0069		Replaces the 2200-0069 PFP for 2200-01-0000		\$4,750.00
2200-0070		Replaces the 2200-0070 PFP for 2200-01-0000		\$4,750.00
2200-0071		Replaces the 2200-0071 PFP for 2200-01-0000		\$4,750.00
2200-0072		Replaces the 2200-0072 PFP for 2200-01-0000		\$4,750.00
2200-0073		Replaces the 2200-0073 PFP for 2200-01-0000		\$4,750.00
2200-0074		Replaces the 2200-0074 PFP for 2200-01-0000		\$4,750.00
2200-0075		Replaces the 2200-0075 PFP for 2200-01-0000		\$4,750.00
2200-0076		Replaces the 2200-0076 PFP for 2200-01-0000		\$4,750.00
2200-0077		Replaces the 2200-0077 PFP for 2200-01-0000		\$4,750.00
2200-0078		Replaces the 2200-0078 PFP for 2200-01-0000		\$4,750.00
2200-0079		Replaces the 2200-0079 PFP for 2200-01-0000		\$4,750.00
2200-0080		Replaces the 2200-0080 PFP for 2200-01-0000		\$4,750.00
2200-0081		Replaces the 2200-0081 PFP for 2200-01-0000		\$4,750.00
2200-0082		Replaces the 2200-0082 PFP for 2200-01-0000		\$4,750.00
2200-0083		Replaces the 2200-0083 PFP for 2200-01-0000		\$4,750.00
2200-0084		Replaces the 2200-0084 PFP for 2200-01-0000		\$4,750.00
2200-0085		Replaces the 2200-0085 PFP for 2200-01-0000		\$4,750.00
2200-0086		Replaces the 2200-0086 PFP for 2200-01-0000		\$4,750.00
2200-0087		Replaces the 2200-0087 PFP for 2200-01-0000		\$4,750.00
2200-0088		Replaces the 2200-0088 PFP for 2200-01-0000		\$4,750.00
2200-0089		Replaces the 2200-0089 PFP for 2200-01-0000		\$4,750.00
2200-0090		Replaces the 2200-0090 PFP for 2200-01-0000		\$4,750.00
2200-0091		Replaces the 2200-0091 PFP for 2200-01-0000		\$4,750.00
2200-0092		Replaces the 2200-0092 PFP for 2200-01-0000		\$4,750.00
2200-0093		Replaces the 2200-0093 PFP for 2200-01-0000		\$4,750.00
2200-0094		Replaces the 2200-0094 PFP for 2200-01-0000		\$4,750.00
2200-0095		Replaces the 2200-0095 PFP for 2200-01-0000		\$4,750.00
2200-0096		Replaces the 2200-0096 PFP for 2200-01-0000		\$4,750.00
2200-0097		Replaces the 2200-0097 PFP for 2200-01-0000		\$4,750.00
2200-0098		Replaces the 2200-0098 PFP for 2200-01-0000		\$4,750.00
2200-0099		Replaces the 2200-0099 PFP for 2200-01-0000		\$4,750.00
2200-0100		Replaces the 2200-0100 PFP for 2200-01-0000		\$4,750.00
2200-0101		Replaces the 2200-0101 PFP for 2200-01-0000		\$4,750.00
2200-0102		Replaces the 2200-0102 PFP for 2200-01-0000		\$4,750.00
2200-0103		Replaces the 2200-0103 PFP for 2200-01-0000		\$4,750.00
2200-0104		Replaces the 2200-0104 PFP for 2200-01-0000		\$4,750.00
2200-0105		Replaces the 2200-0105 PFP for 2200-01-0000		\$4,750.00
2200-0106		Replaces the 2200-0106 PFP for 2200-01-0000		\$4,750.00
2200-0107		Replaces the 2200-0107 PFP for 2200-01-0000		\$4,750.00
2200-0108		Replaces the 2200-0108 PFP for 2200-01-0000		\$4,750.00
2200-0109		Replaces the 2200-0109 PFP for 2200-01-0000		\$4,750.00
2200-0110		Replaces the 2200-0110 PFP for 2200-01-0000		\$4,750.00
2200-0111		Replaces the 2200-0111 PFP for 2200-01-0000		\$4,750.00
2200-0112		Replaces the 2200-0112 PFP for 2200-01-0000		\$4,750.00
2200-0113		Replaces the 2200-0113 PFP for 2200-01-0000		\$4,750.00
2200-0114		Replaces the 2200-0114 PFP for 2200-01-0000		\$4,750.00
2200-0115		Replaces the 2200-0115 PFP for 2200-01-0000		\$4,750.00
2200-0116		Replaces the 2200-0116 PFP for 2200-01-0000		\$4,750.00
2200-0117		Replaces the 2200-0117 PFP for 2200-01-0000		\$4,750.00
2200-0118		Replaces the 2200-0118 PFP for 2200-01-0000		\$4,750.00
2200-0119		Replaces the 2200-0119 PFP for 2200-01-0000		\$4,750.00
2200-0120		Replaces the 2200-0120 PFP for 2200-01-0000		\$4,750.00
2200-0121		Replaces the 2200-0121 PFP for 2200-01-0000		\$4,750.00
2200-0122		Replaces the 2200-0122 PFP for 2200-01-0000		\$4,750.00
2200-0123		Replaces the 2200-0123 PFP for 2200-01-0000		\$4,750.00
2200-0124		Replaces the 2200-0124 PFP for 2200-01-0000		\$4,750.00
2200-0125		Replaces the 2200-0125 PFP for 2200-01-0000		\$4,750.00
2200-0126		Replaces the 2200-0126 PFP for 2200-01-0000		\$4,750.00
2200-0127		Replaces the 2200-0127 PFP for 2200-01-0000		\$4,750.00
2200-0128		Replaces the 2200-0128 PFP for 2200-01-0000		\$4,750.00
2200-0129		Replaces the 2200-0129 PFP for 2200-01-0000		\$4,750.00
2200-0130		Replaces the 2200-0130 PFP for 2200-01-0000		\$4,750.00
2200-0131		Replaces the 2200-0131 PFP for 2200-01-0000		\$4,750.00
2200-0132		Replaces the 2200-0132 PFP for 2200-01-0000		\$4,750.00
2200-0133		Replaces the 2200-0133 PFP for 2200-01-0000		\$4,750.00
2200-0134		Replaces the 2200-0134 PFP for 2200-01-0000		\$4,750.00
2200-0135		Replaces the 2200-0135 PFP for 2200-01-0000		\$4,750.00
2200-0136		Replaces the 2200-0136 PFP for 2200-01-0000		\$4,750.00
2200-0137		Replaces the 2200-0137 PFP for 2200-01-0000		\$4,750.00
2200-0138		Replaces the 2200-0138 PFP for 2200-01-0000		\$4,750.00
2200-0139		Replaces the 2200-0139 PFP for 2200-01-0000		\$4,750.00
2200-0140		Replaces the 2200-0140 PFP for 2200-01-0000		\$4,750.00
2200-0141		Replaces the 2200-0141 PFP for 2200-01-0000		\$4,750.00
2200-0142		Replaces the 2200-0142 PFP for 2200-01-0000		\$4,750.00
2200-0143		Replaces the 2200-0143 PFP for 2200-01-0000		\$4,750.00
2200-0144		Replaces the 2200-0144 PFP for 2200-01-0000		\$4,750.00
2200-0145		Replaces the 2200-0145 PFP for 2200-01-0000		\$4,750.00
2200-0146		Replaces the 2200-0146 PFP for 2200-01-0000		\$4,750.00
2200-0147		Replaces the 2200-0147 PFP for 2200-01-0000		\$4,750.00
2200-0148		Replaces the 2200-0148 PFP for 2200-01-0000		\$4,750.00
2200-0149		Replaces the 2200-0149 PFP for 2200-01-0000		\$4,750.00
2200-0150		Replaces the 2200-0150 PFP for 2200-01-0000		\$4,750.00
2200-0151		Replaces the 2200-0151 PFP for 2200-01-0000		\$4,750.00
2200-0152		Replaces the 2200-0152 PFP for 2200-01-0000		\$4,750.00
2200-0153		Replaces the 2200-0153 PFP for 2200-01-0000		\$4,750.00
2200-0154		Replaces the 2200-0154 PFP for 2200-01-0000		\$4,750.00
2200-0155		Replaces the 2200-0155 PFP for 2200-01-0000		\$4,750.00
2200-0156		Replaces the 2200-0156 PFP for 2200-01-0000		\$4,750.00
2200-0157		Replaces the 2200-0157 PFP for 2200-01-0000		\$4,750.00
2200-0158		Replaces the 2200-0158 PFP for 2200-01-0000		\$4,750.00
2200-0159		Replaces the 2200-0159 PFP for 2200-01-0000		\$4,750.00
2200-0160		Replaces the 2200-0160 PFP for 2200-01-0000		\$4,750.00
2200-0161		Replaces the 2200-0161 PFP for 2200-01-0000		\$4,750.00
2200-0162		Replaces the 2200-0162 PFP for 2200-01-0000		\$4,750.00
2200-0163		Replaces the 2200-0163 PFP for 2200-01-0000		\$4,750.00
2200-0164		Replaces the 2200-0164 PFP for 2200-01-0000		\$4,750.00
2200-0165		Replaces the 2200-0165 PFP for 2200-01-0000		\$4,750.00
2200-0166		Replaces the 2200-0166 PFP for 2200-01-0000		\$4,750.00
2200-0167		Replaces the 2200-0167 PFP for 2200-01-0000		\$4,750.00
2200-0168		Replaces the 2200-0168 PFP for 2200-01-0		

[illegible]

[\[pdf\]](#) Accessories Price List

Neoprene Case 843829117135 \$29 99 22 52 \$ StrikeFire® ARD35 Vortex 2025 Price List Effective

myvendorlink external vfile d vrf s 179003 v 90409 sv 0 i 211 ft b |||

6-36x56 FFP EBR-7D MRAD ... Defender-CCWTM DFCCW-MRD6 Defender-

CCWTM 6 MOA Red Dot DFCCW-MRD3 Defender-CCWTM 3 MOA Red Dot

DFCCW-MGD3 Defender-CCW 3 MOA Green Dot Sight Viper Shotgun Enclosed

VPR-SGMRD3-MR-E Viper SG Enc...

lang:nl score:19 filesize: 186.73 K page_count: 7 document date: 2025-05-22