

ZN-MT03

Generic ZN-MT03 CO2 Detector User Manual

Model: ZN-MT03 | Brand: Generic

1. INTRODUCTION

The Generic ZN-MT03 CO2 Detector is a portable semiconductor air quality monitor designed to accurately measure carbon dioxide (CO2) concentration, temperature, and humidity in various indoor environments. This device provides real-time data with a clear digital display and visual alerts, making it suitable for homes, offices, agricultural settings, and laboratories.

Package Contents:

- 1 x ZN-MT03 CO2 Detector
- 1 x USB Data Cable
- 1 x User Manual (this document)

2. SAFETY INFORMATION

- Do not expose the device to extreme temperatures, direct sunlight, or high humidity.
- Avoid dropping or subjecting the device to strong impacts.
- Do not attempt to disassemble or modify the device. This will void the warranty.
- Keep out of reach of children.
- Use only the provided USB cable for charging.
- Ensure proper ventilation around the device for accurate readings.

3. PRODUCT OVERVIEW

The ZN-MT03 detector features a compact design with a clear digital display that shows CO2 concentration in Parts Per Million (PPM), temperature in Celsius, and relative humidity percentage. It utilizes semiconductor detection technology for accurate air quality assessment and provides visual alerts through flashing lights to indicate different CO2 levels.



Figure 3.1: Front view of the ZN-MT03 CO2 Detector with its digital display active.

Key Features:

- Accurate Semiconductor CO2 Detection
- Real-time Temperature and Humidity Monitoring
- Clear Digital Display with Visual Alerts
- Portable Design for Multiple Applications
- Fast Response and Stable Readings (1-second refresh rate)

4. SETUP

4.1 Initial Charging

Before first use, ensure the device is fully charged. Connect the provided USB data cable to the device's charging port and to a standard USB power adapter (not included) or a computer USB port. The battery indicator on the display will show charging status.



Figure 4.1: Side view highlighting the USB charging port.

4.2 First Use and Calibration

1. Press and hold the power button for 3 seconds to turn on the device.
2. Upon startup, place the detector in a well-ventilated area for approximately 20 minutes. This allows the sensor to stabilize and calibrate to ambient air conditions.
3. Once the data displayed becomes stable, the device is ready for accurate detection in your desired location.

5. OPERATING INSTRUCTIONS

5.1 Power On/Off

To power on the device, press and hold the power button located on the side for approximately 3 seconds. To power off, repeat the same action by pressing and holding the power button for 3 seconds.

5.2 Understanding the Display

The digital display provides real-time readings for CO2 concentration, temperature, and humidity. The CO2 reading is prominently displayed in PPM (Parts Per Million) and is accompanied by a color-coded indicator (green, yellow, red) and flashing lights to signify different concentration levels.



Figure 5.1: Close-up of the ZN-MT03 display interface.

- **CO2 (PPM):** Main numerical reading. Color changes and flashing lights indicate concentration levels (e.g., green for good, yellow for moderate, red for high).
- **TEMP (°C):** Current ambient temperature.
- **HUMI (%RH):** Current relative humidity.
- **Battery Indicator:** Shows remaining battery life.

5.3 Application

The ZN-MT03 is versatile and can be used in various settings to monitor air quality:

- **Homes and Offices:** To ensure healthy indoor air quality.
- **Agricultural Planting & Greenhouses:** To optimize CO2 levels for plant growth.
- **Production Warehouses & Laboratories:** For environmental monitoring and safety.



Figure 5.2: ZN-MT03 in a greenhouse setting.

6. MAINTENANCE

6.1 Cleaning the Device

To maintain optimal performance, periodically clean the exterior of the device with a soft, dry cloth. Do not use abrasive cleaners, solvents, or immerse the device in water. Ensure the ventilation openings are free from dust and debris.

6.2 Battery Care

The ZN-MT03 features a built-in rechargeable battery. For best battery life, avoid fully discharging the device frequently. Recharge the device when the battery indicator shows low power. If storing the device for an extended period, charge it to approximately 50% and store in a cool, dry place.

7. TROUBLESHOOTING

Problem	Possible Cause	Solution
---------	----------------	----------

Problem	Possible Cause	Solution
Device does not turn on.	Low or depleted battery.	Charge the device using the provided USB cable.
Inaccurate CO2 readings.	Device not properly calibrated or placed in a poorly ventilated area.	Place the device in a well-ventilated area for 20 minutes for recalibration. Ensure ventilation openings are clear.
Display is dim or unresponsive.	Low battery or device malfunction.	Charge the device. If the issue persists, contact customer support.

8. SPECIFICATIONS

Parameter	Value
Model	ZN-MT03
Material	ABS
Battery	3.7V 1200mAh (built-in)
CO2 Detection Range	400~5000 PPM
CO2 Detection Accuracy	1 PPM
Temperature Detection Range	0~50°C
Temperature Detection Accuracy	±1°C
Humidity Detection Range	0%~99% RH
Humidity Detection Accuracy	±5% RH
Item Weight	197 g
Parcel Dimensions	12 x 12 x 4 cm

9. WARRANTY AND SUPPORT

This product comes with a standard manufacturer's warranty. For specific warranty details, please refer to the documentation provided at the time of purchase or contact your retailer. For technical support, troubleshooting assistance, or any inquiries regarding the ZN-MT03 CO2 Detector, please contact the Generic customer support team through your purchase platform.

