

Manuals+ — User Manuals Simplified.

# Delta OHM LPS03MA0 Sensor Setup and Data Acquisition User Guide

September 9,  
2023

[Home](#) » [Delta OHM](#) » **Delta OHM LPS03MA0 Sensor Setup and Data Acquisition User Guide** 



 Member of GHM GROUP

**DATASENSE**

**Sensor Setup and Data Acquisition**



## Contents [ [hide](#) ]

### 1 INTRODUCTION

### 2 FEATURES

### 3 Documents / Resources

### 4 Related Posts

## INTRODUCTION


DATAsense software is an intuitive and easily installed platform for the control and configuration of the products belonging PYRAsense family.

## FEATURES

### Real Time Data

To monitor pyranometer values directly on your PC.

Graph for displaying the values over the 24 hours



### Data-logging

For recording measurement campaigns, opening and viewing previously saved file

Delta OHM LPS03MA0 Sensor Setup and Data Acquisition - fig2

## PRODUCTS TO BE CONNECTED


Product Type	Model
Pyranometer	LPS10M00 LPS10M0T LPS10MA0 LPS10MAT
Pyranometer	LPS02M00 LPS02M0T LPS02MA0 LPS02MAT
Pyranometer	LPS03M00 LPS03M0T LPS03MA0 LPS03MAT

## Configuration

Configure analog output

Configure attention thresholds for internal sensor values

Configure product identification information



scan here the QR CODE




<https://www.deltaohm.com/product/pyrasense03-class-c-pyranometer/>

Measuring the Enviroment, leading the change

[www.deltaohm.com](http://www.deltaohm.com)

## Documents / Resources

	<a href="#">Delta OHM LPS03MA0 Sensor Setup and Data Acquisition [pdf] User Guide</a> LPS10M00, LPS10M0T, LPS10MA0, LPS10MAT, LPS02M00, LPS02M0T, LPS02MA0, LPS02MAT, LPS03M00, LPS03M0T, LPS03MA0, LPS03MAT, LPS03MA0 Sensor Setup and Data Acquisition, LPS03MA0, Sensor Setup and Data Acquisition, Setup and Data Acquisition, and Data Acquisition, Data Acquisition, Acquisition
---	---

## Related Posts

[Delta OHM HD32.3TC Viewing the Data with Datalog10 Software Instruction Manual](#)

HD32.3TC Viewing the Data with Datalog10 Software Instruction Manual Start the DeltaLog10 software. Connect the instrument mini-USB port...


[Ooma Motion Sensor Setup Guide](#)

ooma motion sensor Key Features Status indicator light (hidden) Motion sensor lens Standing attachment ...



[ICP DAS tM-AD5 Data Acquisition User Guide](#)

ICP DAS tM-AD5 Data Acquisition User Guide  
Congratulations! Congratulations on purchasing the tM-AD5 the most popular automation solution...

[SONBUS SZ2000 ZIGBEE Wireless Data Acquisition Module User Manual](#)

SZ2000 ZIGBEE wireless data acquisition module User Manual File Version: V21.3.25  
SZ2000 uses the standard ZIGBEE Wireless Communication...

Acquisition, and Data Acquisition, Data Acquisition, Delta OHM, LPS02M00, LPS02M0T, LPS02MA0, LPS02MAT, LPS03M00, LPS03M0T, LPS03MA0, LPS03MA0 Sensor Setup and Data Acquisition, LPS03MAT, LPS10M00, LPS10M0T, LPS10MA0, LPS10MAT, Sensor Setup and Data Acquisition, Setup and Data Acquisition

—Previous Post  
[Delta OHM LPS02 Series Photometric Probe User Manual](#)

## Leave a comment

Your email address will not be published. Required fields are marked \*

Comment \*

Name

Email

Website

☐ Save my name, email, and website in this browser for the next time I comment.

Post Comment

## Search

Search ...

Search

@manualsplus YouTube

Manuals+,