

EPSON
BA-T500II
Deployment
Tool



EPSON BA-T500II Deployment Tool Instructions


[Home](#) » [Epson](#) » EPSON BA-T500II Deployment Tool Instructions 

Contents

- [1 EPSON BA-T500II Deployment Tool](#)
- [2 Instructions](#)
- [3 Documents / Resources](#)
 - [3.1 References](#)
- [4 Related Posts](#)

EPSON

EPSON BA-T500II Deployment Tool



Instructions

Version	Ver.3.6.0
Uploaded date	2024/6/13
File size	23,124KB
Explanation	<p>This is a tool used to install a lot of printers efficiently and set the printer driver and change the settings of driver.</p> <p>Also with this tool, it can create a silent package easily to install or setting the driver.</p> <p>1.Note</p> <ul style="list-style-type: none">– None <p>2. Environment [Support OS]</p> <ul style="list-style-type: none">– Windows 11– Windows 10 (32/64bit)– Windows 8.1 (32/64bit)– Windows 8 (32/64bit)– Windows 7 SP1 (32/64 bit) <p>[Support interface]</p> <ul style="list-style-type: none">– Serial– Parallel– USB2.0/3.0 (USB3.0 is supported in the environment for Windows 8 or later.)– Wired/Wireless LAN– Bluetooth <p>[Other requirements]</p> <p>Printer Driver:</p> <ul style="list-style-type: none">– TM-C3500: Ver.1.0.0.5a or later– TM-C3510: Ver.1.0.0.1a or later– TM-C3520: Ver.1.0.0.1a or later– TM-C3400: Ver.1.4 or later– Advanced Printer Driver Ver.4.09 or later– Advanced Printer Driver Ver.5.00 or later– CW-C6000/C6500 series Printer Driver Ver. 1.0.0.0 or later– CW-C8000 series Printer Driver Ver. 1.0.0.0 or later <p>EpsonNet SetupManager Ver.2.2.2 or later TM-XX utility (Only for supported products)</p> <p>(*) The Advanced Printer Driver is not necessary if you are using UPOS driver.</p>

(*) In the UPOS driver environment, you can set the printer by using the EPSON Deployment Tool; however, you cannot set the UPOS driver.

3. Supported Products [Support Model]

- BA-T500II
- CW-C6000 series, CW-C6500 series, CW-C8000 series
- DM-D70
- EU-m30
- TM-C3400, TM-C3400BK, TM-C3500, TM-C3510, TM-C3520
- TM-H2000, TM-H6000IV, TM-H6000V
- TM-J7200, TM-J7700, TM-L500A Ticket, TM-L90, TM-L100
- TM-m10, TM-m30, TM-m30II, TM-m30II-H, TM-m30II-S, TM-m30II-SL, TM-m30II-NT, TM-m30III, TM-m30III-H, TM-m50, TM-m50II, TM-m50II-H
- TM-P20, TM-P60II, TM-P80, TM-P20II, TM-P80II

– TM-S2000MJ, TM-S9000MJ, TM-S2000II-MJ, TM-S9000II-MJ, TM-S2000II-NW, TM-S9000II-NW

– TM-T20, TM-T20II, TM-T20III, TM-T20IIIL, TM-T20X, TM-T70II, TM-T70II-DT2, TM-T81, TM-T81II, TM-T81III

– TM-T82, TM-T82II, TM-T82III, TM-T82IIIL, TM-T82X, TM-T83III, TM-T88V, TM-T88VI, TM-T88VII, TM-T88VI-DT2

– TM-T88VI-iHUB, TM-T100

4. Changes from the Previous Version [Added support for the following models]

– CW-C8000 series


[Bug fix]

Fixed restriction item.

– WPA-Enterprise configuration will fail in some models *1 when a printer that is not covered by the configuration is connected to the same network. In such a case, remove the printer that is irrelevant to the setting from the network. WPA-Enterprise configuration can also be done with Web Config, the model dedicated utility, or the like.

*1: BA-T500II, TM-H2000, TM-H6000IV, TM-L500A Ticket, TM-L90, TM-m10, TM-m30, TM-P20, TM-P60II, TM-P80, TM-T20, TM-T20II, TM-T70II, TM-T81, TM-T81II, TM-T82, TM-T82II, TM-

T88V, TM printer with UB-R04 or UB-R05



[EPSON BA-T500II Deployment Tool](#) [pdf] Instructions

BA-T500II, CW-C6000 series, CW-C6500 series, CW-C8000 series, DM-D70, EU-m30, TM-C3 400, TM-C3400BK, TM-C3500, TM-C3510, TM-C3520, TM-H2000, TM-H6000IV, TM-H6000V, TM-J7200, TM-J7700, TM-L500A Ticket, TM-L90, M-L100, TM-m10, TM-m30, TM-m30II, TM-m 30II-H, TM-m30II-S, TM-m30II-SL, TM-m30II-NT, TMm30III, TM-m30III-H, TM-m50, TM-m50II, TM-m50II-H, TM-P20, TM-P60II, TM-P80, TM-P20II, TM-P80II, BA-T500II Deployment Tool, BA -T500II, Deployment Tool, Tool

References

- [User Manual](#)

[Manuals+](#), [Privacy Policy](#)

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.