

gembird FC-K500 Computer Case Fornax Instruction Manual

Home » GEMBIRD » gembird FC-K500 Computer Case Fornax Instruction Manual

gembird FC-K500 Computer Case Fornax




Contents

- 1 REMARKS
- 2 A: Package details
- 3 B: Schematic diagram of wire interface
- 4 C: IO panel introduction
- 5 D: Chassis disassembly diagram
- 6 E: Remove and install glass side panels
- 7 F: The power supply installation
- 8 G: Motherboard installation
- 9 H: The graphics card installation
- 10 I: Max CPU Height diagram
- 11 J: Fan installation
- 12 K: Water cooling installation
- 13 L: SSD installation
- 14 M: HDD installation
- 15 Documents / Resources
 - 15.1 References
- **16 Related Posts**

- 1. Before installing and operating the device, read the following instruction carefully
- 2. Before installing the device, check the list of components and their condition. In case of problems, contact the seller.
- 3. To avoid personal injury and/or equipment damage do not insert objects or body parts into the device while it is operating
- 4. Check wiring diagrams to avoid short circuits and/or damage equipment.
- 5. Do not block the air inlets and outlets.
- 6. Keep the device away from heat sources, sunlight, water and oils. Do not use in a high humidity environment. Place it on a stable, flat and vibration-free surface in a well-ventilated room.
- 7. Do not clean with chemicals or wet cloths (chemicals: bleach, wax, benzene, alcohol, solvent, mosquito repellent, perfumes, lubricants).
- 8. Wear protective gloves when handling the device to avoid cuts and injuries.

A: Package details

· Motherboard screw




x 6

· The power screw




x 6

HDD screw




· Copper pillar




B: Schematic diagram of wire interface


Please refer to the manual that came with your motherboard for any specific connection instructions



C: IO panel introduction




D: Chassis disassembly diagram



E: Remove and install glass side panels


Metal side plate installation: buckle the side plate and fix it with two screws



F: The power supply installation


The power supply can be fixed by aligning the screw in the figure to the hole position(ATX PSU :max length205mm)

Note: different types of power supply, hole location may be slightly different, take the actual object as the standard.




G: Motherboard installation

According to the motherboard type (ATX/M-ATX/ITX), the copper pillars may need to be re-arranged manually according to the fixing locations specific to your motherboard



H: The graphics card installation

VGA length limit:385mm



I: Max CPU Height diagram

Max CPU Height: 165mm



J: Fan installation

Rear fan: 1X120MM(included)




K: Water cooling installation

Align the SSD holes and fix them with screws




L: SSD installation

Align the SSD holes and fix them with screws



M: HDD installation

Align the hard disk holes and fix them with HDD screws



N:Panel disassembly



Documents / Resources



gembird FC-K500 Computer Case Fornax [pdf] Instruction Manual FC-K500 Computer Case Fornax, FC-K500, Computer Case Fornax, Fornax

References

• User Manual

Manuals+, Privacy Policy

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.