



HUSQVARNA PRO BATTERY SERIES

HOW LONG WILL THE BATTERY LAST?

CHARGING TIME FOR DIFFERENT BATTERIES AND CHARGERS

		CHARGING CYCLES	QC500		QC250		QC80 / QC80F	
			CHARGING LEVEL		CHARGING LEVEL		CHARGING LEVEL	
	BLi950X	1500	1 h 40 min	2 h 20 min	—	—	—	—
	BLi550X	1500	1 h	1 h 25 min	—	—	—	—
	BLi300	1500	35 min	1 h	1 h 5 min	1 h 30 min	4 h	4 h 20 min
	BLi200X/ BLi200	1500	30 min	50 min	35 min	55 min	2 h 25 min	2 h 40 min

Required temperature for charging: min. 5°C max. 40°C Best option

WORKING TIME ON ONE CHARGE

WORKING TIME

ON ONE CHARGE

APPLICATION	PRODUCT NAME	BATTERY				
		BLi950X	BLi550X	BLi300	BLi200X	BLi200
HEDGE TRIMMERS						
Tough cutting	520iHT4	6 h	3 h	1 h 45 min	1 h	1 h
	520iHE3					
	520iHD60					
Light trimming	520iHT4	12 h 30 min	6 h 15 min	3 h 45 min	2 h	2 h
	520iHE3					
	520iHD60					
BLOWERS						
Tough blowing	550iBTX*	1 h	30 min	—	—	—
	530iBX**	1 h 45 min	45 min	35 min	15 min	15 min
	525iB					
Light blowing	550iBTX*	1 h 45 min	50 min	—	—	—
	530iBX**	3 h 30 min	1 h 45 min	1 h	35 min	35 min
	525iB					

N/A = Values were not available at time of printing. — = Not recommended
The runtimes are up-to-times and correspond to work time using save™: actual work, basic maintenance and movement /climbing needed for generic operations.
Given guidelines are indicative only and may not always be repeatable from one setting to another.
*Requires BLi backpack battery module.
**Requires backpack battery / battery belt FLEXI.
***Full capacity only provided by BLi200X / BLi300

WORKING TIME ON ONE CHARGE

WORKING TIME
ON ONE CHARGE



APPLICATION	PRODUCT NAME	BATTERY					
		BLi950X	BLi550X	BLi300	BLi200X	BLi200	
CHAINSAWS							
Take down /removal		540i XP®	12 h	6 h	3 h 30 min	2 h	2 h
	T540i XP® ***						
Pruning in tree		540i XP®	17 h 30 min	9 h	5 h 30 min	3 h	3 h
		T540i XP® ***				3 h	3 h
		535i XP®					
		T535i XP®					
Pruning		540i XP®	7 h 30 min	3 h 45 min	2 h 15 min	1 h 15 min	1 h 15 min
		T540i XP® ***				1 h 15 min	1 h 15 min
		535i XP®					
		T535i XP®					
Log cutting		540i XP®	3 h 30 min	1 h 45 min	1 h	30 min	30 min
		T540i XP® ***				35 min	35 min
		535i XP®					
		T535i XP®					
Carpentering		540i XP®	18 h 45 min	9 h 30 min	5 h 30 min	3 h	3 h
		T540i XP® ***				3 h	3 h
		535i XP®					
		T535i XP®					
POLE SAWS							
Pruning		530iPT5	11 h 30 min	5 h 45 min	3 h 30 min	2 h	2 h
		530iP4					
FORESTRY CLEARING SAW							
Clearing		530iPX	8 h 15 min	4 h 15 min	2 h 30 min	1 h 20 min	1 h 20 min
BRUSHCUTTERS							
Tough grass cutting		520iRX	4 h 15 min	2 h	1 h 15 min	40 min	40 min
		535iRXT	2 h 25 min	1 h 5 min	45 min	25 min	25 min
Tough grass cutting		520iRX	8 h 15 min	4 h 15 min	2 h 15 min	1 h 20 min	1 h 20 min
		535iRXT	1 h 50 min	50 min	30 min	15 min	15 min
TRIMMERS							
Tough grass cutting		520iLX	4 h 15 min	2 h	1 h 15 min	40 min	40 min
Light grass cutting		520iLX	8 h 15 min	4 h 15 min	2 h 15 min	1 h 20 min	1 h 20 min