

CAS Product Quick Guide

CL-5500

CAS CL-5500- Ticket and Label Printing Scale

- To select Ticket or Label mode, press 1810 + **Menu** Key.
Sales mode 1 = Ticket mode, 2 = Label mode.

Sales Operation (Ticket mode)

Weight items

1. Press speed key to call up a PLU
OR
press PLU number + **PLU** key
2. Place item on the Platter
3. Press **Print** Key then Enter Clerk Number to recode a sale. (or Clerk Speed Key)
4. Remove item from platter.

Count items

1. Press speed key to call up a PLU
OR
press PLU number + **PLU** key
2. Enter the number of pieces.
3. Press **Print** Key then Enter Clerk Number to recode a sale. (or Clerk Speed Key)
4. Remove item from platter.

To complete sale

1. Press **PAY** key then Enter Clerk Number + **Print** Key. (or Clerk Speed Key)
2. Enter Payment Method. 0 = Cash 3= Card + **Print** Key

Labelling Operation (Label mode)

1. Press speed key to call up a PLU
OR
press PLU number + **PLU** key
2. Place item on the Platter
3. Press **Print** Key to print a label.

