


SAVE THESE INSTRUCTIONS

Find the latch and the polarity line. Align parts as shown below and insert the adapter box into the track.

Continue to rotate until the latch snaps in place between the two track rails.

Final Position



Second Circuit Positioning

1. Hold onto Adapter Box with one hand
2. Place the end of a flat head screw driver under the contact shown below
3. Gently pull up, the contact should move vertically until hitting a hard stop
4. Follow instructions for inserting into track

Find contact above the ground contact.
This is the only contact that is adjustable.

