



# ELENOR ASSEMBLY INSTRUCT


A



SIZE +1 CM





SIZE +1 CM




Assemble the parts together as shown in the diagram.

(STAGE 2)





Turn the Base upside down and fix it on a flat surface. Then, mount the feet in the mounting package to the profile.

FEET



Place the metal case inside the assembled product.

**The installation is complete.**




ⓑ X1




© X2



X4



X2



X24



© X16



X12

