



Release Notes – Zebra Android 14

14-09-18.00-UG-U115-STD-GRT-04 Release (GMS)

Highlights

This Android 14 GMS release 14-09-18.00-UG-U115-STD-GRT-04 covers TC15 series product. Please see, device compatibility under Addendum Section for more details.

This release requires a mandatory step OS Update method to upgrade to A14 BSP software from A13 and A11. Please refer for more details under “OS Update Installation Requirements and Instructions” section.

Software Packages

Package Name	Description
GR_FULL_UPDATE_14-09-18.00-UG-U115-STD-GRT-04.zip	Full Update Package
GR_DELTA_UPDATE_14-09-18.00-UG-U105-STD_TO_14-09-18.00-UG-U115-STD.zip	Delta package update from 14-09-18.00-UG-U105-STD TO 14-09-18.00-UG-U115-STD release

Security Updates

This build is Compliant up to [Android Security Bulletin](#) of June 01, 2025.

LifeGuard Update 14-09-18.00-UG-U115

- This LG patch is applicable for 14-09-18.00-UG-U105-STD-GRT-04 version.

- **New Features**

- None

- **Resolved Issues**

- SPR-56634: Resolved an issue where notification bar could be pulled down after long pressing the power button despite disabling Notification pulldown from MX.

- **Usage Notes**

- None

LifeGuard Update 14-09-18.00-UG-U105

- This LG patch is applicable for 14-09-18.00-UG-U91-STD-GRT-04 version.

○ New Features

- Scanning Framework
:
 - Added MP7000 support for A14
 - SF string Localization for Japanese.
 - FR5ss5S Scan Engine is added to A14.
 - Added USB scanner/cradle/MP7000 support to A14.

○ Resolved Issues

- None.

○ Usage Notes

- None

LifeGuard Update 14-09-18.00-UG-U91

- This LG patch is applicable for 14-09-18.00-UG-U68-STD-GRT-04 version.

New Features

- **[CPG] Custom Feature CSP:**
 - Implemented support for enabling and disabling custom features using GUIDs through StageNow configuration profiles.
 - Added functionality to process extra parameters when enabling features. Allows more granular configuration options, enabling additional settings to be applied during feature activation.

Resolved Issues

- SPR-54688: Add a fix to resolve locked orientation setting doesn't work properly.

- SPR-55031: Resolved an issue where dialer not appearing on SOTI Lockscreen.
- SPR-55730: Resolved an issue where mixer path configuration for deep-buffer-playback bt-sco-wb is using the SLIM BUS control instead of AUX_PCM_RX.

Usage Notes

- None

LifeGuard Update 14-09-18.00-UG-U68

- This LG patch is applicable for 14-09-18.00-UG-U45-STD-GSE-04 version.

New Features

- ZVC:
 1. Added support for MDM to launch ZVC using remapped key with intent broadcast.
 2. Added support to display ZVC UI in French (Canada).

Resolved Issues

- SPR-55622: Add a fix to resolve tx path VoIP in handsfree for all the bands and PTTPRO in handset and handsfree mode for all the bands.
- SPR-55368: Fixed issue where the DPR setting is different when changing the display size manually versus when changing over Stagenow.

Usage Notes

- None

LifeGuard Update 14-09-18.00-UG-U45

- This LG patch is applicable for 14-09-18.00-UG-U25-STD-GRT-04 version.

New Features

- TUT:
 1. Enable Network Selection for EHS Users. Device operator is able to view and select available network for connectivity while the device is locked down (EHS).
 2. Skip SUW barcode Google restriction-A14:
 - Due to new mandatory privacy requirements from Google, the Setup Wizard Bypass feature has been discontinued on devices running Android 13 and later.
 - Consequently, it is now restricted to skip the Setup Wizard screen, and the StageNow barcode will not function during the Setup Wizard, displaying a toast message stating "Not supported."

- If the Setup Wizard has already been completed and its data was configured to persist on the device in the past, there is no need to repeat this process following an Enterprise Reset.
- For more details, please refer to the Zebra FAQ documentation: <https://techdocs.zebra.com/zebradna/latest/faq/#setupwizardsuw>

- **Resolved Issues**

- SPR-55016: Added support to remap a key with flashlight application.
- SPR-55073: Fixed issue where incorrect information was being recorded in Rx Logger Resource file.

- **Usage Notes**

- None

LifeGuard Update 14-09-18.00-UG-U25

- This LG patch is applicable for 14-09-18.00-UG-U15-STD-GRT-04 version.

- **New Features**

- Fusion:
 - Added Support for WLAN TLS 1.3.
- TUT:
 - UI Manager adds the ability to Configure Color Inversion, System Navigation and Talk Back for accessibility usage.

- **Resolved Issues**

- SPR-54744: Resolved an issue where in the free fall detection is not functioning.

- **Usage Notes**

- None

LifeGuard Update 14-09-18.00-UG-U15

- This LG patch is applicable for 14-09-18.00-UG-U00-STD-GRT-04 version.

- **New Features**

- Audio:
 - The on/Off switch for the device microphone, which controls audio input through connected audio device.
- OSX:
 - Display Boring SSL version in Software Components.
- AudioVolumeManager:
 - Implement changes to block volume increase beyond threshold.

○ Resolved Issues

- SPR-54043: Resolved an issue where Scanner changes, Active Index should not be reset if clear submit failed.
- SPR-53808: Resolved an issue where in few devices were unable to scan enhanced dot data matrix labels consistently.
- SPR-54264: Resolved an issue where in snap on trigger not working when DS3678 is connected.
- SPR-54026: Resolved an issue where in EMDK Barcode parameters for 2D inverse.
- SPR -53586: Resolved an issue where in battery draining was observed on few devices with external keyboard.

○ Usage Notes

- None

Version Information

Below Table contains important information on versions

Description	Version
Product Build Number	14-09-18.00-UG-U115-STD-GRT-04
Android Version	14
Security Patch level	June 01, 2025.
Component Versions	Please see Component Versions under Addendum section

Device Support

The products supported in this release are TC15 series product. Please see device compatibility details under Addendum Section.

New Features

- Allows User to select a portion of available device storage to be used as system RAM. This feature can be turned ON/OFF from device admin only. Please refer to <https://techdocs.zebra.com/mx/powermgr/> for more details.
- Added support for DHCP Option 119. (DHCP option 119 would work only on managed devices over WLAN only and WLAN profile should be created by device owner).
- Scanning
 - Added support for Regular Expression checking in Free-Form OCR and Picklist + OCR workflows.
 - Updated version of Decoder library IMGKIT_9.02T01.27_06_02.

- Enhanced Scanning performance with SE55/SE58 Scan Engines.
- FS40 (SSI Mode) Scanner Support with DataWedge.
- Expose the GS1 DataBar Security Level settings.
- New Configurable Focus Parameters offered for devices with SE55 Scan Engine

OS Update Installation Requirements and Instructions

- To update from **A13 to A14** release, user must follow the steps below.
 - Step-1: Device MUST have A13 September 2024 LG BSP Image or a greater A13 BSP version installed which is available on zebra.com portal.
 - Step-2: Upgrade to this release A14 BSP.
- To update from **A11 to A14** release, user must follow the steps below.
 - Step-1: Device MUST have A11 October 2024 LG BSP Image or a greater A11 BSP version installed which is available on zebra.com portal.
 - Step-2: Upgrade to this release A14 BSP.

Important Links

- [6375-A14-os-update-instructions](#) (if the link does not work, please copy it to browser and try)
- [Zebra Techdocs](#)
- [Developer Portal](#)

Addendum

Device Compatibility

This software release has been approved for use on the following devices.

Device Family	Part Number		Device Specific Manuals and Guides
TC15	TC15BK-1PE14S-A6 TC15BK-1PE14S-IA TC15BK-1PE14S-TK	TC15BK-1PF14S-A6 TC15BK-1PF14S-BR	TC15 Home Page

Component Versions

Component / Description	Version
Linux Kernel	5.4.268

Android SDK Level	34
Scanning	43.33.10.0
Datawedge	15.0.31
MXMF/OSX	MXMF: 14.2.0.13
	OSX version: QCT6375.140.14.10.7
Touch FW	Touch Version: 0x0a
	Mode:finger only
RxLogger	14.0.12.24
Bluetooth Pairing Utility	Build Version: 6.3
Zebra Data Services	14.0.1.1014
AnalyticsMgr	10.0.0.1008
Files	Version 14
Stage Now	Application Version : 13.4.0.0
	Build Version: 14.2.0.13
Battery Manager	1.5.4
WWAN	HW MBN: DSDS_CDMALess-LA-Strait:0a001900
	SW MBN: SIM 0: SW_Default:0ae00005
	SW MBN: SIM 1: SW_Default: 0ae00005
TS.25	16-12-2024
NFC	NFC_NCIHALx_AR18C0.13.01.00
Ambient Light Sensor	stk_stk3a5x Ambient Light Sensor
Sensors (Accel, Gyro)	Gyroscope: icm4x6xx Gyroscope
	Accelerometer: icm4x6xx Accelerometer
Camera	2.04.102(175-00)
GreenMode	1.18
ZebraDeviceManager(ZDM)	14.2.0.13
ZSL	6.1.4
Acoustics Profiles	General: TC15-U-1.1
	Cellular: TC15-U-1.1
GMS	14_202411
Zebra BlueTooth	14.8.1
Audio	vendor:0.12.0.0
	ZQSSI:0.12.0.0
Baseband Version	MPSS.HI.4.3.4-00625-MANNAR_GEN_PACK-1
oem info	9.0.1.257
Common Transport Layer	3.0.0.1012

Revision History

Rev	Description	Date
1.0	Initial release	September 23, 2024