

# **Assembly Manual**

#### Leg Extension/Curl Machine Model: LKC-1





## **PREPARATION**

#### **Tools for Assembly:**

- Electric Screwdriver
- Hex Key (Allen Wrench) Set
- Wrench Set and Adjustable Wrench
- Rubber Mallet
- Lubricant (for smooth assembly)

#### **Important Tips:**

**Hand-tighten bolts and nuts during assembly.** This ensures that the structure can be adjusted as needed. Once the entire unit is assembled, tighten all hardware securely.

Periodically check for loose screws and bolts, especially after initial use. Tighten them if necessary to ensure safety and stability.

#### Component Overview



1 Right Main Frame 1 pc



② Rotational Arm Support 1 pc



3 Cushion Bracket Frame 1 pc



4 Backrest Frame 1 pc



(5) Leg Roller Frame 1 pc



6 Connector Tube 1 pc



7 Left Base Support Frame 1 pc



8 Front Base Support Frame 1 pc





10 Left Small Handle 1 pc



1 Right Large Handle 1 pc



1 Left Large Handle 1 pc



3 Foam Roller 1 pc



(4) Backrest 1 pc



(15) Cushion 1 pc



16 Roller Frame Cover 1 pc

#### Hardware Details



A M8 Washer 7 pcs



® M10 Washer 28 pcs



© M10 Nut 16 pcs



© M8x30 External Hexagon Screw 3 pcs



(E) M8x50 External Hexagon Screw 2 pcs



(F) M8x80 External Hexagon Screw 2 pcs



© M10x20 Hexagon Socket Countersunk Head Screw 1pc



(H) M10x25 Hexagon Socket Countersunk Head Screw 1pc



① M10x70 External Hexagon Screw 8 pcs




® M10x65 Round Head Square Neck Screw 4 pcs



(L) M10x75 External Hexagon Screw 4 pcs


## Step 1 Main Frame Assembly

| Item No. | Name                          | Qty | Item No. | Name                     | Qty |
|----------|-------------------------------|-----|----------|--------------------------|-----|
| <b>B</b> | M10 Washer                    | 16  | 1)       | Right Main Frame         | 1   |
| ©        | M10 Nut                       | 8   | 7        | Left Base Support Frame  | 1   |
| (1)      | M10x70 External Hexagon Screw | 4   | 8        | Front Base Support Frame | 1   |
| Ĺ        | M10x75 External Hexagon Screw | 4   | 9        | Right Small Handle       | 1   |
|          |                               |     | 10       | Left Small Handle        | 1   |
|          |                               |     | (1)      | Right Large Handle       | 1   |
|          |                               |     | 12       | Left Large Handle        | 1   |




## Step 2 Rotational Arm Support Assembly

| Item No. | Name                                | Qty |
|----------|-------------------------------------|-----|
| (B)      | M10 Washer                          | 4   |
| ©        | M10 Nut                             | 4   |
| K        | M10x65 Round Head Square Neck Screw | 4   |
| 2        | Rotational Arm Support              | 1   |



## Step 3 Connector Tube Assembly

| Item No. | Name                          | Qty |
|----------|-------------------------------|-----|
| (B)      | M10 Washer                    | 8   |
| ©        | M10 Nut                       | 4   |
| <u> </u> | M10x70 External Hexagon Screw | 4   |
| 6        | Connector Tube                | 1   |






## Step 4 Leg Roller Frame Assembly

| Item No. | Name             | Qty |
|----------|------------------|-----|
| (5)      | Leg Roller Frame | 1   |



## Step 5 Foam Roller Assembly


| Item No. | Name   | Qty |
|----------|--|-----|
| ©        | M10x20 Hexagon Socket Countersunk Head Screw | 1   |
| H        | M10x25 Hexagon Socket Countersunk Head Screw | 1   |
| (3)      | Foam Roller                                  | 1   |
| 16       | Roller Frame Cover                           | 1   |






Step 6 Cushion Bracket Frame Assembly

| Item No. | Name                  | Qty |
|----------|-----------------------|-----|
| 3        | Cushion Bracket Frame | 1   |



## Step 7 Cushion Assembly

| Item No. | Name                         | Qty |
|----------|------------------------------|-----|
| (A)      | M8 Washer                    | 4   |
| (D)      | M8x30 External Hexagon Screw | 2   |
| E        | M8x50 External Hexagon Screw | 2   |
| 15       | Cushion                      | 1   |



## Step 8 Backrest Assembly


| Item No. | Name                         | Qty |
|----------|------------------------------|-----|
| A        | M8 Washer                    | 3   |
| (D)      | M8x30 External Hexagon Screw | 1   |
| E        | M8x80 External Hexagon Screw | 2   |
| 4        | Backrest Frame               | 1   |
| 14)      | Backrest                     | 1   |





Step 9 Backrest Assembly

| Item No. | Name           | Qty |
|----------|----------------|-----|
| 4        | Backrest Frame | 1   |
| (4)      | Backrest       | 1   |





# **Contact Us**

For any questions or assistance with the assembly of this product, please feel free to contact us.

Email: support@kingsmithstrength.com

We are committed to providing you with the support you need and ensuring your satisfaction!