



delta^Δ

Wearable Safety Beacons

Assembly instructions

Parts

- A** x1 — Beacon (Front & Rear)
- B** x1 — Mount
- C** x1 — Mount Band



Operation modes:

ACTION	LIGHT MODE	EST. RUN TIME
Press once (1)	Pulsing	10 Hours
Press again (2)	Constant Beam	3.5 Hours
Press again (3)	Movement Detection*	20 Hours


*3 quick flashes indicates movement mode activated. Light will stop flashing if no movement is detected for 7 seconds.

USB Charging

Charge periodically in any USB port or when light appears dimmer.
Charge Time: approx 50 mins
 Slow pulse while charging.
 Constant light when fully charged.




IMPORTANT NOTE
 Failure to charge after extensive use may affect battery life.




Attach to Mount

- 1** Slide beacon into mount, be sure it is lined up securely.
- 2** Attach band, wrap around bar secure other side to bottom hook.



Attachment Option

- 1** Zip Ties (not included) can be used for permanent attachment of mount and to secure to larger size bars.



WARNING

Do not look directly into this light.
 May cause temporary blindness.





CHOKING HAZARD!

Not to be used by children under 5 years old.



IMPORTANT NOTE
 Max width of Zip Ties is 5mm, (3/16")

Easy Attachment Anywhere



Assembly video

Visit designbydelta.com/downloads

