YEAR:


MODEL: TRIM:


FR-S / BRZ / GT86 / GR86


ZN6 / ZN8 / ZD8 / ZN8 RK-C4063T-04: SPORTS TOURING CATBACK, STAINLESS STEEL TIP

RK-C4063T-04T: SPORTS TOURING CATBACK, BURNT STAINLESS STEEL TIP

No. Description Part Num. Qty **Torque** 2.5" Composite 2-Bolt Gasket 65C2-T05 1 1 2.5" Composite 2-Bolt Gasket 65C2-01 2 1 M10 Serrated Hex Head Bolt L=35mm M10B35 3 6 ~42 ft-lbs. M10 Serrated Nut 4 M10N 6 ~42 ft-lbs.







- You can install this system as an assembled unit or section by section. If installing section by section,
- we recommend starting from the front and working rearwards

2. Remove OE exhaust system: rear muffler and midpipe


- Install all gaskets and hardware. Leave the hardware hand tight.
- For the midpipe to intermediate pipe connection: A. if using OEM intermediate pipe,

Install REMARK exhaust components using the original rubber hangers unless otherwise noted

- retain OEM gasket and re-use OEM hardware. Torque to OEM spec.
 - B. if using an aftermarket intermediate pipe with a flat 2-bolt flange, use gasket provided

with the intermediate pipe


and retighten hardware.



- NOTE: When installing on a 2013-2021 model, the fitment of tips to bumper openings is quite tight. Make sure to position correctly before starting the car. See images at the bottoms of this guide.




2022





- 11. Start the engine 12. Check for any leaks, fitment issues, rubbing, etc.. 13. After ~100 miles of driving, re-check for exhaust leaks, fitment issues, and re-torque all hardware.
- 2013 2021



- Limited Warranty only applies to the original purchaser of the product
- REMARK is not responsible for fitment issues on non-US spec vehicles as all products are developed on US spec models
- Product finishes are not covered under warranty and considered wear & tear No warranty whatsoever will be valid if the defect was caused by abuse, negligence and/or mishandling. That includes weather conditions, natural disasters, any road/off-road conditions, and any accidents/collision you were
- Acidic cleaning products or steel wool are not to be used unless by a trained professional. Some chemical cleaning products may damage the product and/or finishes.
- Wear and tear (the damage that happens to our product in ordinary use) is not covered by our limited warranty. Improper installation or misuse of the product may lead to failure and damage to both product and vehicle. The
- user assumes all responsibility. All products are intended for use off-public streets and highways. Vehicle manufacturer warranty may be voided should any modification(s) or removal(s) of OEM(factory) components are determined.

Federal and state law may prohibit the removal, modification or rendering of any device affecting vehicle emis-

- sions or state regulated decibel limits. It is the customer's responsibility to be aware of federal, state and local laws. User assumes all cost and risks associated with purchase and installation of aftermarket components. REMARK is
- not responsible for any fees, fines, or any type of penalties you have received from any authority. Buyers are responsible for all return shipping fees unless otherwise noted

REMARK, INC. 16782 HALE AVE, STE A, IRVINE CA 92606