

RIVALE PROFILE SOFTWARE VERSION HISTORY

| VERSION | DELEASE DATE | DMX CHART | MODIFICATIONS |
|--------------|--------------|-----------|---|
| V101 | 27-Sep-23 | V1 | MODIFICATIONS First version |
| V102 | 19-Oct-23 | V1 | Adjusted Y alignment angle |
| | | | Fixed some bugs on Esim Improved zoom movement |
| V103 | 2-Nov-23 | V1 | Improved animation course when reset |
| | 7-Dec-23 | V1 | Added temperature protection when rotating and fixed gobos morphing |
| V104 | | | Fixed the bug when reset at "All rotating gobos" mode, it shows gobo and gobo rot error. The menu name "Log Collect" inside the Info menu changed to "Data Collect". |
| | | | Added a Total LED Hours in menu, to advoid the issue RMD reads the hours only for "75- |
| | | | 100% dimmer" |
| V105 | 21-Dec-23 | V1 | Added Gobo correction with 17% Cyran Increased a little on CMY rotating range to improve CMY calibration |
| | | | Cancel timer when inside the calibration menus |
| V106 | 22-Dec-23 | V1 | Changed to only need input one time pins for calibration, relock only after reset/restore |
| | 19-Jan-23 | V107 | Improve light output at low DMX value |
| | | | Added "Standard" Mode |
| | | | Added "CIr cmy comp" to Menu Remove the timer when hidden menu Calibration and cmy comp were already unlocked |
| | | | Allowed relock the hidden menu by doing a power cycle |
| V107 | | | Continue to improve light output when at narrow beam and small IRIS & color engaged |
| | | | Display QR code in SN |
| | | | Add a double confirmation layer in clear CMY comp |
| | | | Identify first two letters in SN whether to reduce power when stacking gobo Add SN QR code in special menu |
| | | | Update NFC app |
| | 28-Feb-24 | V107 | Add Defog ON with all Head and Base Fans to maximum and Dimmer to Max and Zoom to |
| V108 | | | Narrow Data Collect reload Off |
| | | | Improved on Focus Slip issue |
| | | | Signal selection inside the DMX addressing |
| | 11-Mar-24 | V109 | Add the RDM QR code |
| V109 | | | Error display only 1 time |
| v 105 | | | CTO compensation for Magenta wheel |
| | | | Changing the focus driving to avoid losing steps |
| | | | Add gobo control for RA same as RV Remove all limitation on gobos |
| | 24-Mar-24 | V109 | Remove limitation on single gobo function for Mag version |
| | | | Fix gobo or color wheel mismatch issue |
| | | | CTO compensation for fixed color wheel Magenta |
| V110 | | | Add framing range |
| | | | Change votage in constant fans on mode |
| | | | Fix gobo control "full" issue |
| | 24-May-24 | V109 | Modify button function in address page |
| | | | Changed default framing position Fix random movement issue. |
| V111 | | | Use linear power drop when framing. |
| | | | Adding privacy policy concent in data collect/fixture manager. |
| | | | Adjust current for focus when light head points to 90°. |
| | 31-May-24 | V112 | Rectified Issue: Stop rotation by shortcut(CH6/7: 64-127) will no more affect Pan/Tilt movement (Ch1/3) |
| V112 | | | Modified option in "gobo correction" as ON/OFF instead of CTB/Cyan/OFF |
| | | | Added FS Mode |
| | | | Change defog fan logic. |
| V113 | 24-Jun-24 | V112 | Fix PAN/TILT Flip issue |
| V114 | 12-Jul-24 | V114 | Added quick address setup via NFC Adding Tracking 360 mode |
| **** | 30. 27 | | Improve Dimming issue on LED when blade not fully in |
| | 23-Sep-24 | V114 | Tilt acceleration curves modified for better and safer movement |
| V115 | | | CMY fade improved |
| | | | Iris fade improved |
| | | | Minor bug fixes Add protection when Pan or Tilt Blocked |
| V116 | 16-Oct-24 | V114 | Add afosc for Pan and Tilt Blocked Add 360SC for Pan and Tilt Degree Option |
| | 4-Dec-24 | | Add 360SC in control Channel |
| V117 | | V117 | Improved Defog Logic |
| | | | Improved Zoom/focus |
| | 13-Mar-25 | V118 | Pan&Tilt repositionning improved |
| | | | Framing Constant mode added New dimmer curve "Linear low" added |
| \max. | | | Add CMY path options, "Shortcut" as default, "Spinout" as option |
| V118 | | | "Photoelectric Encoder" set as default (Restore Factory Settings) |
| | | | Encoder selection (Photoelectric or Magnetic) added in Control channel |
| | | | Continuous Pan & Tilt synchronization issue solved |
| V/110 | | 1/110 | ⚠ Encoder selection will automaticaly switch to Photoelectric during update |
| V119 | | V118 | Spinout out CTO issue solved Improve CMY driving, to correct bug (random flash between colours) |
| + | | | EUROPOVE CIVIT OLIVIUS, TO COLLECT DUS TRANGORI HASO DETWEEN COLOUES! |
| | | | |
| V120 | 23-Jun-25 | V118 | Improve iris synchronization (between multiple fixtures) Improve PAN/TILT reset process to be more consistent on the positionning |
| | 23-Jun-25 | V118 | Improve iris synchronization (between multiple fixtures) |