


HST3, HST3-R, HST3 BW, HST3-R BW M12	$t_{\text{fix, min}}$	$t_{\text{fix, max}}$	$h_{\text{nom, min}}$	$h_{\text{nom, max}}$	h_{min}	$h_{\text{nom}} \circ$
M12x85 10/-	10	10	60	60	100	-
M12x95 20/-	20	20	60	60	100	-
M12x105 30/10	10	30	60	80	$40+h_{\text{nom}}$	
M12x115 40/20	20	40	60	80	$40+h_{\text{nom}}$	
M12x125 50/30	30	50	60	80	$40+h_{\text{nom}}$	
M12x145 70/50	50	70	60	80	$40+h_{\text{nom}}$	
M12x165 90/70	15	90	60	135	$40+h_{\text{nom}}$	
M12x185 110/90	35	110	60	135	$40+h_{\text{nom}}$	
M12x215 140/120	65	140	60	135	$40+h_{\text{nom}}$	
M12x235 160/140	85	160	60	135	$40+h_{\text{nom}}$	
M12x255 180/160	105	180	60	135	$40+h_{\text{nom}}$	
M12x295 220/200	145	220	60	135	$40+h_{\text{nom}}$	
M12x350 275/255	200	275	60	135	$40+h_{\text{nom}}$	

