

Universal Sensor Mounting Bracket

(Product number 6670)

The Universal Sensor Mounting Bracket can be used to mount Solar Radiation or UV sensors. Install the sensor using the hardware and manual included with it.

Install the bracket using the included hardware:

- Two 1½" U-bolts,
- Three each: spacers, #6 split washers, 6 X 32 x 3/8" machine screws
- Four each: ¼-20 nuts, ¼" split lock washers, ¼" flat washers

