


8.2.4. LTE BAND 7 EMISSION MASK ACP


QPSK, (5.0 MHz BAND WIDTH)







Page 311 of 1024













REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680


16QAM, (5.0 MHz BAND WIDTH)



















QPSK, (10.0 MHz BAND WIDTH)


















16QAM, (10.0 MHz BAND WIDTH)







Page 323 of 1024














QPSK, (15.0 MHz BAND WIDTH)


















16QAM, (15.0 MHz BAND WIDTH)







Page 331 of 1024













QPSK, (20.0 MHz BAND WIDTH)







Page 336 of 1024













16QAM, (20.0 MHz BAND WIDTH)







Page 340 of 1024












8.2.5. LTE BAND 12 BANDEDGE


ID: 38806 Date: 3/27/16


QPSK, (1.4 MHz BAND WIDTH)























Page 347 of 1024


16QAM, (1.4 MHz BAND WIDTH)








Page 348 of 1024


















QPSK, (3.0 MHz BAND WIDTH)








Page 352 of 1024


















16QAM, (3.0 MHz BAND WIDTH)








Page 356 of 1024


















QPSK, (5.0 MHz BAND WIDTH)








Page 360 of 1024


















16QAM, (5.0 MHz BAND WIDTH)








Page 364 of 1024



















QPSK, (10.0 MHz BAND WIDTH)

























16QAM, (10.0 MHz BAND WIDTH)






















8.2.6. LTE BAND 13 EMISSION MASK

ID:	38806	Date:	4/6/16
-----	-------	-------	--------


QPSK, (5.0 MHz BAND WIDTH)







Page 376 of 1024


REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680







REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680













REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680


16QAM, (5.0 MHz BAND WIDTH)

























QPSK, (10.0 MHz BAND WIDTH)





















16QAM, (10.0 MHz BAND WIDTH)








Page 389 of 1024














8.2.7. LTE BAND 17 BANDEDGE


ID:	38806	Date:	3/27/16
-----	-------	-------	---------


QPSK, (5.0 MHz BAND WIDTH)
























16QAM, (5.0 MHz BAND WIDTH)








Page 397 of 1024


















QPSK, (10.0 MHz BAND WIDTH)








Page 401 of 1024


















16QAM, (10.0 MHz BAND WIDTH)








Page 405 of 1024

















8.2.8. LTE BAND 25 BANDEDGE


ID:	38806	Date:	3/27/16
-----	-------	-------	---------


QPSK, (1.4 MHz BAND WIDTH)
























16QAM, (1.4 MHz BAND WIDTH)








Page 413 of 1024


















QPSK, (3.0 MHz BAND WIDTH)








Page 417 of 1024


















16QAM, (3.0 MHz BAND WIDTH)








Page 421 of 1024


















QPSK, (5.0 MHz BAND WIDTH)








Page 425 of 1024


















16QAM, (5.0 MHz BAND WIDTH)








Page 429 of 1024


















QPSK, (10.0 MHz BAND WIDTH)








Page 433 of 1024


















16QAM, (10.0 MHz BAND WIDTH)








Page 437 of 1024


















QPSK, (15.0 MHz BAND WIDTH)








Page 441 of 1024


















16QAM, (15.0 MHz BAND WIDTH)








Page 445 of 1024


















QPSK, (20.0 MHz BAND WIDTH)








Page 449 of 1024


















16QAM, (20.0 MHz BAND WIDTH)








Page 453 of 1024
















8.2.9. LTE BAND 26 EMISSION MASK


ID:	38806	Date:	4/8//2016
-----	-------	-------	-----------


QPSK, (1.4 MHz BAND WIDTH)







Page 457 of 1024














16QAM, (1.4 MHz BAND WIDTH)


















QPSK, (3.0 MHz BAND WIDTH)







Page 463 of 1024













Page 465 of 1024


16QAM, (3.0 MHz BAND WIDTH)


















Page 468 of 1024


QPSK, (5.0 MHz BAND WIDTH)


















16QAM, (5.0 MHz BAND WIDTH)







Page 472 of 1024













QPSK, (10.0 MHz BAND WIDTH)













16QAM, (10.0 MHz BAND WIDTH)












8.2.10. LTE BAND 27 EMISSION MASK


QPSK, (1.4 MHz BAND WIDTH)







Page 479 of 1024













16QAM, (1.4 MHz BAND WIDTH)







REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680












QPSK, (3.0 MHz BAND WIDTH)







Page 485 of 1024


REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680






Page 486 of 1024







Page 487 of 1024


16QAM, (3.0 MHz BAND WIDTH)







Page 488 of 1024












Page 490 of 1024


QPSK, (5.0 MHz BAND WIDTH)







Page 491 of 1024






Page 492 of 1024







Page 493 of 1024


16QAM, (5.0 MHz BAND WIDTH)







Page 494 of 1024












Page 496 of 1024


QPSK, (10.0 MHz BAND WIDTH)







Page 497 of 1024







16QAM, (10.0 MHz BAND WIDTH)






Page 499 of 1024








8.2.11. LTE BAND 30 EMISSION MASK ACP

QPSK, (5.0 MHz BAND WIDTH)













16QAM, (5.0 MHz BAND WIDTH)












REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680


QPSK, (10.0 MHz BAND WIDTH)









16QAM, (10.0 MHz BAND WIDTH)










LTE BAND 41 EMISSION MASK ACP 8.2.12.


QPSK, (5.0 MHz BAND WIDTH)







REPORT NO: 16U23309-E8V3 EUT MODEL: A1660, A1680 DATE: JULY 26, 2016 FCC ID: BCG-E3085A













16QAM, (5.0 MHz BAND WIDTH)







Page 512 of 1024













QPSK, (10.0 MHz BAND WIDTH)







Page 516 of 1024













REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680


16QAM, (10.0 MHz BAND WIDTH)


















QPSK, (15.0 MHz BAND WIDTH)







Page 524 of 1024













REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680


16QAM, (15.0 MHz BAND WIDTH)


















QPSK, (20.0 MHz BAND WIDTH)







Page 532 of 1024









REPORT NO: 16U23309-E8V3 DATE: JULY 26, 2016 FCC ID: BCG-E3085A EUT MODEL: A1660, A1680

16QAM, (20.0 MHz BAND WIDTH)

