




5906607901

Welder WSE3500
scheppach



Main products

5906607901

Spare part list

391319 - 0181 - WSE3500 - -

Spare	Description	additional	Item	Abb.	ConstructStatus
5906607001	Handle		1	A	*
5906607002	Top Cover		2	A	*
5906607003	switch		3	A	*
5906602014	power cable	3Gx1,5mm² / 3000mm	4	A	*
5906607004	Bottom cover		5	A	*
5906607005	DC fan		8	A	*
5906607006	IGBT		10	A	*
5906607007	Rectifier heatsink		12	A	*
5906607008	Transformer		15	A	*



5906607901

Welder WSE3500
scheppach



Main products

Spare part list

5906607901

391319 - 0181 - WSE3500 - -

Spare	Description	additional	Item	Abb.	ConstructStatus
5906607009	Capacitance		16	A	*
5906607010	Control PCB		17	A	*
5906607011	Main PCB		19	A	*
5906607012	Knob		22	A	*
5906607013	Panel PCB		25	A	*
5906604015	Wire-feeding Unit		26	A	*
5906607014	silk		31	A	*
5906607015	fan cover		32	A	*
5906607016	Hose package		o.Abb.	A	*
5906607017	Ground cable		o.Abb.	A	*
5906607018	Wire roller 0,8mm + 0,9mm	0,8mm + 0,9mm	o.Abb.	A	*
5906607019	Wire roller 0,6mm + 0,8mm	0,6mm + 0,8mm	o.Abb.	A	*
5906609027	Nozzle 0,6mm	0,6mm	o.Abb.	A	*
5906609028	Nozzle 0,8mm	0,8mm	o.Abb.	A	*
5906609029	Nozzle 0,9mm	0,9mm	o.Abb.	A	*
7906600710	flux wire 0,6 mm scheppach (DIY)		o.Abb.	A	*
7906600711	flux wire 0,8 mm scheppach (DIY)		o.Abb.	A	*
7906600712	flux wire 0,8 mm stainless steel scheppach (DIY)		o.Abb.	A	*
7906600709	gloves scheppach (DIY)		o.Abb.	A	*
7906600701	Cinder brush for welder WSE900 scheppach		o.Abb.	A	*
7906600702	cap for welder WSE900 scheppach		o.Abb.	A	*

!!! Do you know: From now on you can view spare parts lists in our spare parts shop and order spare parts and accessories directly. More information can be found here: <https://www.scheppach.com/Shop.aspx>