


For BMW E46 1999-2005 / C7200

Central Control Disassembly and Operation
Post-installation rendering



TOOLS REQUIRED FOR DISASSEMBLY

- 1.Wire
- 2.Protocol box
- 3.Installation tools



Disassembly:

1. Use a pry bar to effortlessly open the central control decorative trim, then use a screwdriver to unscrew the screws on both sides securing the CD player. Disconnect the wiring, and remove the CD player.



2. Use a pry bar to pry open the air conditioning control panel, pull out the connecting cable, and remove the air conditioning control panel.



3. Pry open the storage compartment beneath the air conditioning control panel and remove it.



4. Unscrew the screws on both sides securing the air vent beneath the air conditioner, then gently lift the air vent upward to remove the CD player base frame.



PROPOSE

Before starting the replacement job, you should prepare tools such as a plastic pry tool and a screwdriver, and make sure the car's power is cut off during the installation.


Installation

(If the wiring harness does not match, please contact customer service to request the correct wiring harness)

1. Reinstall the air conditioning control panel and storage compartment back into the vehicle, and ensure proper wiring connection.



2. Connect the new radio wires to the original car wiring, gently lift the air vent, and insert the new radio frame into the corresponding position.



3. Install the new radio into the original vehicle, secure the screws on both sides with a screwdriver, then reattach the central control decorative trim. The installation of the new radio is now complete.



COMPARATION

Effect of Installation



GENTLE REMINDERS

Due to the complexity of the product structure, you may encounter some problems during installation. If you still have any questions about the installation after reading this manual, you can contact us and we will respond to you within 24 hours. Don't worry; we will do our best to solve the problem for you until you are satisfied.

After-sales email: cheyang728@gmail.com

WARN FCC WARNING

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference.
- (2) This device must accept any interference received, including interference that may cause undesired operation.