

## **INSTRUCTION MANUAL**



Version QM: 8718-1.0-2465





#### **ABOUT US**

...

Some "HUUGER" moments may cure you of everything.

Derive from the Danish term "Hygge", and convey happiness and contentment to every family. HUUGER is devoted to creating a cosy corner at home.

Surrounded by pieces of furniture you love, and relax in mind. We hope some HUUGER home moments can free you from a busy life. And creating a satisfying home corner, we believe, doesn't mean it costs much. That's why HUUGER always focuses on high-quality, practical, and reasonably-priced products.


### MATTERS NEEDING ATTENTION

- You need a helper to finish the installation.
- Don't over-tighten the screws until all the parts are in place. Failure to follow the instructions may cause misalignment of the screws.
- DO NOT let children climb the product.
- To avoid suffocation danger, keep small parts and package materials away from children.
- Adult assembly required. Keep children away during the installation.
- Children should not use it without parents' supervision.
- You could use "corner guard" to protect children from getting hurt by the edges.
- If any parts were missing, broken or wrongly delivered, contact us immediately via email: service@huuger.com, we are here to help you.







#### PART LIST





#### PART LIST




#### PART LIST

































3

Note: The screws connecting two parts 7 are facing downwards, and the same applies to the screws connecting two parts 8.







A


0

**x4** 

**x4** 


6


Note: The direction of the metal pieces on parts 5 is consistent with that of the parts 3 and 4.




7

Note: The sizes on both sides of this hole are different. Please place the bigger side facing upwards and the smaller side facing downwards.









#### A Possible problems during installation:

There is a gap between the 2 boards.




 The hole in the bar is not aligned with the hole in the board, and the screw can not be installed.



#### A Recommended solution:


• Please loosen the screws which fix the boards, adjust the boards to make them fit together without gaps, then tighten the screws. Since the diameter of the screw hole in the bar is larger than the hole in the bolt, the position of the board can be adjusted.




• If the above method doesn't work, please contact us with a photo of the holes, we will help you further.


10

Note: Please tighten the screws in order from the middle to both sides.











x18



14



20

**x2** 

## HELP CENTER

# Please contact us first, if you have any problem!

www.huuger.com

#### **WARNINGS**

Seller does not assume any and all responsibility or liability from personal injury, property damage or loss, whether direct or indirect, or incidental, resulting from the incorrect instruction, improper use, inadequate maintenance, or neglect of this product.



