




DESIGNED FOR LIFE

Assembly Instructions



Conference Table

Model No.
HOGA-J0320
HOGA-J0404



LITTLE TREE
Little Tree by Tribesigns

www.tribesigns.com



Contact Us

We're here to help you.



Your satisfaction is our top priority. If you encounter any issues with this product, such as missing or damaged parts, we're here to help. Please retain the original packaging and take photos of the packaging and the product, then contact us as soon as possible.


Warm Tips

1. Carefully read these instructions and keep them for future reference.
2. Check the parts list and confirm everything's there before starting assembly.
3. When assembling, put all parts on a soft, smooth surface like a carpet to avoid scratches.
4. Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.

How to Get the Assembly Video

Step 1


Scan the QR code.






Installation Video

Step2

Search with the Model No.
(on the bottom left corner of the title page)





Note: If you can't find the assembly video, please contact us.



We recommend using hand tools for assembly.

If an electric screwdriver is used, reduce power and torque to avoid damage to the product.




**⚠ Caution**


Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.




Parts List




❶ 2 pcs




❷ 1 pc




❸ 2 pcs



❹ 2 pcs




❺ 2 pcs



❻ 2 pcs













❼ 2 pcs



❽ 2 pcs

Hardware List



| | | | | | | | | | |
|---|-------|---|------|---|-------|--|------|---|------|
| A | X16+1 | B | X8+1 | C | X16+1 | D | X4+1 | E | X4+1 |
|  | |  | |  | |  | |  | |
| M6X12 mm | | M6X15 mm | | M6X25 mm | | M6X35 mm | | M6X48 mm | |

| | | | | | | | | | |
|---|-------|---|----|---|------|---|----|---|----|
| F | X20+1 | G | X1 | H | X6+1 | I | X4 | J | X4 |
|  | |  | |  | |  | |  | |
| M6X55 mm | | M4X55 mm | | Ø10X50 mm | | M6XØ20 mm | | 40X20 mm | |





1

screw down





X2


| A | X16 | G | X1 |
|---|-----|---|----|
|  | |  | |
| M6X12 mm | | M4X55 mm | |

2

pre-drill 70%





X2

| C | X8 |
|---|----|
|  | |
| M6X25 mm | |




3

pre-drill 70%



| C | X8 |
|----------|----|
| | |
| M6X25 mm | |


4





| H | X6 |
|-----------|----|
| | |
| Ø10X50 mm | |

**5**



screw down



| B | X8 | J | X4 |
|---|----|---|----|
|  | |  | |
| M6X15 mm | | 40X20 mm | |

6

pre-drill 70%







| F | X20 | I | X4 |
|---|-----|---|----|
|  | |  | |
| M6X55 mm | | M6XØ20 mm | |



7

screw down




| D | X4 | E | X4 |
|---|----|---|----|
|  | |  | |
| M6X35 mm | | M6X48 mm | |



DESIGNED FOR LIFE

Thank you for your support!



Contact our customer service team



support@tribesigns.com
www.tribesigns.com



1-424-220-6888

7 AM to 8 PM EST,
Monday to Friday

Follow Tribesigns



Facebook



Instagram



Pinterest



Twitter



YouTube



TikTok



WhatsApp