

# N8550-48B8C Switch

## FSOS Software Release Notes

---

Model: N8550-48B8C

## Contents

1. Version Information.....	1
2. Bug fixes.....	1
2.1 V410 R240.....	1
3. Version changes.....	1
3.1 V410 R240.....	1
3.2 V100 R201.....	2
4. Upgrade Instructions.....	2
4.1 Upgrade file.....	2

## 1. Version Information

Version Number	V410R240
Product	N8550-48B8C
Version Type	Official Version
Applicable Customers	Data Center Customers
Release Date	2021-07-27
Baseline Version	V100R201

Use the show version command to view the version number, an example is as follows:

```
N8550-48B8C#show ver
FS Platform
Copyright (c) 2009-2020 FS.COM Inc. All Rights Reserved.
FSP (R) Software Version V410R240
Compiled Jul 27 2021 10:35:46
FS Switch N8550-48B8C
System Uptime is 0 days 0 hours 17 minutes 30 seconds

Hardware Version : N/A
BIOS Version      : N/A
FPGA Version      : N/A
Serial Number     : 732656X1944010

System Memory     : 16322248K
```

## 2. Bug fixes

### 2.1 V410 R240

Based on v100r201 newly added to solve the following problems

Solve the problem of incompatibility with 10G SFP+ Passive DAC 3m cable

## 3. Version changes

### 3.1 V410 R240

#### Hardware support status changes

None

#### Functional support changes

Add MLAG, EVPN and NTP functions

## 3.2 V100R201

### Hardware support status changes

None

### Functional support changes

None

## 4. Upgrade Instructions

### 4.1 Upgrade File

To upgrade the device to this version or downgrade to this version, you need to use the following upgrade file.

Applicable Products	Upgrade File	
N8550-48B8C	[Upgrade File]	onie-installer
	[File Description]	installation package
	[File Size]	168561942 bytes
	[MD5 Value]	edb21194d9a0ad4eef09a129cadbf84f