


PT5II User Manual





Packing List


- | | |
|------------------------------|---------------------------|
| 1 x PT5 II Monitor | 1 x Pair of Rubber Covers |
| 1 x MH-2 Mount | 1 x User Manual |
| 1 x HDMI to HDMI Cable | 1 x Safety Box |
| 1 x Micro HDMI to HDMI Cable | 1 x Sunshade |

UI Operation Logic

Tap the screen, swipe left or right, cycle through the shortcut function interface and the image setting interface.




(Shortcut Function Interface)



(Main Menu Interface)

How to get in icon functions

Click the icon to turn on the function; click the icon again to turn off the function.



Long press the icon, the setting interface shows at the bottom.

Click the  icon, the setting interface shows at the bottom of the UI.

Hold the icon and slide to enter the shortcut functions menu.

Click the  icon to get in the shortcut functions menu.



There are two  in the bottom setting interface, which means you can turn to the next page.



Click  to return to the previous page.

3D LUT Loading and Deleting

Click  icon, 3D LUT setting interface shows at the bottom, select , click the 3D LUT file to use the 3D LUT file.

Load the 3D LUT file into the U disk, plug it into the monitor USB port.



Click  to enter the corresponding location of the U disk and load the 3D LUT file.

Click , select the 3D LUT file, hold and swipe up, select "Yes" to delete the 3D LUT file.

Firmware Upgrade

Unzip the firmware package to the root directory of the U disk.

Please make sure not to power off during the upgrade process.

Compatible with USB flash drives in FAT, FAT32, ExFAT and NTFS formats. (FAT32 is recommended)

Please use a U disk with storage capacity below 16G.



Click the  icon to get in the firmware upgrade interface, select , Select "Yes" to upgrade the firmware.

Shortcut Function Icons

 Peaking	 Rectangle Crop
 Zebra	 HDR(HLG)
 False Color	 Check Field
 Luma Waveform	 Guides
 RGB Waveform	 Cross Hair
 Audio Meters	 Grids
 Luma Histogram	 Add Shortcut Function
 3D LUT	 Delete Shortcut Function

Bottom Settings Area Icon

HDMI Input Signal Resolution	 Backlight
After Date Loading Before/After 3D LUT	 Enter the shortcut function selection interface
Off 3D LUT Switch	 Enter the shortcut function setting interface

Main Menu Icon

 Image Setting	 3D LUT
 Image and Menu Flip Settings	 Volume Setting
 System Setting	 View version information and firmware upgrades

Website:

www.portkeys.com

Email:

Services@portkeys.com

Company Address:

1406, 14th Floor, Block D, Building 3, Cloud Park, Longgang District, Shenzhen, Guangdong, China

Factory Address:

2nd Floor, Building A, Jingjiang Industrial Park, NO.101, Shangwei Road, Longhua District, Shenzhen, Guangdong, China

