


REPLACEMENT OF LOCKRAIL RETAINER KIT

WORK INSTRUCTION

Resources Required

- A. Precision Hook
- B. Spring 43062
- C. Retainer Clip 04872



Procedure

NOTE: DO NOT USE THE OLD SPRING FOR REPAIR

1. With the hook, disengage the actual spring.
2. Pull out the spring.
3. Assemble the spring in the retainer and snap the part in the lock rail about 2" away from the latch.



Step 1



Step 2




Step 3

4. Push the assembled retainer clip towards the latch until it locks in the machining holes.
5. The retainer clip fits perfectly with the latch and is parallel to the lock rail.
6. Test the latch
7. Dispose of the old spring



Step 4



Step 5



Step 6




Step 7

INSTRUCTIONS DE TRAVAIL

Resources requises

- A. Crochet de précision
- B. Ressort 43062
- C. Butée 04872



Procédure

NOTE: N'UTILISEZ PAS L'ANCIEN RESSORT POUR LA RÉPARATION

1. Avec le crochet, désengager le ressort.
2. Retirer le ressort.
3. Assembler le ressort sur la butée et l'insérer 2" plus loin dans la rainure de la glissière à loquets.



Étape 1



Étape 2




Étape 3

4. Pousser la butée assemblée vers le loquet jusqu'à ce qu'elle se verrouille en place dans les usinages.
5. La butée s'emboîte parfaitement avec le loquet et est parallèle à la glissière.
6. Tester le loquet.
7. Jeter le ressort remplacé.



Étape 4



Étape 5



Étape 6



Étape 7