










- | | |
|----------------------------------|------------------------------|
| (D) Montageanleitung | (GB) Assembly instructions |
| (FR) Notice de montage | (IT) Istruzioni di montaggio |
| (NL) Handleiding voor de montage | (PL) Instrukcja montażu |
| (CZ) Montážní návod | (SK) Návod na montáž |
| (HU) Szerelési útmutató | (RO) Instrucțiuni de montaj |
| (TR) Montaj talimatları | (UA) Інструкція по монтажу |

















Name • Nom • Nome • Naam • Nazwa • Jaméno • Názov • Név • Denumire • Isim • Название		
Nr. • No. • N° • Номер • Č • Sz		
Typ • Type • Tip • Tipus • Tipo • Тип		

1 1x




№	Size/MaB			Qty	
	1400	1600	1800		
1	1485x200x35	1685x200x35	1885x200x35	1	
2	1485x200x35	1685x200x35	1885x200x35	1	
3	2085x200x50			2	
4	1485x150x20	1685x150x20	1885x150x20	2	
6	520x70x20			3	
7	2025x80x20			1	
8	150x150x190			4	
9	155x70x20			2	




H4 x12  M6x30	P9 x4  	O1 x1  S 4 mm	K1 x6  Ø8x35	P2 x2  	P3 x2 
A1 x10  Ø7x50	J2 x14  4x16	J3 x16  4x30	J5 x6  4x40	J10 x32  Ø6,3x(13-16mm)	




3^{4x}




Step 1





Step 2




Step 3





4^{4x}




5^{3x}







8^{2x}



9^{2x}



10^{2x}



11^{2x}

