



Dose Sensor

for Tork Soap and Sanitizer Dispenser







1




2





3




4



5




6



7




8




Replace battery 

1




Replace battery

2




Dose Sensor for Tork Soap and Sanitizer Dispenser


3




4



5



6



7





Manufactured by Essity Hygiene and Health AB
SE-405 03 Göteborg, Sweden
Visiting address: Mölndals Bro 2, Mölndal

UK:
Essity UK Limited
Southfields Road, Dunstable, Bedfordshire, LU6 3EJ, UK
+44 1582 677400

North America:
Distributed by Essity HMS North America Inc
2929 Arch Street
Suite 2600
Philadelphia, PA 19104

www.essity.com, www.torkglobal.com

Made in Sweden