




200W USB-C 6-PORT PD GAN CHARGER




Connect the included C5 power cable to the C5 connector on the rear of the charger.




Plug the power cable directly to a power outlet.




The LED Indicator light will illuminate white when receiving power.



The 200W charger can be laid flat horizontally on the supported rubber feet or vertically using the included Desktop Stand.




Plug in cables (sold separately) to the charger's USB-C PD ports. We always recommend using certified charging cables. EMARK cables are required to reach wattage above 60W.



Connect and charge up to six USB-C devices simultaneously. Total max output: 200W. When connecting devices to all six PD ports, connect your largest device to the PD1 port.


CHARGING

7




When connected to PD1 or PD2, supported device can charge with a max output of 140W. Only one device can be connected at a time to either port in order to achieve 140W charging. USB-C to MagSafe 3 Cable must be used in order to achieve 140W output through PD1 or PD2.

8



When connected to PD3 or PD4, supported device can charge with a max output of 100W.

9



When connected to PD5 or PD6, supported device can charge with a max output of 20W.