



MARINFLOC SB 01 Efficient Oily Water Separator Owner's Manual

[Home](#) » [MARINFLOC](#) » MARINFLOC SB 01 Efficient Oily Water Separator Owner's Manual 

MARINFLOC SB 01 Efficient Oily Water Separator



Contents

- [1 Service Bulletin](#)
- [2 Documents / Resources](#)
 - [2.1 References](#)

Service Bulletin

no. 01, 2000-03-20

Corrosion problems related to defective backflushing cycle and high bilge water temperature

System applicability: Marinfloc CD and TD units

Background

It has been found necessary to point out, that if the backflushing cycle has not been carried out according to the manual instructions, severe corrosion problems may occur in a very short period of time.

There are four major reasons to these corrosion problems:


- The system has not been properly backflushed with fresh water after having completed a full bilge water cleaning and discharge operation.
- The chloride content of the treated water has been >1000 ppm.
- The temperature of the bilge water to be treated has been >55 °C.
- Salt water (high chloride concentration) standing still in the filter stages.

To prevent and avoid these problems we would like to stress the importance of:

1. Keeping the temperature of the bilge water to be treated at maximum 55 °C.
2. After each completed bilge water cleaning and discharge operation (i.e. if the unit will be stopped for one hour or more): backflush the system with fresh water of a temperature of 65 °C or at least 5 °C higher than the process water temperature.
3. Install cathodic protection using sacrificial zinc anodes with an iron core. The sacrificial anodes are to be inserted into the top plug of the three filter stages. The anodes are bought from Marinfloc, article no. CD-099-0015110.



Documents / Resources

	<p>MARINFLOC SB 01 Efficient Oily Water Separator [pdf] Owner's Manual SB 01 Efficient Oily Water Separator, SB 01, Efficient Oily Water Separator, Oily Water Separator, Water Separator, Separator</p>
---	--

References

- [User Manual](#)

[Manuals+](#), [Privacy Policy](#)

This website is an independent publication and is neither affiliated with nor endorsed by any of the trademark owners. The "Bluetooth®" word mark and logos are registered trademarks owned by Bluetooth SIG, Inc. The "Wi-Fi®" word mark and logos are registered trademarks owned by the Wi-Fi Alliance. Any use of these marks on this website does not imply any affiliation with or endorsement.