


MAXUS BREW Espresso Scale with Timer User Guide

[Home](#) » [MAXUS](#) » MAXUS BREW Espresso Scale with Timer User Guide 



Contents

- [1 Calibration](#)
- [2 Documents / Resources](#)
- [2.1 References](#)

Calibration

Your scale comes calibrated from the factory and most users won't need to calibrate their scales for a long time. If the scale should ever deliver a false reading, it can be calibrated in the following way if required.

- Prepare the required calibration weight for your scale (you can find the info on the specs chart).
- Find a flat and level surface to perform calibration and let the scale to acclimate to room temperature.
- Be sure the scale is on and nothing is on the platform, press and hold the MODE key for a few seconds until the screen shows "CAL" then release, click the MODE key again, the display starts to flash the number of required calibration weight.
- Gently place the required calibration weight on the center of the platform, after a few seconds, "PASS" is briefly displayed, then the display will show the number of the calibration weight, now you may remove the calibration weight from the platform.
- The calibration is complete and you are ready to weigh.



Documents / Resources

<p>Calibration Your scale comes calibrated from the factory and most users won't need to calibrate their scales for a long time. If the scale should ever deliver a false reading, it can be calibrated in the following way if required.</p> <ul style="list-style-type: none">• Prepare the required calibration weight for your scale (you can find the info on the specs chart).• Find a flat and level surface to perform calibration and let the scale to acclimate to room temperature.• Be sure the scale is on and nothing is on the platform, press and hold the MODE key for a few seconds until the screen shows "CAL" then release, click the MODE key again, the display starts to flash the number of required calibration weight.• Gently place the required calibration weight on the center of the platform, after a few seconds, "PASS" is briefly displayed, then the display will show the number of the calibration weight, now you may remove the calibration weight from the platform.• The calibration is complete and you are ready to weigh.	<p>MAXUS BREW Espresso Scale with Timer [pdf] User Guide BREW Espresso Scale with Timer, BREW, Espresso Scale with Timer, Scale with Timer, Timer</p>
--	---

References

- [User Manual](#)