



SPCOM00000044 N-Com System Instructions

[Home](#) » [N-Com](#) » SPCOM00000044 N-Com System Instructions 

Contents

- [1 SPCOM00000044 N-Com System](#)
- [2 INSTRUCTIONS FOR REPLACING THE SPCOM00000044](#)
- [3 Documents / Resources](#)
- [4 Related Posts](#)





SPCOM00000044 N-Com System




INSTRUCTIONS FOR REPLACING THE SPCOM00000044


1. Remove the N-Com system from the helmet (see instruction booklet).
2. Open the e-box (**Fig. 1-2**).




3. Disconnect the antenna connector (**Fig. 3**).



4. Place the new antenna inside the plastic box (e-box).
5. Connect the new antenna.
6. Only for BX4 – Position the cable in the special fixing hook (**Fig. 4**).



7. Close the e-box (**Fig. 5**).



8. Make sure that all fixing points are properly secured.

9. Reposition the N-Com system inside the helmet (see instruction booklet).

Documents / Resources

	n-com SPCOM00000044 N-Com System [pdf] Instructions SPCOM00000044 N-Com System, SPCOM00000044, SPCOM00000044 N-Com
--	--